



HONDA



report date: 2024-03-28

General information

Make	HONDA
Model	FR-V VTEC SPORT
Colour	Black
Year of manufacture	2006
Top speed	120 mph
0 - 60 mph	10.5 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	148 BHP
Max. torque	192 Nm at 4.000 rpm
Engine capacity	1.998 cc
Cylinders	4
Fuel type	Petrol
Consumption city	25.7 mpg
Consumption extra urban	40.9 mpg
Consumption combined	33.6 mpg
CO2 emission	199 g/km
CO2 label	J





Internet history

Entry 1

Date	2021-12-17
Pictures	0
Listing price	View report

source: [autotrader.co.uk](#)



MOT history

MOT expiry date	2024-12-29
MOT pass rate	75 %
MOT passed	15
Failed MOT tests	5
Total advice items	28
Total items failed	3

MOT #20 2023-12-27 12:09

MOT test number 805581446797

Result ✓ Passed

Next expiry date 2024-12-29

Advice Rear Vehicle structure is corroded but structural rigidity is not significantly reduced (6.1.1 (c) (i))

Advice Front Headlamp has a product on the lens but not seriously reducing light output both side (4.1.4 (b))

Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Rear Suspension component corroded but not seriously weakened (5.3.3 (b) (i))

Advice Nearside Front Suspension arm ball joint has slight play (5.3.4 (a) (i))

Advice Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

MOT #19 2022-12-29 13:54

MOT test number 779555721567

Result ✓ Passed

Advice Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #18 2021-12-30 11:23

MOT test number 498791995575

Result ✓ Passed

**MOT #17** 2021-02-09 10:48**MOT test number** 523653124513**Result** ✓ Passed**MOT #16** 2021-02-08 10:33**MOT test number** 273352625692**Result** ✗ Failed**DANGEROUS** Front Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))**MAJOR** Rear Registration plate insecure (0.1 (a))**MOT #15** 2019-06-17 16:38**MOT test number** 614826827149**Result** ✓ Passed**Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))**Advice** Vehicle heavily undersealed**MOT #14** 2018-09-18 08:41**MOT test number** 444151406089**Result** ✓ Passed**MOT #13** 2018-09-13 09:41**MOT test number** 720845230791**Result** ✗ Failed**MAJOR** Engine MIL inoperative or indicates a malfunction (8.2.1.2 (h))

**MOT #12** 2017-09-13 16:03**MOT test number** 324721907645**Result** ✓ Passed**Advice** Rear registration plate deteriorated but not likely to be misread (6.3.1d)**Advice** Front registration plate deteriorated but not likely to be misread (6.3.1d)**Advice** Eml on dash**MOT #11** 2017-09-12 10:22**MOT test number** 417991100411**Result** ✗ Failed**Advice** Eml on dash**Advice** Rear registration plate deteriorated but not likely to be misread (6.3.1d)**Advice** Front registration plate deteriorated but not likely to be misread (6.3.1d)**Fail** Offside Front Suspension arm ball joint dust cover excessively damaged so that it no longer prevents the ingress of dirt (2.4.G.2)**MOT #10** 2016-09-13 10:17**MOT test number** 276401003971**Result** ✓ Passed**Advice** Front registration plate deteriorated but not likely to be misread (6.3.1d)**Advice** Nearside Front Track rod end ball joint dust cover deteriorated, but preventing the ingress of dirt (2.2.C.1c)**Advice** Rear registration plate deteriorated but not likely to be misread (6.3.1d)**Advice** O\s rear calliper sticking slight bind

**MOT #9** 2015-09-14 15:27**MOT test number** 514358392039**Result** ✓ Passed**Advice** Exhaust emissions light on dash rear o2 sensor**Advice** Offside Rear Anti-roll bar linkage has slight play in a ball joint (2.4.G.2)**Advice** Nearside Front Anti-roll bar linkage has slight play in a ball joint (2.4.G.2)**MOT #8** 2015-03-27 10:57**MOT test number** 935396885080**Result** ✗ Failed**Fail** Nearside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)**MOT #7** 2014-03-19 14:01**MOT test number** 195658874403**Result** ✓ Passed**MOT #6** 2013-03-19 13:37**MOT test number** 917838173081**Result** ✓ Passed**MOT #5** 2012-03-23 10:05**MOT test number** 916063382000**Result** ✓ Passed**MOT #4** 2012-03-21 16:51**MOT test number** 658861982070**Result** ✗ Failed**Fail** Nearside Rear Anti-roll bar linkage has excessive play in a ball joint (2.4.G.2)



MOT #3	2011-03-25 14:27
---------------	------------------

MOT test number	898784981006
------------------------	--------------

Result	✓ Passed
---------------	----------

Notice	Child seat fitted not allowing full inspection of adult belt
---------------	--

MOT #2	2010-03-26 13:19
---------------	------------------

MOT test number	192785480420
------------------------	--------------

Result	✓ Passed
---------------	----------

Notice	Child seat fitted not allowing full inspection of adult belt
---------------	--

MOT #1	2009-03-31 13:22
---------------	------------------

MOT test number	440330399036
------------------------	--------------

Result	✓ Passed
---------------	----------

Notice	Unable to check o/s/r seat belt due to baby seat
---------------	--



Tax & MOT check

✓
Taxed
Tax due:
1 March 2025

✓
MOT
Expires:
29 December 2024

Tax status	Valid until 1 March
Days left	306
MOT expiry date	29 December 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	J
Single payment (12 months)	£ 365,00,-
Single six month payment	£ 200,75,-
Total payable by 12 monthly instalments	£ 383,25,-



Damage history

Check the damage history for this HONDA. See if, where and when this HONDA had damage and the car repair costs. We also check if this HONDA was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra HONDA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this HONDA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this HONDA? How many owners did this HONDA have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date

More info >

Plate changes

See in this check if this HONDA had different number plates.

Number of plates	1
Current registration	
Plate since	2024-03-28
Current registration	
Plate since	2024-03-28

More info >



Finance check

Check if this HONDA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this HONDA has been settled.

If not, and you buy this HONDA then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this HONDA is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	22
First mileage registration	2006-03-31
Last registration	2023-12-27
Complete history	See info



Registration #1	2006-03-31	23 mi
Registration #2	2009-03-31	34.945 mi
Registration #3	2010-03-26	46.679 mi
Registration #4	2011-03-25	58.601 mi
Registration #5	2012-03-21	71.176 mi
Registration #6	2012-03-23	71.176 mi
Registration #7	2013-03-19	80.474 mi
Registration #8	2014-03-19	88.852 mi
Registration #9	2015-03-27	96.537 mi
Registration #10	2015-09-14	98.834 mi
Registration #11	2016-09-13	104.617 mi
Registration #12	2016-09-13	104.617 mi
Registration #13	2016-09-13	104.617 mi
Registration #14	2016-09-13	104.617 mi
Registration #15	2016-09-13	104.617 mi
Registration #16	2016-09-13	104.617 mi
Registration #17	2016-09-13	104.617 mi
Registration #18	2016-09-13	104.617 mi
Registration #19	2016-09-13	104.617 mi
Registration #20	2016-09-13	104.617 mi
Registration #21	2016-09-13	104.617 mi
Registration #22	2016-09-13	104.617 mi

More info >



Safety ratings

NCAP rating	★★★★☆
Video	see crash video



Dimensions & weight

Width	2113 mm
Height	1610 mm
Length	4285 mm
Wheel base	2680 mm
Kerb weight	1447 kg

Additional information

Fuel tank capacity	58 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	6
Engine number	K20A92003809