



TOYOTA



report date: 2024-03-28

General information

Make	TOYOTA
Model	CELICA VVTI BLUE
Colour	Blue
Year of manufacture	2005
Top speed	127 mph
0 - 60 mph	8.7 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	140 BHP
Max. torque	172 Nm at 4.200 rpm
Engine capacity	1.794 cc
Cylinders	4
Fuel type	Petrol
Consumption city	27.4 mpg
Consumption extra urban	45.6 mpg
Consumption combined	36.7 mpg
CO2 emission	185 g/km
CO2 label	I







Internet history

Entry 1

Date	2021-08-27
Pictures	5
Listing price	View report



source: [autotrader.co.uk](https://www.autotrader.co.uk)



MOT history

MOT expiry date	2024-09-04
MOT pass rate	89 %
MOT passed	16
Failed MOT tests	2
Total advice items	16
Total items failed	5

MOT #18	2023-09-05 12:39
MOT test number	666519270743
Result	✓ Passed
Next expiry date	2024-09-04
Advice	Nearside Front Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))
Advice	Offside Front Wheel bearing slightly noisy (5.1.3 (b) (i))

MOT #17	2023-09-05 12:39
MOT test number	584253367160
Result	✗ Failed
Pass with rectification	Nearside Rear Stop lamp(s) not working (4.3.1 (a) (ii))
Pass with rectification	Nearside Front Direction indicator not working (4.4.1 (a) (ii))
Advice	Nearside Front Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))
Pass with rectification	Offside Rear Stop lamp(s) not working (4.3.1 (a) (ii))
Advice	Offside Front Wheel bearing slightly noisy (5.1.3 (b) (i))

**MOT #16** 2022-09-05 08:00**MOT test number** 442981652906**Result** ✓ Passed**Advice** Offside Front Anti-roll bar linkage damaged but not seriously weakened (5.3.3 (b) (i))**Advice** Nearside Front Anti-roll bar linkage damaged but not seriously weakened (5.3.3 (b) (i))**MOT #15** 2021-06-29 10:29**MOT test number** 529487935534**Result** ✓ Passed**MOT #14** 2020-07-04 11:45**MOT test number** 100875115037**Result** ✓ Passed**Advice** Rear Brake pipe corroded, covered in grease or other material both (1.1.11 (c))**Advice** Tyre worn close to legal limit/worn on edge all (5.2.3 (e))**Advice** Offside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))**MOT #13** 2019-07-04 10:12**MOT test number** 664320542512**Result** ✓ Passed**Advice** Nearside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))**Minor** Nearside Front Anti-roll bar linkage ball joint dust cover severely deteriorated (5.3.4 (b) (i))**MOT #12** 2018-07-02 10:47**MOT test number** 318411272649**Result** ✓ Passed

**MOT #11** 2018-07-02 10:47**MOT test number** 352710623827**Result** ✗ Failed**Pass with rectification** Offside Headlamp aim too low (4.1.2 (a))**Pass with rectification** Nearside Headlamp aim too low (4.1.2 (a))**MOT #10** 2017-06-30 11:07**MOT test number** 980575082309**Result** ✓ Passed**MOT #9** 2016-07-04 10:17**MOT test number** 712254520264**Result** ✓ Passed**Advice** Front tyres slightly worn on outer edges**MOT #8** 2015-06-30 10:28**MOT test number** 995021585187**Result** ✓ Passed**Notice** Oil leak**MOT #7** 2014-07-01 11:22**MOT test number** 255232284425**Result** ✓ Passed**MOT #6** 2013-07-04 11:46**MOT test number** 328835583104**Result** ✓ Passed

**MOT #5** 2012-03-29 12:06**MOT test number** 648549082020**Result** ✓ Passed**MOT #4** 2011-03-30 13:32**MOT test number** 149729681025**Result** ✓ Passed**MOT #3** 2010-03-30 14:34**MOT test number** 200169880066**Result** ✓ Passed**Notice** N/s front tyre worn & bald on inner edge**Notice** Slight corrosion on rear brake discs**MOT #2** 2009-03-28 09:34**MOT test number** 350237689027**Result** ✓ Passed**MOT #1** 2008-04-03 16:21**MOT test number** 173364698409**Result** ✓ Passed**Advice** Nearside Front Windscreen has damage to an area less than a 40mm circle outside zone 'A'
(8.3.1d)



Tax & MOT check

✓
Taxed
Tax due:
1 June 2024

✓
MOT
Expires:
4 September 2024

Tax status	Valid until 1 June
Days left	34
MOT expiry date	4 September 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	I
Single payment (12 months)	£ 320,00,-
Single six month payment	£ 176,00,-
Total payable by 12 monthly instalments	£ 336,00,-



Damage history

Check the damage history for this TOYOTA. See if, where and when this TOYOTA had damage and the car repair costs. We also check if this TOYOTA was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	

Extra TOYOTA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this TOYOTA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,299
Auction value	£ 19,299
Average private trade value	£ 19,299

More info >



Owner history

For how long did the current and previous owner(s) have this TOYOTA? How many owners did this TOYOTA have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this TOYOTA had different number plates.

Number of plates	1
Current registration	*****
Plate since	2019-09-29
Current registration	*****
Plate since	2019-09-29

More info >



Finance check

Check if this TOYOTA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this TOYOTA has been settled. If not, and you buy this TOYOTA then you could lose the money and the car you paid for. Download the premium report [here](#) and check if this TOYOTA is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	20
First mileage registration	2005-02-14
Last registration	2023-09-05
Complete history	See info



Registration #1	2005-02-14	11 mi
Registration #2	2008-04-03	46.691 mi
Registration #3	2009-03-28	52.270 mi
Registration #4	2010-03-30	58.080 mi
Registration #5	2011-03-30	63.987 mi
Registration #6	2012-03-29	68.515 mi
Registration #7	2013-07-04	70.565 mi
Registration #8	2014-07-01	74.001 mi
Registration #9	2015-06-30	77.201 mi
Registration #10	2016-07-04	80.265 mi
Registration #11	2016-07-04	80.265 mi
Registration #12	2016-07-04	80.265 mi
Registration #13	2016-07-04	80.265 mi
Registration #14	2016-07-04	80.265 mi
Registration #15	2016-07-04	80.265 mi
Registration #16	2016-07-04	80.265 mi
Registration #17	2016-07-04	80.265 mi
Registration #18	2016-07-04	80.265 mi
Registration #19	2016-07-04	80.265 mi
Registration #20	2016-07-04	80.265 mi

More info >



Car features

The TOYOTA factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete TOYOTA factory list for this vehicle [here](#).

More info >

Dimensions & weight

Width	1735 mm
Height	1315 mm
Length	4350 mm
Wheel base	2600 mm
Kerb weight	1145 kg
Max. allowed weight	1565 kg

Additional information

Fuel tank capacity	55 l
Fuel delivery	Multi-Point Injection
Number of doors	3
Number of seats	4
Number of axles	2
Engine number	1ZZ2317949