



PEUGEOT



report date: 2024-03-29

General information

Make	PEUGEOT
Model	206 LOOK HDI
Colour	Grey
Year of manufacture	-
Top speed	104 mph
Gearbox	5 speed Manual

Engine & fuel consumption

Power	67 BHP
Max. torque	160 Nm at 1.750 rpm
Cylinders	4
Fuel type	Diesel
Consumption city	49.6 mpg
Consumption extra urban	76.4 mpg
Consumption combined	64.2 mpg



LABEL UNKNOWN



Internet history

Entry 1

Date	2021-08-03
Pictures	13
Listing price	<a href="#">View report</a>



source: [autotrader.co.uk](https://www.autotrader.co.uk)

**MOT history**

<b>MOT #18</b>	2023-02-04 09:55
<b>MOT test number</b>	499243967733
<b>Result</b>	✓ Passed
<b>Next expiry date</b>	2024-02-16
<b>Minor</b>	Nearside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))
<b>Advice</b>	Offside Front Inner Tyre worn close to legal limit/worn on edge edge worn out (5.2.3 (e))
<b>Advice</b>	Engine undertray hanging off
<b>Advice</b>	Nearside Front Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))
<b>Advice</b>	Nearside Front Inner Tyre worn close to legal limit/worn on edge edge worn (5.2.3 (e))

<b>MOT #17</b>	2023-01-28 13:49
<b>MOT test number</b>	950978856195
<b>Result</b>	✗ Failed
<b>Advice</b>	Nearside Front Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))
<b>Advice</b>	Nearside Front Inner Tyre worn close to legal limit/worn on edge edge worn (5.2.3 (e))
<b>Advice</b>	Engine undertray hanging off
<b>Minor</b>	Nearside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))
<b>Fail</b>	Nearside Front Upper Anti-roll bar linkage ball joint dust cover no longer prevents the ingress of dirt boot split (5.3.4 (b) (ii))
<b>Advice</b>	Offside Front Inner Tyre worn close to legal limit/worn on edge edge worn out (5.2.3 (e))
<b>Fail</b>	Nearside Rear Tyre has ply or cords exposed (5.2.3 (d) (ii))

**MOT #16**

2022-02-04 10:52

**MOT test number**

735411502501

**Result**

✓ Passed

**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Offside Front Play in steering rack inner joint(s)**Minor** Offside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))**Advice** Nearside Front Play in steering rack inner joint(s)**Advice** Oil leak, but not excessive (8.4.1 (a) (i))**MOT #15**

2021-02-17 11:04

**MOT test number**

449471406544

**Result**

✓ Passed

**Minor** Offside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))**Advice** Offside Front Track rod end ball joint has slight play (2.1.3 (b) (i))**Advice** Nearside Front Track rod end ball joint has slight play (2.1.3 (b) (i))**MOT #14**

2020-02-13 11:17

**MOT test number**

437220985929

**Result**

✓ Passed

**Advice** Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))**Minor** Offside Front Anti-roll bar linkage ball joint dust cover severely deteriorated (5.3.4 (b) (i))**Advice** Slight Play Inner Rack

**MOT #13** 2020-02-13 11:17**MOT test number** 382418788218**Result** ✗ Failed**Pass with rectification** Offside Rear Stop lamp(s) not working (4.3.1 (a) (ii))**Minor** Offside Front Anti-roll bar linkage ball joint dust cover severely deteriorated (5.3.4 (b) (i))**Advice** Slight Play Inner Rack**Advice** Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))**MOT #12** 2019-02-15 09:19**MOT test number** 235860521134**Result** ✓ Passed**Advice** Front Anti-roll bar linkage ball joint has slight play both sides (5.3.4 (a) (i))**Advice** Oil leak, but not excessive (8.4.1 (a) (i))**Advice** Inner Track rod end ball joint has slight play both sides (2.1.3 (b) (i))**MOT #11** 2018-02-15 13:32**MOT test number** 318673028695**Result** ✓ Passed**Advice** Nearside Front Tyre worn close to the legal limit strong advise (4.1.E.1)**Advice** Nearside Front Inner Track rod end ball joint has slight play ### STRONG ADVISE ### (2.2.B.1f)**Advice** ## strong advise ## play in steering inner joints**Advice** Offside Front Tyre worn close to the legal limit strong advise (4.1.E.1)

**MOT #10**

2018-02-15 13:32

**MOT test number**

556596588335

**Result**

✗ Failed

**Pass with rectification** Nearside Rear Registration plate lamp not working (1.1.C.1d)**Advice** ## strong advise ## play in steering inner joints**Advice** Offside Front Tyre worn close to the legal limit strong advise (4.1.E.1)**Advice** Nearside Front Tyre worn close to the legal limit strong advise (4.1.E.1)**Advice** Nearside Front Inner Track rod end ball joint has slight play ### STRONG ADVISE ### (2.2.B.1f)**MOT #9**

2017-03-30 14:18

**MOT test number**

818698616070

**Result**

✓ Passed

**Advice** Windscreen has damage to an area less than a 40mm circle outside zone 'A' nearside and offside (8.3.1d)**Advice** Nearside Front Suspension arm synthetic bush deteriorated but not resulting in excessive movement (2.4.G.2)**Advice** Slight play in inner joints**Advice** Offside Front coil spring corroded (2.4.C.1b)**MOT #8**

2016-03-24 09:24

**MOT test number**

617488868736

**Result**

✓ Passed

**MOT #7**

2015-04-24 13:43

**MOT test number**

517164315126

**Result**

✓ Passed

**Advice** Offside Front coil spring corroded (2.4.C.1b)**Notice** Play in steering rack inner joint(s)**Advice** Nearside Front Lower Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)

**MOT #6**

2015-04-24 13:43

**MOT test number**

676064115129

**Result****✗ Failed****Advice** Offside Front coil spring corroded (2.4.C.1b)**Pass with rectification** Nearside Headlamp aim beam image obviously incorrect (1.8.A.1b)**Pass with rectification** Offside Headlamp aim too high (1.8)**Advice** Nearside Front Lower Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)**Notice** Play in steering rack inner joint(s)**Pass with rectification** Nearside Headlamp aim too high (1.8)**MOT #5**

2014-04-25 11:47

**MOT test number**

777625014146

**Result****✓ Passed****Notice** Off side front tyre worn on edges**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Notice** Play in steering rack inner joint(s)**MOT #4**

2013-05-07 12:17

**MOT test number**

537577823106

**Result****✓ Passed****MOT #3**

2013-05-04 10:59

**MOT test number**

338294623169

**Result****✗ Failed****Fail** Nearside Front Suspension arm has excessive play in a ball joint (2.4.G.2)



MOT #2	2012-04-30 11:21
MOT test number	566661522168
Result	✓ Passed

MOT #1	2011-04-12 12:57
MOT test number	526352101197
Result	✓ Passed

- Advice** Nearside Front Suspension arm has slight play in a ball joint (2.4.G.2)
- Advice** Rear Exhaust has part of the system slightly deteriorated (7.1.1a)
- Advice** Offside Front Suspension arm has slight play in a ball joint (2.4.G.2)





Damage history

Check the damage history for this PEUGEOT. See if, where and when this PEUGEOT had damage and the car repair costs. We also check if this PEUGEOT was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra PEUGEOT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this PEUGEOT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this PEUGEOT? How many owners did this PEUGEOT have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this PEUGEOT had different number plates.

Number of plates	1
Current registration	<b>RE08ZSO</b>
Plate since	2019-03-29
Current registration	<b>RE08ZSO</b>
Plate since	2019-03-29

More info >



Finance check

Check if this PEUGEOT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this PEUGEOT has been settled.

If not, and you buy this PEUGEOT then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this PEUGEOT is financed.

Finance company	REDACTED	REDACTED
Date of agreement	REDACTED	REDACTED
Agreement type	REDACTED	REDACTED
Agreement term	REDACTED	REDACTED
Agreement number	REDACTED	REDACTED
Contact info	REDACTED	REDACTED

More info >



Mileage check

Odometer	In miles
Mileage registrations	19
First mileage registration	2008-04-30
Last registration	2023-02-04
Complete history	<a href="#">See info</a>



Registration #1	2008-04-30	12 mi
Registration #2	2011-04-12	14.298 mi
Registration #3	2012-04-30	19.227 mi
Registration #4	2013-05-04	25.914 mi
Registration #5	2013-05-07	25.914 mi
Registration #6	2014-04-25	34.385 mi
Registration #7	2015-04-24	46.694 mi
Registration #8	2016-03-24	55.098 mi
Registration #9	2017-03-30	63.994 mi
Registration #10	2018-02-15	71.631 mi
Registration #11	2019-05-20	75.277 mi
Registration #12	2020-05-20	75.277 mi
Registration #13	2021-05-20	75.277 mi
Registration #14	2022-05-20	75.277 mi
Registration #15	2023-05-20	75.277 mi
Registration #16	2024-05-20	75.277 mi
Registration #17	2025-05-20	75.277 mi
Registration #18	2026-05-20	75.277 mi
Registration #19	2027-05-20	75.277 mi

More info >



Car features

The PEUGEOT factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete PEUGEOT factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating



Video [see crash video](#)



Dimensions & weight

Width	1652 mm
Height	1433 mm
Length	3822 mm
Wheel base	2445 mm
Kerb weight	1061 kg
Max. allowed weight	1525 kg

Additional information

Fuel tank capacity	50 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5

<b>Number of axles</b>	2
<b>Engine number</b>	FDAF2155881