



AYI8KXS

report date: 2024-03-28

General information

Make	VOLVO
Model	XC90 D5 POWERPULSE INSCRIPTION AWD
Colour	Grey
Year of manufacture	2018
Top speed	137 mph
Gearbox	8 speed automatic

Engine & fuel consumption

Power	231 BHP
Max. torque	480 Nm at 1.750 rpm
Engine capacity	1.969 cc
Cylinders	4
Fuel type	Diesel
Consumption combined	35.3 mpg
CO2 emission	163 g/km
CO2 label	G






Internet history

Entry 2

Date	2021-08-17
Pictures	5
Listing price	View report



source: [cargurus.co.uk](https://www.cargurus.co.uk)

Entry 1

Date	2021-08-17
Pictures	5
Listing price	View report



source: [heyicar.co.uk](https://www.heyicar.co.uk)

**MOT history**

MOT expiry date	2025-03-07
MOT pass rate	67 %
MOT passed	4
Failed MOT tests	2
Total advice items	9
Total items failed	2

MOT #6	2024-02-20 15:55
MOT test number	795511512415
Result	✓ Passed
Next expiry date	2025-03-07
Advice	Brake disc worn, but not excessively Both front (1.1.14 (a) (i))
Advice	Front Brake pad(s) wearing thin (1.1.13 (a) (ii))

MOT #5	2023-03-08 10:07
MOT test number	210700668998
Result	✓ Passed

MOT #4	2023-03-02 12:16
MOT test number	482572555933
Result	✗ Failed
Fail	Nearside Rear Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (5.2.3 (d) (i))
Advice	Nearside Front Tyre has a cut but not deep enough to reach the ply or cords (5.2.3 (d) (i))

MOT #3	2022-03-01 12:20
MOT test number	535640738207
Result	✓ Passed

**MOT #2** 2021-03-03 12:20**MOT test number** 616575829476**Result** ✓ Passed

- Advice** Offside Front Play in steering rack inner joint(s)
- Advice** Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Advice** Exhaust has a minor leak of exhaust gases Metal EGR pipe underbonnet split. (6.1.2 (a))

MOT #1 2021-03-03 10:37**MOT test number** 652814428668**Result** ✗ Failed

- Fail** Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))
- Advice** Offside Front Play in steering rack inner joint(s)
- Advice** Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Advice** Exhaust has a minor leak of exhaust gases Metal EGR pipe underbonnet split. (6.1.2 (a))



Tax & MOT check

✓
Taxed
Tax due:
1 October 2024

✓
MOT
Expires:
7 March 2025

Tax status	Valid until 1 October
Days left	156
MOT expiry date	7 March 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	I
First licence fee (12 months)	£ 645,00,-
First licence fee diesel non RDE2 tested (12 months)	£ 1.040,00,-
Standard rate (12 months)	£ 180,00,-
Standard rate (6 months)	£ 99,00,-
Premium rate (12 months)	£ 570,00,-
Premium rate (6 months)	£ 313,50,-



Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners did this VOLVO have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date

More info >

Plate changes

See in this check if this VOLVO had different number plates.

Number of plates	1
Current registration	AY18KXS
Plate since	2019-09-28
Current registration	AY18KXS
Plate since	2019-09-28

More info >



Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLVO is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	9
First mileage registration	2018-03-07
Last registration	2024-02-20
Complete history	See info



Registration #1	2018-03-07	25 mi
Registration #2	2021-03-03	48.734 mi
Registration #3	2021-03-03	48.734 mi
Registration #4	2022-03-03	55.777 mi
Registration #5	2023-03-03	62.820 mi
Registration #6	2024-02-20	69.863 mi
Registration #7		
Registration #8		
Registration #9		

More info >



Car features

The VOLVO factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLVO factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	97%
Children	87%
Pedestrian	72%
Safety systems	94%
Overall rating	89%
Video	see crash video



Dimensions & weight

Width	2008 mm
Height	1776 mm
Length	4950 mm
Max. allowed weight	2750 kg

Additional information

Number of seats	7
Number of axles	2
Engine number	2422425