





report date: 2024-03-29

## General information

Make	FORD
Model	TRANSIT 430 SHR BUS 17 STR
Colour	White
Year of manufacture	2014
Gearbox	6 speed Manual

# Engine & fuel consumption

Power	133 BHP
Max. torque	355 Nm at 1.500 rpm
Engine capacity	2.198 cc
Cylinders	4
Fuel type	Diesel



CarCheck.co.uk page 1/12



# Internet history

## Entry 1

Date 2021-11-06

Pictures 13

Listing price <u>View report</u>









source: yesauto.com

CarCheck.co.uk page 2/12



MOT history

MOT expiry date	2024-12-07
MOT pass rate	67 %
MOT passed	8
Failed MOT tests	4
Total advice items	11
Total items failed	12

MOT #12	2023-12-06 15:06
MOT test number	315686708785
Result	<b>✓</b> Passed
Next expiry date	2024-12-07
Advice Nearside Front Lower Suspension arm pin or bush worn but not res rear bush (5.3.4 (a) (i))	ulting in excessive movement

MOT #11	2023-12-04 12:17
MOT test number	364691221655
Result	<b>×</b> Failed
Fail Nearside Front Tyre has ply or cords exposed (5.2.3 (d) (ii))	
Advice Nearside Front Lower Suspension arm pin or bush worn but not resulting rear bush (5.3.4 (a) (i))	ng in excessive movement
Minor Offside Front Windscreen wiper blade defective (3.4 (b) (i))	
Advice Tyre worn close to legal limit/worn on edge all tyres (5.2.3 (e))	
Fail Offside Front Lower Suspension arm ball joint dust cover no longer preven (b) (ii))	ts the ingress of dirt (5.3.4

MOT #10	2022-12-07 14:07
MOT test number	545388390528
Result	✓ Passed
Advice Nearside Front Suspension arm pin or bush worn but not resulting in arm rear bush (5.3.4 (a) (i))  Advice Suspect slight dampness of oil on offside rear outer half shaft.	excessive movement Lower

CarCheck.co.uk page 3/12



AF64VXY

report date: 2024-03-29

MOT #9 2022-12-01 10:36

MOT test number 208285442069

Result X Failed

Fail Central Outer Seat belt buckle damaged Second row outer seat cover missing sharp edges. (7.1.2 (d))

Fail Offside Front Side repeater missing (4.4.1 (a) (ii))

**Advice** Suspect slight dampness of oil on offside rear outer half shaft.

Fail Offside Rear Seat belt buckle damaged Back seat cover missing sharp edges (7.1.2 (d))

**Advice** Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement Lower arm rear bush (5.3.4 (a) (i))

Fail Nearside Rear Seat belt buckle not functioning as intended Second row outer seat (7.1.2 (d))

MOT #8 2021-12-08 14:31

**MOT test number** 347921992909

**Result** ✓ Passed

**MOT #7** 2021-11-26 09:14

MOT test number 286225179262

Result X Failed

Fail Nearside Rear Brake disc in such a condition that it is seriously weakened (1.1.14 (a) (ii))

Fail Offside Front Brake disc in such a condition that it is seriously weakened (1.1.14 (a) (ii))

Fail Offside Rear Brake disc in such a condition that it is seriously weakened (1.1.14 (a) (ii))

**Fail** Service brake efficiency below requirements (1.2.2 (a) (i))

Fail Nearside Front Brake disc in such a condition that it is seriously weakened (1.1.14 (a) (ii))

MOT #6 2021-02-05 09:00

**MOT test number** 551769219078

CarCheck.co.uk page 4/12



MOT #5 2021-02-04 16:29

**MOT test number** 736019992756

Result × Failed

Fail Power steering pipe/hose leaking return pipe leaking at rack (2.1.5 (a))

MOT #4 2019-08-01 07:12

**MOT test number** 950177666634

Advice Front Brake pad(s) wearing thin getting low (1.1.13 (a) (ii))

**Advice** Nearside side repeater cracked and full of water

MOT #3 2018-07-05 13:41

**MOT test number** 231325207221

**Result** ✓ Passed

**Advice** Offside Rear hub seal leaking

MOT #2 2017-07-01 09:43

MOT test number 160804996665

**Result** ✓ Passed

**MOT #1** 2016-06-14 14:37

**MOT test number** 412441467658

**Result** ✓ Passed

CarCheck.co.uk page 5/12



7 December 2024

See MOT history

### Tax & MOT check

**MOT** expiry date

**Full MOT history** 



CarCheck.co.uk page 6/12



AF64VXY

report date: 2024-03-29

### Damage history

Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report <u>here</u> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



#### Extra FORD salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 7/12



### Vehicle valuation

What is this car worth? See the vehicle value of this FORD in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

**Trade retail value** 

**Auction value** 

Average private trade value

More info >

CarCheck.co.uk page 8/12



Owner history	
For how long did the current and previous owner(s) have this FORD? How many owners check it in the premium report and see all owner registrations. Download the full report	
********	
***************************************	
	More info >
Plate changes	
See in this check if this FORD had different number plates.	
Number of plates	,
Current registration	SK UK
Plate since	
Current registration	NK SIE
Plate since	
	More info >

CarCheck.co.uk page 9/12



### Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this FORD is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

More info >

CarCheck.co.uk page 10/12



Mileage check

Registration #14

Odometer	In kilometers
Mileage registrations	14
First mileage registration	2014-09-29
Last registration	2023-12-06
Complete history	See info



Registration #1	2014-09-29	7 mi
Registration #2	2016-06-14	5.429 mi
Registration #3	2017-07-01	8.435 mi
Registration #4	2018-07-05	15.365 mi
Registration #5	2019-08-01	24.395 mi
Registration #6	2021-02-04	30.184 mi
Registration #7	2021-02-05	30.184 mi
Registration #8		71.777 es
Registration #9		11.777 es
Registration #10		11.777 es
Registration #11		9.70 es
Registration #12		11.777 es
Registration #13		11.777 es

mn.n.n

More info >

77.777 86

CarCheck.co.uk page 11/12



Car features

50225	Air conditionin
50295	
50482	
50501	
60566	
60567	
50569	

# Safety ratings

NCAP rating	****
Adult	84%
Children	90%
Pedestrian	48%
Safety systems	71%
Overall rating	76%
Video	see crash video



# Additional information

Fuel delivery	Direct Injection
Number of doors	5
Number of seats	17
Engine number	DD18442

CarCheck.co.uk page 12/12