



report date: 2024-03-29

General information

Make	BMW
Model	525 525i SE
Colour	Blue
Year of manufacture	2004
Top speed	145 mph
0 - 60 mph	8.7 seconds
Gearbox	6 speed automatic

Engine & fuel consumption

Power	189 BHP
Max. torque	245 Nm at 3.500 rpm
Engine capacity	2.494 cc
Cylinders	6
Fuel type	Petrol
Consumption city	20.0 mpg
Consumption extra urban	37.7 mpg
Consumption combined	28.5 mpg
CO2 emission	239 g/km
CO2 label	L






Internet history

Entry 1

Date	2021-12-06
Pictures	18
Listing price	View report



source: autotrader.co.uk



MOT history

MOT expiry date	2024-10-05
MOT pass rate	74 %
MOT passed	17
Failed MOT tests	6
Total advice items	48
Total items failed	11

MOT #23	2023-09-29 12:01
---------	------------------

MOT test number	320209455811
-----------------	--------------

Result	✓ Passed
--------	----------

Next expiry date	2024-10-05
------------------	------------

- Advice** Offside Front Shock absorbers has light misting of oil (5.3.2 (b))
- Advice** Nearside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
- Advice** Nearside Rear Lower Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
- Advice** Nearside Front Shock absorbers has light misting of oil (5.3.2 (b))
- Advice** Offside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
- Advice** Offside Rear Lower Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

**MOT #22**

2023-09-29 12:01

MOT test number

430379526384

Result**✗ Failed**

Advice Nearside Rear Lower Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

Advice Nearside Front Shock absorbers has light misting of oil (5.3.2 (b))

Pass with rectification Offside Front Road wheel fixing loose (5.2.1 (a) (i))

Advice Offside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

Advice Offside Rear Lower Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

Advice Offside Front Shock absorbers has light misting of oil (5.3.2 (b))

Advice Nearside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

MOT #21

2022-10-04 14:24

MOT test number

316975492372

Result**✓ Passed**

Advice Nearside Front Shock absorbers has light misting of oil (5.3.2 (b))

Advice Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Rear Anti-roll bar corroded but not seriously weakened (5.3.3 (b) (i))

**MOT #20**

2021-10-05 13:38

MOT test number

686287806663

Result

✓ Passed

- Advice** Offside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))
- Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Nearside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))
- Advice** Nearside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))
- Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Rear Anti-roll bar corroded but not seriously weakened (5.3.3 (b) (i))
- Advice** Offside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))

MOT #19

2021-10-05 13:38

MOT test number

668311184646

Result

✗ Failed

- Advice** Offside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))
- Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Offside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))
- Pass with rectification** Nearside Front Headlamp aim projected beam image is obviously incorrect (4.1.2 (c))
- Advice** Nearside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))
- Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Nearside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))
- Advice** Rear Anti-roll bar corroded but not seriously weakened (5.3.3 (b) (i))
- Pass with rectification** Front Windscreen washer provides insufficient washer liquid (3.5 (a))

**MOT #18** 2020-10-02 09:52**MOT test number** 803082510447**Result** ✓ Passed**Advice** Oil leak, but not excessive (8.4.1 (a) (i))**MOT #17** 2019-04-02 08:13**MOT test number** 877679047559**Result** ✓ Passed**MOT #16** 2018-04-06 12:46**MOT test number** 777453790090**Result** ✓ Passed**Advice** Nearside Rear Brake pipe slightly corroded (3.6.B.2c)**Advice** Offside Rear Brake pipe slightly corroded (3.6.B.2c)**MOT #15** 2017-03-27 11:19**MOT test number** 775663988900**Result** ✓ Passed**Advice** Both front bottom suspension arm rubber bushes perished and movement**Advice** Oil leak

**MOT #14** 2017-03-23 11:40**MOT test number** 594080544911**Result** ✗ Failed

Fail Offside Front Anti-roll bar linkage ball joint dust cover excessively deteriorated so that it no longer prevents the ingress of dirt (2.4.G.2)

Advice Oil leak

Fail Nearside Anti-roll bar linkage ball joint dust cover excessively deteriorated so that it no longer prevents the ingress of dirt (2.4.G.2)

Fail Front Brakes imbalanced across an axle (3.7.B.5b)

Advice Both front bottom suspension arm rubber bushes perished and movement

MOT #13 2016-03-24 17:20**MOT test number** 127884037017**Result** ✓ Passed

Advice Offside Rear Brake pipe slightly corroded to flexible brake pipe (3.6.B.2c)

MOT #12 2016-03-24 10:23**MOT test number** 402512744562**Result** ✗ Failed

Advice Nearside Rear Tyre worn close to the legal limit (4.1.E.1)

Fail Offside Rear Tyre tread depth below requirements of 1.6mm 225/50/17w runflat (4.1.E.1)

Advice Offside Rear Brake pipe slightly corroded to flexible brake pipe (3.6.B.2c)

MOT #11 2015-04-01 18:07**MOT test number** 608271295073**Result** ✓ Passed

**MOT #10** 2014-04-04 15:39**MOT test number** 925784994021**Result** ✓ Passed**Advice** Rear Anti-roll bar corroded but not seriously weakened (2.4.G.1)**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**MOT #9** 2013-03-25 14:18**MOT test number** 486604183066**Result** ✓ Passed**MOT #8** 2012-03-21 16:58**MOT test number** 795891482070**Result** ✓ Passed**Notice** Offside front drop link upper rubber dust cover split**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**MOT #7** 2012-03-21 16:07**MOT test number** 307761082028**Result** ✗ Failed**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**Fail** Windscreen washer provides insufficient washer liquid (8.2.3)**MOT #6** 2011-04-05 12:28**MOT test number** 968815091072**Result** ✓ Passed**MOT #5** 2010-03-04 11:57**MOT test number** 162813260014**Result** ✓ Passed

**MOT #4** 2009-06-08 12:58**MOT test number** 810809259109**Result** ✓ Passed**MOT #3** 2009-06-05 12:08**MOT test number** 684616459184**Result** ✗ Failed**Notice** Advise tracking**Fail** Nearside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1)**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**Fail** Nearside Headlamp aim too low (1.8)**Fail** Offside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**MOT #2** 2008-03-14 14:39**MOT test number** 181924778045**Result** ✓ Passed**MOT #1** 2007-03-13 13:35**MOT test number** 620282277026**Result** ✓ Passed



Tax & MOT check

X

Untaxed

Tax expired:
23 April 2024

✓

MOT

Expires:
5 October 2024

Tax status	Expired at 23 April 2024
Days left	7 days too late
MOT expiry date	5 October 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	K
Single payment (12 months)	£ 395,00,-
Single six month payment	£ 217,25,-
Total payable by 12 monthly instalments	£ 414,75,-



Damage history

Check the damage history for this BMW. See if, where and when this BMW had damage and the car repair costs. We also check if this BMW was scrapped. Download the premium report [here](#) for the results.

Damage 1	
Date	
Category	
Type	
Damage 2	
Date	
Category	
Type	



Extra BMW salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this BMW in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this BMW? How many owners did this BMW have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date

More info >

Plate changes

See in this check if this BMW had different number plates.

Number of plates	1
Current registration	RK04YDR
Plate since	2024-03-29
Current registration	RK04YDR
Plate since	2024-03-29

More info >



Finance check

Check if this BMW is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this BMW has been settled.

If not, and you buy this BMW then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this BMW is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	25
First mileage registration	2004-03-01
Last registration	2023-09-29
Complete history	See info



Registration #1	2004-03-01	12 mi
Registration #2	2007-03-13	20.418 mi
Registration #3	2008-03-14	36.499 mi
Registration #4	2009-06-05	46.416 mi
Registration #5	2009-06-08	46.442 mi
Registration #6	2010-03-04	53.674 mi
Registration #7	2011-04-05	61.518 mi
Registration #8	2012-03-21	67.312 mi
Registration #9	2012-03-21	67.312 mi
Registration #10	2013-03-25	75.338 mi
Registration #11	2014-04-04	80.966 mi
Registration #12	2015-04-01	83.788 mi
Registration #13	2016-03-24	93.888 mi
Registration #14	2016-03-24	93.888 mi
Registration #15	2016-03-24	93.888 mi
Registration #16	2016-03-24	93.888 mi
Registration #17	2016-03-24	93.888 mi
Registration #18	2016-03-24	93.888 mi
Registration #19	2016-03-24	93.888 mi
Registration #20	2016-03-24	93.888 mi
Registration #21	2016-03-24	93.888 mi
Registration #22	2016-03-24	93.888 mi
Registration #23	2016-03-24	93.888 mi
Registration #24	2016-03-24	93.888 mi
Registration #25	2016-03-24	93.888 mi



Car features

The BMW factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete BMW factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1846 mm
Height	1468 mm
Length	4841 mm
Wheel base	2888 mm
Kerb weight	1575 kg
Max. allowed weight	2060 kg

Additional information

Fuel tank capacity	70 l
Fuel delivery	Multi-Point Injection
Number of doors	4
Number of seats	5

Number of axles	2
Engine number	31023343