



report date: 2024-03-28

General information

| | |
|---------------------|----------------|
| Make | FIAT |
| Model | 500C LOUNGE |
| Colour | Purple |
| Year of manufacture | 2015 |
| Top speed | 99 mph |
| 0 - 60 mph | 12.9 seconds |
| Gearbox | 5 speed Manual |

Engine & fuel consumption

| | |
|-------------------------|---------------------|
| Power | 69 BHP |
| Max. torque | 102 Nm at 3.000 rpm |
| Engine capacity | 1.242 cc |
| Cylinders | 4 |
| Fuel type | Petrol |
| Consumption city | 51.4 mpg |
| Consumption extra urban | 65.7 mpg |
| Consumption combined | 60.1 mpg |
| CO2 emission | 111 g/km |
| CO2 label | C |






Internet history

Entry 2

| | |
|---------------|-----------------------------|
| Date | 2022-01-01 |
| Pictures | 23 |
| Listing price | View report |



source: yesauto.com

Entry 1

| | |
|---------------|-----------------------------|
| Date | 2021-12-15 |
| Pictures | 0 |
| Listing price | View report |

source: autotrader.co.uk



MOT history

| | |
|--------------------|------------|
| MOT expiry date | 2024-11-23 |
| MOT pass rate | 58 % |
| MOT passed | 7 |
| Failed MOT tests | 5 |
| Total advice items | 23 |
| Total items failed | 6 |

| | |
|------------------|------------------|
| MOT #12 | 2023-11-24 14:30 |
| MOT test number | 570072680960 |
| Result | ✓ Passed |
| Next expiry date | 2024-11-23 |

| | |
|-----------------|---|
| MOT #11 | 2023-11-22 11:31 |
| MOT test number | 199424532056 |
| Result | ✗ Failed |
| Advice | Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e)) |
| Fail | Nearside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e)) |

| | |
|-----------------|--|
| MOT #10 | 2022-11-02 17:01 |
| MOT test number | 709475325985 |
| Result | ✓ Passed |
| Advice | Rear Sub-frame corroded but not seriously weakened (5.3.3 (b) (i)) |

| | |
|-----------------|---|
| MOT #9 | 2022-11-02 11:09 |
| MOT test number | 934021013430 |
| Result | ✗ Failed |
| Advice | Rear Sub-frame corroded but not seriously weakened (5.3.3 (b) (i)) |
| Fail | Offside Front Lower Suspension arm pin or bush likely to become detached rear bush (5.3.4 (a) (ii)) |



| | |
|------------------------|------------------|
| MOT #8 | 2021-11-22 16:19 |
| MOT test number | 496187049910 |
| Result | ✓ Passed |

| | |
|------------------------|------------------|
| MOT #7 | 2021-02-17 13:13 |
| MOT test number | 950642025957 |
| Result | ✓ Passed |

- Minor** Offside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))
- Advice** Items removed from driver's view prior to test
- Advice** Nearside Rear Upper Shock absorbers has a slightly worn bush (5.3.2 (c))
- Advice** Offside Rear Tyre worn close to legal limit/worn on edge 3mm (5.2.3 (e))
- Advice** Offside Rear Upper Shock absorbers has a slightly worn bush (5.3.2 (c))

| | |
|------------------------|------------------|
| MOT #6 | 2021-02-15 09:32 |
| MOT test number | 268431493741 |
| Result | ✗ Failed |

- Advice** Nearside Rear Upper Shock absorbers has a slightly worn bush (5.3.2 (c))
- Minor** Offside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))
- Advice** Items removed from driver's view prior to test
- Fail** Nearside Front Lower Steering linkage ball joint has excessive play (2.1.3 (b) (i))
- Advice** Offside Rear Upper Shock absorbers has a slightly worn bush (5.3.2 (c))
- Advice** Offside Rear Tyre worn close to legal limit/worn on edge 3mm (5.2.3 (e))

**MOT #5** 2020-02-12 09:51**MOT test number** 861609111483**Result** ✓ Passed**Advice** Offside Front Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))**Advice** Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Advice** Nearside Front Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))**Advice** Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**MOT #4** 2019-02-16 09:22**MOT test number** 256886273980**Result** ✓ Passed**Advice** Nearside Front Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))**Advice** Offside Front Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))**MOT #3** 2019-02-05 09:02**MOT test number** 590804849498**Result** ✗ Failed**Advice** Offside Front Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))**Fail** Anti-lock braking system warning lamp indicates an ABS fault Lamp flashes when right indicator is on.
(1.6 (b))**Advice** Offside Front Track rod end ball joint has slight play (2.1.3 (b) (i))**MOT #2** 2018-02-01 11:44**MOT test number** 604344062654**Result** ✓ Passed**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)



| | |
|-------------------------|---|
| MOT #1 | 2018-02-01 11:44 |
| MOT test number | 476227477688 |
| Result | ✗ Failed |
| Pass with rectification | Nearside Headlamp aim too high (1.8) |
| Advice | Nearside Front Tyre worn close to the legal limit (4.1.E.1) |
| Pass with rectification | Offside Headlamp aim too high (1.8) |



Tax & MOT check

✓
Taxed
Tax due:
1 July 2024

✓
MOT
Expires:
23 November 2024

| | |
|-------------------------|---------------------------------|
| Tax status | Valid until 1 July |
| Days left | 64 |
| MOT expiry date | 23 November 2024 |
| Full MOT history | See MOT history |

Tax calculation

| | |
|--|----------------|
| Vehicle class | 48 |
| Band | C |
| Single payment (12 months) | £ 35,00,- |
| Single six month payment | Not applicable |
| Total payable by 12 monthly instalments | £ 36,75,- |



Damage history

Check the damage history for this FIAT. See if, where and when this FIAT had damage and the car repair costs. We also check if this FIAT was scrapped. Download the premium report [here](#) for the results.

Damage 1

| | |
|----------|--|
| Date | |
| Category | |
| Type | |

Damage 2

| | |
|----------|--|
| Date | |
| Category | |
| Type | |



Extra FIAT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this FIAT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

| | |
|-----------------------------|----------|
| Trade retail value | £ 19,999 |
| Auction value | £ 19,999 |
| Average private trade value | £ 19,999 |

More info >



Owner history

For how long did the current and previous owner(s) have this FIAT? How many owners did this FIAT have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

| | | |
|-------|------|----|
| Owner | From | To |
| Owner | From | To |
| Owner | From | To |
| Owner | From | To |
| Owner | From | To |
| Owner | From | To |
| Owner | From | To |

More info >

Plate changes

See in this check if this FIAT had different number plates.

| | |
|----------------------|------------|
| Number of plates | 1 |
| Current registration | |
| Plate since | 2024-03-28 |
| Current registration | |
| Plate since | 2024-03-28 |

More info >



Finance check

Check if this FIAT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FIAT has been settled.

If not, and you buy this FIAT then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this FIAT is financed.

| | |
|-------------------|-------------|
| Finance company | XXXXXXXX XX |
| Date of agreement | XXXXXXXX XX |
| Agreement type | XXXXXXXX XX |
| Agreement term | XXXXXXXX XX |
| Agreement number | XXXXXXXX XX |
| Contact info | XXXXXXXX XX |

More info >



Mileage check

| | |
|----------------------------|--------------------------|
| Odometer | In miles |
| Mileage registrations | 15 |
| First mileage registration | 2015-02-13 |
| Last registration | 2023-11-24 |
| Complete history | See info |



| | | |
|------------------|------------|-----------|
| Registration #1 | 2015-02-13 | 21 mi |
| Registration #2 | 2018-02-01 | 25.831 mi |
| Registration #3 | 2018-02-01 | 25.831 mi |
| Registration #4 | 2019-02-05 | 31.429 mi |
| Registration #5 | 2019-02-16 | 31.458 mi |
| Registration #6 | 2020-02-12 | 41.623 mi |
| Registration #7 | 2021-02-15 | 51.291 mi |
| Registration #8 | 2021-02-17 | 51.291 mi |
| Registration #9 | 2022-02-01 | 51.291 mi |
| Registration #10 | 2022-02-01 | 51.291 mi |
| Registration #11 | 2022-02-01 | 51.291 mi |
| Registration #12 | 2022-02-01 | 51.291 mi |
| Registration #13 | 2022-02-01 | 51.291 mi |
| Registration #14 | 2022-02-01 | 51.291 mi |
| Registration #15 | 2023-11-24 | 51.291 mi |

More info >



Car features

The FIAT factory car options list is only available in the premium report.

| | |
|-------|------------------|
| S0225 | Air conditioning |
| S0295 | |
| S0482 | |
| S0501 | |
| S0566 | |
| S0567 | |
| S0569 | |

View the complete FIAT factory list for this vehicle [here](#).

More info >

Safety ratings

| | |
|-------------|---------------------------------|
| NCAP rating | ★★★★★ |
| Video | see crash video |



Dimensions & weight

| | |
|---------------------|---------|
| Width | 1627 mm |
| Height | 1488 mm |
| Length | 3571 mm |
| Wheel base | 2300 mm |
| Kerb weight | 865 kg |
| Max. allowed weight | 1305 kg |

Additional information

| | |
|--------------------|-----------------------|
| Fuel tank capacity | 35 l |
| Fuel delivery | Multi-Point Injection |
| Number of doors | 3 |
| Number of seats | 4 |

| | |
|------------------------|---------|
| Number of axles | 2 |
| Engine number | 1197677 |