





report date: 2024-03-29

General information

Make	ТОУОТА
Model	RAV-4 VVT-I XT-R
Colour	Black
Year of manufacture	2005
Top speed	115 mph
0 - 60 mph	10.6 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	147 BHP
Max. torque	192 Nm at 4.000 rpm
Engine capacity	1.998 сс
Cylinders	4
Fuel type	Petrol
Consumption city	25.0 mpg
Consumption extra urban	39.2 mpg
Consumption combined	32.5 mpg
CO2 emission	207 g/km
CO2 label	K



CarCheck.co.uk page 1/13



Internet history

KV05AWW
report date: 2024-03-29

Entry 1


Date 2021-12-11

Pictures 10

Listing price <u>View report</u>









source: autotrader.co.uk

CarCheck.co.uk page 2/13



KV05AWW
report date: 2024-03-29

MOT history

MOT expiry date	2024-09-04
MOT pass rate	89 %
MOT passed	17
Failed MOT tests	2
Total advice items	15
Total items failed	4

MOT #19	2023-09-05 09:52
MOT test number	239239255727
Result	✓ Passed
Next expiry date	2024-09-04
Advice Offside Front Service brake binding but not excessively (1.2.1 (f))	

MOT #18	2022-09-02 0	9:35
MOT test	224463863	3224
Result	✓ Pa	ssed
Advice	Rear Lower Shock absorbers has a slightly worn bush both sides (5.3.2 (c))	
Minor Nearside Front Upper Anti-roll bar linkage ball joint dust cover severely deteriorated (5.3.4 (b) (i))))
Advice Front Headlamp has a product on the lens but not seriously reducing light output both sides (4.1.4 (b))		1.4
Minor	Nearside Front Lower Suspension arm ball joint dust cover severely deteriorated (5.3.4 (b) (i))	

MOT #17	2021-08-27 10:54
MOT test number	667395733351
Result	✓ Passed
MOT #16	2020-09-04 11:53
MOT test number	831706754825
Result	✓ Passed

CarCheck.co.uk page 3/13



report date: 2024-03-29

MOT #15 2019-10-07 12:35

MOT test number 921396329224

Result ✓ Passed

MOT #14 2018-10-10 12:41

MOT test number 216683763226

Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Rear Exhaust has a minor leak of exhaust gases (6.1.2 (a))

MOT #13 2018-09-27 12:33

MOT test number 282940510942

Result X Failed

Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Rear Exhaust has a minor leak of exhaust gases (6.1.2 (a))

Fail Nearside Front Service brake excessively binding (1.2.1 (f))

Fail Nearside Front Shock absorbers has a serious fluid leak (5.3.2 (b))

MOT #12 2017-09-12 08:49

MOT test number 831389740322

Result ✓ Passed

MOT #11 2016-09-09 09:29

MOT test number 952444871831

Result
✓ Passed

CarCheck.co.uk page 4/13



report date: 2024-03-29

MOT #10 2015-09-11 12:57

MOT test number 769247125564

Result \rightarrow Passed

Advice Offside Rear Inner Suspension component mounting prescribed area is corroded but not considered excessive (2.4.A.3)

Advice Nearside Rear Inner Suspension component mounting prescribed area is corroded but not considered excessive (2.4.A.3)

MOT #9 2014-09-05 12:41

MOT test number 866658844201

MOT #8 2014-09-05 12:41

MOT test number 175798044236

Result X Failed

Pass with rectification Rear Registration plate lamp not working (1.1.C.1d)

Pass with rectification Offside Front Front position lamp(s) not working (1.1.A.3b)

MOT #7 2013-09-12 12:14

MOT test number 519055553220

Result

Passed

Advice Nearside Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

Advice Rear Exhaust has a minor leak of exhaust gases (7.1.2)

Advice Offside Front Shock absorber has a light misting of oil (2.7.3)

Advice Offside Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

MOT #6 2012-09-06 09:17

MOT test number 319760252263

Result

Passed

CarCheck.co.uk page 5/13



report date: 2024-03-29

MOT #5	2011-09-14 15:47
MOT test number	329687551453
Result	✓ Passed
MOT #4	2010-11-22 14:15
MOT test number	870826520310
Result	✓ Passed
MOT #3	2009-11-13 10:42
MOT test number	711887219381
Result	✓ Passed
MOT #2	2008-11-14 15:49
MOT test number	170589818320
Result	✓ Passed
MOT #1	2008-03-21 09:54
MOT test number	183681588040
Result	✓ Passed

CarCheck.co.uk page 6/13





report date: 2024-03-29

Tax & MOT check



Tax status	Valid until 1 June
Days left	33
MOT expiry date	4 September 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	K
Single payment (12 months)	£ 395,00,-
Single six month payment	£ 217,25,-
Total payable by 12 monthly instalments	£ 414,75,-

CarCheck.co.uk page 7/13



report date: 2024-03-29

Damage history

Check the damage history for this TOYOTA. See if, where and when this TOYOTA had damage and the car repair costs. We also check if this TOYOTA was scrapped. Download the premium report here for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra TOYOTA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 8/13



report date: 2024-03-29

Vehicle valuation

What is this car worth? See the vehicle value of this TOYOTA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 9/13



report date: 2024-03-29

e union matery	
For how long did the current and previous owner(s) have this TOYOTA? How many owner have? Check it in the premium report and see all owner registrations. Download the full respectively.	

	More info >
Plate changes	
See in this check if this TOYOTA had different number plates.	
Number of plates	,
Current registration	UK UK
Plate since	*****
Current registration	IIK NEW TOWN
Plate since	
	More info >

CarCheck.co.uk page 10/13



KV05AWW
report date: 2024-03-29

Finance check

Check if this TOYOTA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this TOYOTA has been settled.

If not, and you buy this TOYOTA then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this TOYOTA is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

More info >

CarCheck.co.uk page 11/13





report date: 2024-03-29

Mileage check

Odometer	In miles
Mileage registrations	20
First mileage registration	2005-03-23
Last registration	2023-09-05
Complete history	See info



Registration #1	2005-03-23	27 mi
Registration #2	2008-03-21	38.318 mi
Registration #3	2008-11-14	43.761 mi
Registration #4	2009-11-13	48.263 mi
Registration #5	2010-11-22	52.809 mi
Registration #6	2011-09-14	55.267 mi
Registration #7	2012-09-06	61.395 mi
Registration #8	2013-09-12	68.441 mi
Registration #9	2014-09-05	75.539 mi
Registration #10	2015-09-11	85.681 mi
Registration #11		11.777 es
Registration #12		11.777 es
Registration #13		11.777 es
Registration #14		11.777 es
Registration #15		11.777 es
Registration #16		11.777 es
Registration #17		11.777 es
Registration #18		11.777 es
Registration #19		11.777 es
Registration #20		n.m.

More info >

CarCheck.co.uk page 12/13



report date: 2024-03-29

Car features

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

Dimensions & weight

Width	1785 mm
Height	1685 mm
Length	3870 mm
Wheel base	2280 mm
Kerb weight	1325 kg
Max. allowed weight	1685 kg

Additional information

Fuel tank capacity	57 I
Fuel delivery	Multi-Point Injection
Number of doors	3
Number of seats	5
Number of axles	2
Engine number	1AZ1815993

CarCheck.co.uk page 13/13