




report date: 2024-03-28

## General information

Make	VOLKSWAGEN
Model	TOURAN TDI SPORT DSG 7 STR
Colour	Grey
Year of manufacture	2004
Top speed	123 mph
0 - 60 mph	10.3 seconds
Gearbox	6 speed automatic

## Engine & fuel consumption

Power	138 BHP
Max. torque	320 Nm at 1.750 rpm
Engine capacity	1.968 cc
Cylinders	4
Fuel type	Diesel
Consumption city	34.0 mpg
Consumption extra urban	52.3 mpg
Consumption combined	43.5 mpg
CO2 emission	178 g/km
CO2 label	I





## MOT history

MOT expiry date	2020-12-28
MOT pass rate	90 %
MOT passed	9
Failed MOT tests	1
Total advice items	21
Total items failed	3

MOT #10 2019-12-28 16:05

MOT test number 267698684521

Result ✓ Passed

Next expiry date 2020-12-28

**Advice** Direction indicator slightly discoloured both rear (4.4.3 (a))

**Minor** Stop lamp(s) emits other than a steady red light top one (4.3.3 (a) (i))

MOT #9 2018-12-29 12:59

MOT test number 766308880459

Result ✓ Passed

**Advice** Passenger seat(s) missing at time of test all rear

**Advice** Handbrake has alot of travel

**Advice** Front Brake disc worn, pitted or scored, but not seriously weakened both (1.1.14 (a) (ii))

**MOT #8**

2018-12-19 17:22

**MOT test number**

584142121316

**Result****✗ Failed**

- Advice** Handbrake has alot of travel
- Advice** Passenger seat(s) missing at time of test all rear
- Advice** Front Brake disc worn, pitted or scored, but not seriously weakened both (1.1.14 (a) (ii))
- Fail** Nearside Front Headlamp aim projected beam image is obviously incorrect kick up to right (4.1.2 (c))
- Fail** Nearside Front Suspension arm ball joint excessively worn (5.3.4 (a) (i))
- Minor** Front Track rod end ball joint dust cover damaged or deteriorated, but preventing the ingress of dirt both boots cracking (2.1.3 (g) (i))
- Fail** Offside Front Headlamp aim projected beam image is obviously incorrect kick up to right (4.1.2 (c))

**MOT #7**

2014-10-03 14:20

**MOT test number**

956006774266

**Result****✓ Passed**

- Advice** Direction indicator slightly discoloured (1.4.A.2f)
- Notice** Engine management light on
- Advice** Offside Outer Front constant velocity joint gaiter damaged, but preventing the ingress of dirt (2.5.C.1a)
- Notice** Front and rear number plates slightly discoloured
- Notice** Both wipers slightly smearing screen

**MOT #6** 2013-07-31 16:24**MOT test number** 198592513227**Result** ✓ Passed**Advice** Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)**Advice** Brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Advice** Offside Front Front constant velocity joint gaiter damaged, but preventing the ingress of dirt (2.5.C.1a)**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**MOT #5** 2012-08-15 17:00**MOT test number** 555698822268**Result** ✓ Passed**Advice** Front Brake pad(s) wearing thin (3.5.1g)**MOT #4** 2011-07-01 12:19**MOT test number** 238272081171**Result** ✓ Passed**MOT #3** 2010-01-25 14:35**MOT test number** 251595820009**Result** ✓ Passed**MOT #2** 2009-02-05 14:15**MOT test number** 642306539077**Result** ✓ Passed



MOT #1	2007-12-15 12:54
MOT test number	923379147355
Result	✓ Passed
Advice	Offside Windscreen has damage to an area less than a 10mm circle within zone 'A' (8.3.1a)
Advice	Nearside Front constant velocity joint gaiter deteriorated (2.5.C.1a)



Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this VOLKSWAGEN had different number plates.

Number of plates	1
Current registration	 <b>KP54WVZ</b>
Plate since	2024-03-28
Current registration	 <b>KP54WVZ</b>
Plate since	2024-03-28

More info >





Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLKSWAGEN is financed.

Finance company	REDACTED	REDACTED
Date of agreement	REDACTED	REDACTED
Agreement type	REDACTED	REDACTED
Agreement term	REDACTED	REDACTED
Agreement number	REDACTED	REDACTED
Contact info	REDACTED	REDACTED

More info >



Mileage check

Odometer	In miles
Mileage registrations	10
First mileage registration	2004-12-22
Last registration	2019-12-28
Complete history	<a href="#">See info</a>



Registration #1	2004-12-22	13 mi
Registration #2	2007-12-15	106.194 mi
Registration #3	2009-02-05	119.661 mi
Registration #4	2010-01-25	129.095 mi
Registration #5	2011-07-01	144.309 mi
Registration #6	2013-05-20	151.277 mi
Registration #7	2015-05-20	151.277 mi
Registration #8	2017-05-20	151.277 mi
Registration #9	2018-05-20	151.277 mi
Registration #10	2019-12-28	151.277 mi

More info >



Car features

The VOLKSWAGEN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLKSWAGEN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	2066 mm
Height	1635 mm
Length	4391 mm
Wheel base	2677 mm
Max. allowed weight	2290 kg

Additional information

Fuel tank capacity	60 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	7

Engine number

BKD 218336