





report date: 2024-03-29

General information

Make	VAUXHALL
Model	MERIVA EXCLUSIV AC
Colour	Brown
Year of manufacture	2015
Top speed	115 mph
0 - 60 mph	11.9 seconds
Gearbox	6 speed automatic

Engine & fuel consumption

Power	118 BHP
Max. torque	200 Nm at 1.850 rpm
Engine capacity	1.364 сс
Cylinders	4
Fuel type	Petrol
Consumption city	29.7 mpg
Consumption extra urban	49.6 mpg
Consumption combined	39.8 mpg
CO2 emission	166 g/km
CO2 label	Н



CarCheck.co.uk page 1/10



MOT history

MOT expiry date	2024-08-31
MOT pass rate	75 %
MOT passed	6
Failed MOT tests	2
Total advice items	5
Total items failed	9

MOT #8	2023-09-01 12:51
MOT test number	873110779537
Result	✓ Passed
Next expiry date	2024-08-31
Minor Nearside Front Battery insecure but not likely to fall from carrier (4.13 (a) (i))	

MOT #7			2023-08-29 11:25
MOT test n	umber		909018674570
Result			X Failed
Fail Rea	ar fog lamp tell-ta	ale not working (4.9.1 (a) (ii))	
Fail Off	side Front Tyre h	as ply or cords exposed (5.2.3 (d) (ii))	
Pass with	n rectification	Front Headlamp aim too low and too far to the right. Bo	OTH SIDES (4.1.2 (a))
Fail Nearside Rear Tyre has a tear, caused by separation or partial failure of its structure (5.2.3 (d) (ii))			
Fail Rear Rear fog lamp not working (4.5.1 (a) (ii))			
Pass with	n rectification	Nearside Front Side repeater not working (4.4.1 (a) (ii))
Advice	Advice Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))		
Minor Nearside Front Battery insecure but not likely to fall from carrier (4.13 (a) (i))			
Fail Offside Rear Tyre has a tear, caused by separation or partial failure of its structure (5.2.3 (d) (ii))			
Fail Off	side Front Winds	creen washer provides insufficient washer liquid (3.5 (a))

CarCheck.co.uk page 2/10



MOT #6 2022-08-30 14:51

MOT test number 731687671725

MOT #5 2020-07-20 11:54

MOT test number 234463440178

Result ✓ Passed

MOT #4 2019-06-24 12:19

MOT test number 103969031622

Result
✓ Passed

Advice Nearside Rear Rear disc discoloured

MOT #3 2018-07-06 14:22

MOT test number 750565943622

Result ✓ Passed

MOT #2 2018-07-06 11:50

MOT test number 166571879215

Result X Failed

Fail Horn not working (7.7 (a) (ii))

MOT #1 2018-01-10 15:07

MOT test number 556704587973

Advice Offside Obligatory mirror damaged, but not seriously affecting the rear view (8.1.2a)

CarCheck.co.uk page 3/10



Tax & MOT check



Tax status	Valid until 1 February
Days left	277
MOT expiry date	31 August 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	Н
Single payment (12 months)	£ 290,00,-
Single six month payment	£ 159,50,-
Total payable by 12 monthly instalments	£ 304,50,-

CarCheck.co.uk page 4/10



HX15VVW

report date: 2024-03-29

Damage history

Check the damage history for this VAUXHALL. See if, where and when this VAUXHALL had damage and the car repair costs. We also check if this VAUXHALL was scrapped. Download the premium report <u>here</u> for the results.

Damage 1

Date
Category
Type
Damage 2
Date
Category



Extra VAUXHALL salvage check



Type

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 5/10



Vehicle valuation

What is this car worth? See the vehicle value of this VAUXHALL in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 6/10



HX15VVW

report date: 2024-03-29

Owner history

e union motory	
For how long did the current and previous owner(s) have this VAUXHALL? How many own VAUXHALL have? Check it in the premium report and see all owner registrations. Downloner.	

	More info >
Plate changes	
See in this check if this VAUXHALL had different number plates.	
Number of plates	,
Current registration	UK UK
Plate since	
Current registration	UK SIP
Plate since	
	More info >

CarCheck.co.uk page 7/10



Finance check

Check if this VAUXHALL is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VAUXHALL has been settled.

If not, and you buy this VAUXHALL then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this VAUXHALL is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	

Contact info

More info >

CarCheck.co.uk page 8/10



Mileage check

Odometer	In miles
Mileage registrations	9
First mileage registration	2015-03-19
Last registration	2023-09-01
Complete history	See info



Registration #1	2015-03-19	19 mi
Registration #2	2018-01-10	14.442 mi
Registration #3	2018-07-06	15.280 mi
Registration #4	2018-07-06	15.280 mi
Registration #5	2019-06-24	26.596 mi
Registration #6		11.777 es
Registration #7		11.777 es
Registration #8		11.777 es
Registration #9		D.777 es

More info >

CarCheck.co.uk page 9/10



Safety ratings

NCAP rating	****
Adult	89%
Children	77%
Pedestrian	55%
Safety systems	86%
Overall rating	80%
Video	see crash video



Dimensions & weight

Width	1994 mm
Height	1615 mm
Length	4300 mm
Wheel base	2644 mm
Kerb weight	1486 kg
Max. allowed weight	1995 kg

Additional information

Fuel tank capacity	54 I
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5
Number of axles	2
Engine number	B14NEL -19KB8375LUH

CarCheck.co.uk page 10/10