





General information

| Make | HYUNDAI |
|---------------------|----------------|
| Model | IX35 GDI SE |
| Colour | White |
| Year of manufacture | 2015 |
| Top speed | 111 mph |
| 0 - 60 mph | 11.1 seconds |
| Gearbox | 6 speed Manual |

Engine & fuel consumption

| Power | 133 BHP |
|-------------------------|---------------------|
| Max. torque | 165 Nm at 4.850 rpm |
| Engine capacity | 1.591 cc |
| Cylinders | 4 |
| Fuel type | Petrol |
| Consumption city | 34.5 mpg |
| Consumption extra urban | 47.1 mpg |
| Consumption combined | 41.5 mpg |
| CO2 emission | 158 g/km |
| CO2 label | G |







Internet history

Entry 1

Date Pictures 2021-08-15

Listing price

View report

12



source: cargurus.co.uk



MOT history

| MOT expiry date | 2024-05-29 |
|--------------------|------------|
| MOT pass rate | 75 % |
| MOT passed | 6 |
| Failed MOT tests | 2 |
| Total advice items | 8 |
| Total items failed | 4 |

| MOT #8 | 2023-05-30 14:53 | |
|---|------------------|--|
| MOT test number | 351100493310 | |
| Result | Passed | |
| Next expiry date 2024-05-2 | | |
| Minor Offside Rear Brake hose slightly damaged (1.1.12 (b) (i)) | | |
| Advice Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii)) | | |

| MOT #7 | 2022-08-11 11:36 |
|-----------------|------------------|
| MOT test number | 107082505004 |
| Result | ✓ Passed |
| | |

| MOT #6 | 2021-08-19 11:01 |
|-----------------|------------------|
| MOT test number | 769672231384 |
| Result | ✓ Passed |

| MOT #5 | 2021-08-18 14:49 |
|---|------------------|
| MOT test number | 950761044158 |
| Result | 🗙 Failed |
| Fail Offside Rear Position lamp missing (4.2.1 (a) (ii)) | |
| Fail Offside Rear Direction indicator missing (4.4.1 (a) (ii)) | |
| Fail Offside Stop lamp(s) missing (4.3.1 (a) (ii)) | |





| MOT #4 | 2020-08-19 10:12 |
|-----------------|------------------|
| MOT test number | 519959538518 |
| Result | ✓ Passed |
| | |
| МОТ #3 | 2019-05-17 15:45 |
| MOT test number | 909941450241 |
| | |

| MOT #2 2 | 019-05-16 14:41 |
|---|-----------------|
| MOT test number | 415057095363 |
| Result | 🗙 Failed |
| Fail Rear Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii)) | |
| Minor Offside Front Tyre obviously under inflated (5.2.3 (h) (i)) | |
| Advice Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii)) | |

| MOT #1 | | 2018-05-25 09:16 |
|----------|--|------------------|
| MOT test | number | 335130550458 |
| Result | | ✓ Passed |
| Advice | Items removed from driver's view prior to test | |
| Advice | Offside Rear light lens damaged but not affecting function | |
| Advice | Rear Brake pad(s) wearing thin (1.1.13 (a) (ii)) | |
| Advice | Engine bay covers, under trays, and or heat shields, fitted obscuring some compo | onents |



Tax & MOT check

| Tax due: 1 August 2024 | ✓ Taxed | Expires: 29 May 2024 | ✓ мот |
|----------------------------------|------------|--------------------------------|------------------------|
| Tax status | | | Valid until 1 August |
| Days left | | | 93 |
| MOT expiry date | | | 29 May 2024 |
| Full MOT history | | | <u>See MOT history</u> |
| Tax calculation | | | |

| Vehicle class | 48 |
|---|------------|
| Band | G |
| Single payment (12 months) | £ 240,00,- |
| Single six month payment | £ 132,00,- |
| Total payable by 12 monthly instalments | £ 252,00,- |





Damage history

Check the damage history for this HYUNDAI. See if, where and when this HYUNDAI had damage and the car repair costs. We also check if this HYUNDAI was scrapped. Download the premium report <u>here</u> for the results.

| Damage 1 | |
|----------|------|
| Date | |
| Category | Lamp |
| Туре | |
| Damage 2 | AMPL |
| Date | |
| Date | OLE |
| Category | E.S. |
| Туре | |

Extra HYUNDAI salvage check

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.





Vehicle valuation

What is this car worth? See the vehicle value of this HYUNDAI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

| Trade retail value | 4 10.000 |
|-----------------------------|----------|
| Auction value | 4 10.000 |
| Average private trade value | 4 10.200 |





Owner history

For how long did the current and previous owner(s) have this HYUNDAI? How many owners did this HYUNDAI have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>.

| and the second se | |
|---|-------------|
| ********** | |
| ******** | |
| ****** | |
| ********** | |
| ******** | |
| | More info > |
| Plate changes | |
| See in this check if this HYUNDAI had different number plates. | |
| Number of sisters | |
| | |
| Carrent registration | |
| Carrent registration Plate since | |
| Carrent registration Fals since Carrent registration | 業 |





Finance check

Check if this HYUNDAI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this HYUNDAI has been settled.

If not, and you buy this HYUNDAI then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this HYUNDAI is financed.


| Finance company | |
|-------------------|--|
| Date of agreement | |
| Agreement type | |
| Agreement term | |
| Agreement number | |
| Contact info | |





Mileage check

| Odometer | In miles |
|----------------------------|------------|
| Mileage registrations | 10 |
| First mileage registration | 2015-04-30 |
| Last registration | 2023-05-30 |
| Complete history | See info |



| Registration #1 | 2015-04-30 | 7 mi |
|------------------|------------|------------|
| Registration #2 | 2018-05-25 | 33.942 mi |
| Registration #3 | 2019-05-16 | 40.454 mi |
| Registration #4 | 2019-05-17 | 40.454 mi |
| Registration #5 | 2020-08-19 | 42.848 mi |
| Registration #6 | | 11.777 est |
| Registration #7 | | 11.777 mi |
| Registration #8 | | 11.777 esi |
| Registration #9 | | 11.777 mi |
| Registration #10 | | |

More info >





Car features

| 50225 | Air conditioning |
|-------|------------------|
| 50295 | |
| 60482 | |
| 60501 | |
| 0566 | |
| 0567 | |
| 60569 | |

Safety ratings

| NCAP rating | **** |
|----------------|-----------------|
| Adult | 90% |
| Children | 88% |
| Pedestrian | 54% |
| Safety systems | 71% |
| Overall rating | 81% |
| Video | see crash video |



| Dimensions & weight | |
|-----------------------------------|-----------------------|
| Width | 1820 mm |
| Height | 1665 mm |
| Length | 4410 mm |
| Wheel base | 2640 mm |
| Kerb weight | 1427 kg |
| Max. allowed weight | 1830 kg |
| Additional information | |
| Fuel tank capacity | 58 I |
| Fuel delivery | Multi-Point Injection |
| Number of doors | 5 |
| Number of seats CarCheck.co.uk | 5 page 11/11 |

| Number of axles | 2 |
|-----------------|--------------|
| Engine number | G4FDFZ963022 |