





report date: 2024-03-28

General information

| Make | MINI |
|---------------------|--------------------|
| Model | CHALLENGE COOPER S |
| Colour | Grey |
| Year of manufacture | 2015 |
| Top speed | 146 mph |
| 0 - 60 mph | 6.8 seconds |
| Gearbox | 6 speed Manual |

Engine & fuel consumption

| Power | 192 BHP |
|-------------------------|---------------------|
| Max. torque | 280 Nm at 4.600 rpm |
| Engine capacity | 1.998 сс |
| Cylinders | 4 |
| Fuel type | Petrol |
| Consumption city | 36.7 mpg |
| Consumption extra urban | 55.4 mpg |
| Consumption combined | 47.1 mpg |
| CO2 emission | 136 g/km |
| CO2 label | Е |



CarCheck.co.uk page 1/11



report date: 2024-03-28

Internet history

Entry 1

Date 2021-08-14

Pictures 30

Listing price <u>View report</u>









source: cargurus.co.uk

CarCheck.co.uk page 2/11



report date: 2024-03-28

MOT history

| MOT expiry date | 2024-09-12 |
|--------------------|------------|
| MOT pass rate | 75 % |
| MOT passed | 6 |
| Failed MOT tests | 2 |
| Total advice items | 6 |
| Total items failed | 3 |

| MOT #8 | 2023-09-13 06:07 |
|---|------------------|
| MOT test number | 902135880534 |
| Result | ✓ Passed |
| Next expiry date | 2024-09-12 |
| Minor Nearside Front Windscreen wiper blade defective blade large seperation (3.4 (b) | (i)) |
| Advice Items removed from driver's view prior to test Device holder removed | |

| MOT #7 | 2023-09-07 07:00 |
|---|--------------------------|
| MOT test number | 815695898980 |
| Result | 🗙 Failed |
| Minor Nearside Front Windscreen wiper blade defective blade large seperation (3.4 | (b) (i)) |
| Advice Items removed from driver's view prior to test Device holder removed | |
| Fail Offside Front Outer Tyre has a bulge, caused by separation or partial failure of (ii)) | its structure (5.2.3 (d) |
| Fail Offside Front Inner Road wheel badly distorted (5.2.2 (c) (i)) | |
| Advice Front Tyre worn close to legal limit/worn on edge both front on edges (5.2.3 | (e)) |

| MOT #6 | 2022-08-12 05:22 |
|-----------------|------------------|
| MOT test number | 151508442523 |
| Result | ✓ Passed |

CarCheck.co.uk page 3/11



report date: 2024-03-28

| MOT #5 | 2021-08-16 13:49 |
|--|------------------|
| MOT test number | 665155734888 |
| Result | ✓ Passed |
| | |
| MOT #4 | 2020-09-08 07:34 |
| MOT test number | 823102022475 |
| Result | ✓ Passed |
| | |
| MOT #3 | 2020-09-07 13:46 |
| MOT test number | 279005944594 |
| Result | X Failed |
| Fail Nearside Front Inner Tyre has ply or cords exposed (5.2.3 (d) (ii)) | |
| Advice Offside Front Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e)) | |

| MOT #2 | 2019-08-16 11:06 |
|-----------------|------------------|
| MOT test number | 248413919816 |
| Result | √ Passed |
| | |
| MOT #1 | 2018-08-20 10:12 |
| MOT test number | 388300119612 |
| Result | ✓ Passed |

CarCheck.co.uk page 4/11



MOT

report date: 2024-03-28

Tax & MOT check



Tax status

Days left

MOT expiry date

Full MOT history

Valid until 1 October

155

See MOT history

Tax calculation

| Vehicle class | 48 |
|---|------------|
| Band | E |
| Single payment (12 months) | £ 180,00,- |
| Single six month payment | £ 99,00,- |
| Total payable by 12 monthly instalments | £ 189,00,- |

CarCheck.co.uk page 5/11



report date: 2024-03-28

Damage history

Check the damage history for this MINI. See if, where and when this MINI had damage and the car repair costs. We also check if this MINI was scrapped. Download the premium report <u>here</u> for the results.

| Damage 1 | |
|----------|--|
| Date | |
| Category | |
| Туре | |
| Damage 2 | |
| Date | |
| Category | |
| Туре | |



Extra MINI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 6/11



report date: 2024-03-28

Vehicle valuation

What is this car worth? See the vehicle value of this MINI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 7/11



report date: 2024-03-28

| Owner | biotom |
|---------|-----------|
| UWNEI | nisioiv |
| OVVIICI | THISCOL Y |

| o micr miscory | | |
|--|-----------|----|
| For how long did the current and previous owner(s) have this MINI? How many owners did Check it in the premium report and see all owner registrations. Download the full report by | | e? |
| ******** | | |
| | | |
| | | |
| | | |
| | | |
| ************************************** | | |
| | More info | > |
| Plate changes | | |
| See in this check if this MINI had different number plates. | | |
| Number of plates | | |
| Current registration | NK NA | |
| Plate since | | |
| Current registration | NK NA | |
| Plate since | | |
| | More info | > |
| | | |

CarCheck.co.uk page 8/11



report date: 2024-03-28

Finance check

Check if this MINI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MINI has been settled.

If not, and you buy this MINI then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this MINI is financed.

| Finance company | |
|-------------------|--|
| Date of agreement | |
| Agreement type | |
| Agreement term | |
| Agreement number | |
| Control info | |

Contact info

More info >

CarCheck.co.uk page 9/11



report date: 2024-03-28

Mileage check

| Odometer | In miles |
|----------------------------|------------|
| Mileage registrations | 10 |
| First mileage registration | 2015-09-01 |
| Last registration | 2023-09-13 |
| Complete history | See info |



| Registration #1 | 2015-09-01 | 9 mi |
|---------------------------------|------------|-------------------------------------|
| Registration #2 | 2018-08-20 | 17.430 mi |
| Registration #3 | 2019-08-16 | 24.596 mi |
| Registration #4 | 2020-09-07 | 32.682 mi |
| Registration #5 | 2020-09-08 | 32.682 mi |
| | | |
| Registration #6 | | 11.777 es |
| Registration #6 Registration #7 | | 11.777 ea |
| • | | 11.777 es 11.777 es |
| Registration #7 | | 11,777 es 11,777 es 11,777 es |

More info >

CarCheck.co.uk page 10/11



report date: 2024-03-28

Car features

| S0225 | Air conditioning |
|-------|------------------|
| S0295 | |
| 50482 | |
| 50501 | |
| 50566 | |
| 60567 | |
| 50569 | |

Safety ratings

| NCAP rating | **** |
|----------------|-----------------|
| Adult | 79% |
| Children | 73% |
| Pedestrian | 66% |
| Safety systems | 56% |
| Overall rating | 71% |
| Video | see crash video |



Dimensions & weight

| Width | 1932 mm |
|---------------------|---------|
| Height | 1414 mm |
| Length | 3850 mm |
| Wheel base | 2495 mm |
| Kerb weight | 1235 kg |
| Max. allowed weight | 1640 kg |

Additional information

| Fuel tank capacity | 44 | |
|-----------------------------------|------------------|------------|
| Fuel delivery | Direct Injection | |
| Number of doors | 3 | |
| Number of seats CarCheck.co.uk | 4 | page 11/11 |