





report date: 2024-03-29

#### General information

Make	LEXUS
Model	IS 300H EXECUTIVE EDITION
Colour	Silver
Year of manufacture	2016
Top speed	125 mph
0 - 60 mph	8.1 seconds
Gearbox	1 speed CVT

#### Engine & fuel consumption

Power	220 BHP
Max. torque	221 Nm at 4.200 rpm
Engine capacity	2.494 сс
Cylinders	4
Fuel type	Hybrid / Electric
Consumption city	61.4 mpg
Consumption extra urban	61.4 mpg
Consumption combined	64.2 mpg
CO2 emission	101 g/km
CO2 label	В



CarCheck.co.uk page 1/11



report date: 2024-03-29

#### Internet history


#### Entry 1

Date 2021-02-01


Pictures 10

Listing price <u>View report</u>









source: autoonline.co.uk

CarCheck.co.uk page 2/11



report date: 2024-03-29

## MOT history

MOT expiry date	2024-09-26
MOT pass rate	100 %
MOT passed	5
Failed MOT tests	0
Total advice items	8
Total items failed	0

MOT #5	2023-09-27 14:50
MOT test number	205818198196
Result	<b>✓</b> Passed
Next expiry date	2024-09-26
Minor Offside Front Track rod end ball joint dust cover damaged or deteriorating ingress of dirt (2.1.3 (g) (i))	ated, but preventing the
Minor Nearside Front Track rod end ball joint dust cover damaged or deteriorated, but preventing the ingress of dirt (2.1.3 (g) (i))	
Minor Offside Front Lower Steering linkage ball joint ball joint dust cover dar preventing the ingress of dirt (2.1.3 (g) (i))	maged or deteriorated, but

MOT #4	2022-10-06 09:20
MOT test number	313336959664
Result	<b>✓</b> Passed
MOT #3	2021-10-08 09:42
MOT test number	707993303434
Result	<b>✓</b> Passed

MOT #2	2020-11-02 16:42
MOT test number	681437868353
Result	<b>✓</b> Passed

CarCheck.co.uk page 3/11



report date: 2024-03-29

MOT #1 2019-09-27 13:52

**MOT test number** 711211592805

Result ✓ Passed **Advice** Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii)) Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e)) Advice Nearside Rear Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b)) Advice Advice Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii)) Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e)) **Advice** 

CarCheck.co.uk page 4/11



report date: 2024-03-29

#### Tax & MOT check





Expires: 26 September 2024

Tax status	Valid until 1 November
Days left	186
MOT expiry date	26 September 2024
Full MOT history	See MOT history

#### Tax calculation

Vehicle class	59
Band	В
Single payment (12 months)	£ 10,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 10,50,-

CarCheck.co.uk page 5/11



report date: 2024-03-29

#### Damage history

Check the damage history for this LEXUS. See if, where and when this LEXUS had damage and the car repair costs. We also check if this LEXUS was scrapped. Download the premium report <a href="here">here</a> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



#### Extra LEXUS salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 6/11



report date: 2024-03-29

#### Vehicle valuation

What is this car worth? See the vehicle value of this LEXUS in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

**Trade retail value** 

**Auction value** 

Average private trade value

More info >

CarCheck.co.uk page 7/11



report date: 2024-03-29

Owner	history
OWITEL	HISLULY

For how long did the current and previous owner(s) have this LEXUS? How many owners did this LEXUS have? Check it in the premium report and see all owner registrations. Download the full report here.  More info >  Plate changes  See in this check if this LEXUS had different number plates.		
See in this check if this LEXUS had different number plates.		
See in this check if this LEXUS had different number plates.		
See in this check if this LEXUS had different number plates.		
See in this check if this LEXUS had different number plates.		
See in this check if this LEXUS had different number plates.		
See in this check if this LEXUS had different number plates.	MARKET STATE OF THE STATE OF TH	
See in this check if this LEXUS had different number plates.		
See in this check if this LEXUS had different number plates.	***************************************	
See in this check if this LEXUS had different number plates.		More info >
器 UK	Plate changes	
器 UK	See in this check if this LEXUS had different number plates.	
器 UK	Number of plates	,
Plate since	Current registration	UK UK
Plate since	Plate since	
More info >	Current registration	UK UK
More info >	Plate since	
		More info >

CarCheck.co.uk page 8/11



report date: 2024-03-29

#### Finance check

Check if this LEXUS is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this LEXUS has been settled.

If not, and you buy this LEXUS then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this LEXUS is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

Contact info

More info >

CarCheck.co.uk page 9/11



report date: 2024-03-29

### Mileage check

Odometer	In miles
Mileage registrations	7
First mileage registration	2016-09-30
Last registration	2023-09-27
Complete history	See info



Registration #1	2016-09-30	19 mi
Registration #2	2019-09-27	27.309 mi
Registration #3	2020-11-02	28.983 mi
Registration #4		11.777 es
Registration #5		11.777 es
Registration #6		11.777 es
Registration #7		11.777 es

More info >

CarCheck.co.uk page 10/11



report date: 2024-03-29

### Car features

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
50567	
50569	

## Safety ratings

NCAP rating	****
Adult	91%
Children	85%
Pedestrian	80%
Safety systems	66%
Overall rating	85%
Video	see crash video



### Dimensions & weight

Width	1810 mm
Height	1430 mm
Length	4665 mm
Wheel base	2800 mm
Kerb weight	1720 kg
Max. allowed weight	2145 kg

### Additional information

Fuel tank capacity	66 I	
Fuel delivery	Direct Injection	
Number of doors	4	
Number of seats CarCheck.co.uk	5	page 11/11

Number of axles 2

Engine number 2AR1338001