





report date: 2024-03-28

General information

Make	TOYOTA
Model	RAV4 VVT-I XT3
Colour	Silver
Year of manufacture	2004
Top speed	112 mph
0 - 60 mph	10.6 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	147 BHP
Max. torque	192 Nm at 4.000 rpm
Engine capacity	1.998 сс
Cylinders	4
Fuel type	Petrol
Consumption city	24.8 mpg
Consumption extra urban	38.7 mpg
Consumption combined	32.1 mpg
CO2 emission	207 g/km
CO2 label	K



CarCheck.co.uk page 1/13



Internet history

Entry 1

Date 2021-05-24

Pictures 15

Listing price <u>View report</u>









source: autotrader.co.uk

CarCheck.co.uk page 2/13



MOT history

MOT expiry date	2022-03-29
MOT pass rate	89 %
MOT passed	16
Failed MOT tests	2
Total advice items	25
Total items failed	1

MOT #18		2021-03-30 14:34
MOT test	number	278451996748
Result		✓ Passed
Next exp	iry date	2022-03-29
Minor	Windscreen damaged but not adversely affecting driver's view in Zone	'A' under 10mm (3.2 (a) (i))
Advice (c))	Rear Lower Shock absorbers has a slightly worn bush Both rear shock	lower bushes worn (5.3.2
Minor	Front Windscreen wiper blade defective Both front wipers poor (3.4 (b)	(i))
Advice	Tyre slightly damaged/cracking or perishing Both front and O/S/R tyres	s are perished (5.2.3 (d) (ii))

MOT #17		2020-09-30 14:41
MOT test	number	988105112294
Result		✓ Passed
Advice polishing	Nearside Headlamp has a product on the lens but not seriously reduce $4.1.4$ (b))	cing light output recommend
Advice	Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice polishing	Offside Headlamp has a product on the lens but not seriously reducir 4.1.4 (b))	ng light output recommend

CarCheck.co.uk page 3/13



MOT #16 2020-09-25 10:51

MOT test number 736524340750

Result X Failed

Advice Nearside Headlamp has a product on the lens but not seriously reducing light output recommend polishing (4.1.4 (b))

MAJOR Nearside Front Shock absorbers has a serious fluid leak (5.3.2 (b))

Advice Offside Headlamp has a product on the lens but not seriously reducing light output recommend polishing (4.1.4 (b))

Advice Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #15 2019-10-02 09:17

MOT test number 610861332255

Result
✓ Passed

Advice Offside Front Headlamp has a product on the lens but not seriously reducing light output deteriorated (4.1.4 (b))

Advice Nearside Front Headlamp has a product on the lens but not seriously reducing light output deteriorated (4.1.4 (b))

MOT #14 2018-10-02 11:09

MOT test number 420740094699

Result
✓ Passed

Advice Offside Front Brake pad(s) wearing thin (1.1.13 (a) (ii))

Advice Nearside Front Brake pad(s) wearing thin (1.1.13 (a) (ii))

MOT #13 2017-09-14 11:42

MOT test number 199411437951

Advice Windscreen has damage to an area less than a 10mm circle within zone 'A' (8.3.1a)

Advice Brake pipe slightly corroded rears (3.6.B.2c)

Advice Headlamp deteriorated but light output not reduced both (1.7.5a)

CarCheck.co.uk page 4/13



MJ04NWF

report date: 2024-03-28

MOT #12 2016-10-04 15:59

MOT test number 798475823023

Result ✓ Passed

Advice Windscreen has damage to an area less than a 10mm circle within zone 'A' (8.3.1a)

MOT #11 2015-09-24 11:47

MOT test number 726320453613

Result

Passed

Advice Nearside Brake pipe slightly corroded Front to Rear (3.6.B.2c)

Advice Offside Front Tyre worn close to the legal limit 235/60/16 100H (4.1.E.1)

Advice Offside Brake pipe slightly corroded Front to Rear (3.6.B.2c)

MOT #10 2014-10-03 12:09

MOT test number 165936374295

Result \(\sqrt{Passed} \)

MOT #9 2014-05-07 15:19

MOT test number 206767224480

Result
✓ Passed

MOT #8 2014-05-07 14:04

MOT test number 355337424161

Result X Failed

Fail Offside Rear coil spring broken (2.4.C.1a)

MOT #7 2013-04-06 10:33

MOT test number 437626393083

Result

Passed

CarCheck.co.uk page 5/13



 MOT #6
 2012-04-21 10:36

 MOT test number
 879122012158

Advice Offside Rear Tyre worn close to the legal limit (4.1.E.1)

Advice Nearside Rear Tyre worn close to the legal limit (4.1.E.1)

MOT #5

MOT test number

Result

Notice Advise rear tyres low

MOT #4 2010-04-23 14:17

MOT test number 744733010177

Result ✓ Passed

MOT #3 2009-04-18 08:48

MOT test number 880848109167

Result ✓ Passed

MOT #2

MOT test number

2008-04-18 12:08

231159208447

Result

✓ Passed

 MOT #1
 2007-04-20 11:45

 MOT test number
 563770817141

 Result
 ✓ Passed

CarCheck.co.uk page 6/13





Tax & MOT check



Tax expired:
1 September 2022

Х мот

Expired: 29 March 2022

Tax status	Expired at 1 September
Days left	605 days too late
MOT expiry date	29 March 2022
Full MOT history	See MOT history

Tax calculation

Waltisla slave	40
Vehicle class	48
Band	K
Single payment (12 months)	£ 395,00,-
Single six month payment	£ 217,25,-
Total payable by 12 monthly instalments	£ 414,75,-

CarCheck.co.uk page 7/13



Damage history

Check the damage history for this TOYOTA. See if, where and when this TOYOTA had damage and the car repair costs. We also check if this TOYOTA was scrapped. Download the premium report here for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra TOYOTA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 8/13



Vehicle valuation

What is this car worth? See the vehicle value of this TOYOTA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 9/13



Owner history

e when miscory	
For how long did the current and previous owner(s) have this TOYOTA? How many owner have? Check it in the premium report and see all owner registrations. Download the full respectively.	

	More info >
Plate changes See in this check if this TOYOTA had different number plates.	
See in this eneck is this 1919 in that amerene names places	
Number of plates	,
Current registration	UK UK
Plate since	
Current registration	UK UK
Plate since	
	More info >

CarCheck.co.uk page 10/13



Finance check

Check if this TOYOTA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this TOYOTA has been settled.

If not, and you buy this TOYOTA then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this TOYOTA is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

Contact info

More info >

CarCheck.co.uk page 11/13



Mileage check

Odometer	In miles
Mileage registrations	20
First mileage registration	2004-04-23
Last registration	2021-03-30
Complete history	See info



Registration #1	2004-04-23	6 mi
Registration #2	2007-04-20	15.489 mi
Registration #3	2008-04-18	19.793 mi
Registration #4	2009-04-18	24.396 mi
Registration #5	2010-04-23	27.905 mi
Registration #6	2011-04-20	31.507 mi
Registration #7	2012-04-21	35.198 mi
Registration #8	2013-04-06	37.882 mi
Registration #9	2014-05-07	41.094 mi
Registration #10	2014-05-07	41.094 mi
Registration #11		0.70 es
Registration #12		11.777 es
Registration #13		0.777 es
Registration #14		11.777 es
Registration #15		0.777 es
Registration #16		11.777 es
Registration #17		9.70 es
Registration #18		11.777 es
Registration #19		0.70 es
Registration #20		11.777 au

More info >

CarCheck.co.uk page 12/13



Car features

S0225	Air conditionin
S0295	
50482	
50501	
50566	
60567	
50569	

Safety ratings

NCAP rating	***
Video	see crash video



Dimensions & weight

Width	1735 mm
Height	1695 mm
Length	3805 mm
Wheel base	2280 mm
Kerb weight	1325 kg
Max. allowed weight	1685 kg

Additional information

· · · · · · · · · · · · · · · · · · ·	
Fuel tank capacity	57 I
Fuel delivery	Multi-Point Injection
Number of doors	3
Number of seats CarCheck.co.uk	5 page 13/13

Number of axles 2

Engine number 1AZ1491272