



DYIIORF

report date: 2024-03-29

General information

Make	MAZDA
Model	MX-5 I ROADSTER MIYAKO
Colour	Black
Year of manufacture	2011
Top speed	135 mph
0 - 60 mph	7.9 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	158 BHP
Max. torque	188 Nm at 5.000 rpm
Engine capacity	1.999 cc
Cylinders	4
Fuel type	Petrol
Consumption city	28.0 mpg
Consumption extra urban	48.7 mpg
Consumption combined	38.2 mpg
CO2 emission	177 g/km
CO2 label	I





Internet history

Entry 1

Date	2021-02-01
Pictures	1
Listing price	View report



source: [autoonline.co.uk](https://www.autoonline.co.uk)



MOT history

MOT expiry date	2024-05-03
MOT pass rate	92 %
MOT passed	11
Failed MOT tests	1
Total advice items	22
Total items failed	3

MOT #12	2023-05-04 18:04
MOT test number	619894627893
Result	✓ Passed
Next expiry date	2024-05-03

MOT #11	2022-03-11 16:31
MOT test number	952500827286
Result	✓ Passed

MOT #10	2021-02-19 16:54
MOT test number	773468331196
Result	✓ Passed

MOT #9	2020-08-26 10:26
MOT test number	152249981001
Result	✓ Passed

MOT #8	2019-08-30 13:16
MOT test number	392777097791
Result	✓ Passed

Advice Offside Rear Nail in tyre

**MOT #7**

2018-08-14 14:45

MOT test number

221321084658

Result

✓ Passed

- Advice** Front osf shocker dust cover warn
- Advice** Rear Anti-roll bar linkage ball joint has slight play both sides (5.3.4 (a) (i))
- Advice** Rear Suspension arm pin or bush worn but not resulting in excessive movement both side (5.3.4 (a) (i))
- Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

MOT #6

2018-08-10 14:46

MOT test number

952434290158

Result

✗ Failed

- Advice** Rear Anti-roll bar linkage ball joint has slight play both sides (5.3.4 (a) (i))
- Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Fail** Offside Rear Service brake excessively binding (1.2.1 (f))
- Fail** Offside Front Anti-roll bar linkage ball joint dust cover no longer prevents the ingress of dirt insecure (5.3.4 (b) (ii))
- Fail** Nearside Front Anti-roll bar linkage ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))
- Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened pitted on inner side (1.1.14 (a) (ii))
- Advice** Front osf shocker dust cover warn
- Advice** Nearside Rear Service brake binding but not excessively (1.2.1 (f))
- Advice** Rear Suspension arm pin or bush worn but not resulting in excessive movement both side (5.3.4 (a) (i))
- Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))

MOT #5

2018-02-15 16:51

MOT test number

367552599621

Result

✓ Passed

- Advice** Advise all tyre are lightly cracked on the inner and outer side walls

**MOT #4** 2017-02-15 11:02**MOT test number** 963177468968**Result** ✓ Passed**Advice** Nearside Rear Inner Tyre worn close to the legal limit (4.1.E.1)**Advice** All tyres have cracking**Advice** Front Brake pad(s) wearing thin (3.5.1g)**MOT #3** 2016-02-15 16:17**MOT test number** 807448654909**Result** ✓ Passed**Advice** Plastic sill covers and undertrays fitted**MOT #2** 2015-02-13 14:28**MOT test number** 157604345090**Result** ✓ Passed**Advice** Nearside Rear Anti-roll bar linkage has slight play in a ball joint (2.4.G.2)**Notice** Nail in offside rear tyre**MOT #1** 2014-02-20 12:33**MOT test number** 199221054074**Result** ✓ Passed**Advice** Nearside Rear Shock absorber has a light misting of oil (2.7.3)**Notice** O/s/r tyre has small cut on outer sidewall**Advice** Offside Rear Shock absorber has a light misting of oil (2.7.3)



Damage history

Check the damage history for this MAZDA. See if, where and when this MAZDA had damage and the car repair costs. We also check if this MAZDA was scrapped. Download the premium report [here](#) for the results.

Damage 1	
Date	
Category	
Type	
Damage 2	
Date	
Category	
Type	



Extra MAZDA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this MAZDA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,299
Auction value	£ 19,299
Average private trade value	£ 19,299

More info >



Owner history

For how long did the current and previous owner(s) have this MAZDA? How many owners did this MAZDA have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this MAZDA had different number plates.

Number of plates	1
Current registration	*****
Plate since	2019-09-29
Current registration	*****
Plate since	2019-09-29

More info >



Finance check

Check if this MAZDA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MAZDA has been settled.

If not, and you buy this MAZDA then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this MAZDA is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	14
First mileage registration	2011-06-30
Last registration	2023-05-04
Complete history	See info



Registration #1	2011-06-30	19 mi
Registration #2	2014-02-20	10.765 mi
Registration #3	2015-02-13	14.793 mi
Registration #4	2016-02-15	18.975 mi
Registration #5	2017-02-15	22.397 mi
Registration #6	2018-02-15	25.711 mi
Registration #7	2018-08-10	27.156 mi
Registration #8	2019-05-20	28.277 mi
Registration #9	2019-05-20	28.277 mi
Registration #10	2019-05-20	28.277 mi
Registration #11	2019-05-20	28.277 mi
Registration #12	2019-05-20	28.277 mi
Registration #13	2019-05-20	28.277 mi
Registration #14	2019-05-20	28.277 mi

More info >



Safety ratings

NCAP rating	★★★★☆
Video	see crash video



Dimensions & weight

Width	1720 mm
Height	1245 mm
Length	4020 mm
Wheel base	2330 mm
Kerb weight	1165 kg
Max. allowed weight	1375 kg

Additional information

Fuel tank capacity	50 l
Fuel delivery	Multi-Point Injection
Number of doors	2
Number of seats	2
Number of axles	2
Engine number	LF 11032835