




report date: 2024-03-29

General information

Make	FORD
Model	MONDEO TITANIUM TDCI
Colour	Grey
Year of manufacture	2010
Top speed	137 mph
0 - 60 mph	8.6 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	161 BHP
Max. torque	340 Nm at 2.000 rpm
Engine capacity	1.997 cc
Cylinders	4
Fuel type	Diesel
Consumption city	44.1 mpg
Consumption extra urban	61.4 mpg
Consumption combined	53.3 mpg
CO2 emission	139 g/km
CO2 label	E





Internet history

---

**Entry 1**

Date	2021-07-10
Pictures	0
Listing price	<a href="#">View report</a>

source: [cargurus.co.uk](http://cargurus.co.uk)



MOT history

<b>MOT expiry date</b>	2023-07-11
<b>MOT pass rate</b>	92 %
<b>MOT passed</b>	11
<b>Failed MOT tests</b>	1
<b>Total advice items</b>	17
<b>Total items failed</b>	2

<b>MOT #12</b>	2022-07-04 14:30
<b>MOT test number</b>	595139488284
<b>Result</b>	✓ Passed
<b>Next expiry date</b>	2023-07-11
<b>Advice</b>	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
<b>Advice</b>	Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

<b>MOT #11</b>	2021-07-12 13:54
<b>MOT test number</b>	795997357982
<b>Result</b>	✓ Passed

<b>MOT #10</b>	2020-02-03 12:30
<b>MOT test number</b>	280912452225
<b>Result</b>	✓ Passed
<b>Advice</b>	Brake pad(s) wearing thin both rear (1.1.13 (a) (ii))
<b>Advice</b>	Offside Front fog light lens damaged
<b>Advice</b>	Nearside Rear Child Seat fitted not allowing full inspection of adult belt
<b>Advice</b>	Brake disc worn, pitted or scored, but not seriously weakened both rear (1.1.14 (a) (ii))
<b>Advice</b>	Coil spring corroded both rear (5.3.1 (b) (i))
<b>Advice</b>	Offside Rear Child Seat fitted not allowing full inspection of adult belt



<b>MOT #9</b>	2019-02-13 16:19
<b>MOT test number</b>	109469711053
<b>Result</b>	✓ Passed
<b>Advice</b>	Offside Front Tyre has a cut but not deep enough to reach the ply or cords side wall (5.2.3 (d) (i))
<b>Advice</b>	Direction indicator slightly discoloured both rear (4.4.3 (a))
<b>Advice</b>	Nearside Rear Child Seat fitted not allowing full inspection of adult belt

<b>MOT #8</b>	2018-02-22 10:54
<b>MOT test number</b>	197946113546
<b>Result</b>	✓ Passed

<b>MOT #7</b>	2017-02-20 10:05
<b>MOT test number</b>	444718842011
<b>Result</b>	✓ Passed

<b>MOT #6</b>	2017-01-20 15:33
<b>MOT test number</b>	458618819129
<b>Result</b>	✓ Passed
<b>Advice</b>	Nearside Rear Trailing arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)

<b>MOT #5</b>	2017-01-19 11:39
<b>MOT test number</b>	122440040894
<b>Result</b>	✗ Failed
<b>Fail</b>	Offside Rear Trailing arm rubber bush deteriorated resulting in excessive movement (2.4.G.2)
<b>Fail</b>	Rear Direction indicator incorrect colour (1.4.A.2f)
<b>Advice</b>	Nearside Rear Trailing arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)



<b>MOT #4</b>	2015-12-30 12:52
<b>MOT test number</b>	746738295469
<b>Result</b>	✓ Passed
<b>Advice</b>	Engine light
<b>Advice</b>	Tyre worn close to the legal limit both rear (4.1.E.1)

<b>MOT #3</b>	2015-01-03 10:35
<b>MOT test number</b>	415913505047
<b>Result</b>	✓ Passed
<b>Advice</b>	Nearside Rear Tyre worn close to the legal limit (4.1.E.1)
<b>Advice</b>	Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)

<b>MOT #2</b>	2013-11-29 11:01
<b>MOT test number</b>	626993433311
<b>Result</b>	✓ Passed

<b>MOT #1</b>	2013-08-15 09:56
<b>MOT test number</b>	685567523225
<b>Result</b>	✓ Passed




Damage history

Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report [here](#) for the results.


Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra FORD salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



**Vehicle valuation**

What is this car worth? See the vehicle value of this FORD in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

<b>Trade retail value</b>	£ 19,999
<b>Auction value</b>	£ 19,999
<b>Average private trade value</b>	£ 19,999

**More info** >



Owner history

For how long did the current and previous owner(s) have this FORD? How many owners did this FORD have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Start	End

More info >

Plate changes

See in this check if this FORD had different number plates.

Number of plates	1
Current registration	YD60WUJ
Plate since	2024-03-29
Current registration	YD60WUJ
Plate since	2024-03-29

More info >



**Finance check**

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this FORD is financed.


<b>Finance company</b>	REDACTED
<b>Date of agreement</b>	REDACTED
<b>Agreement type</b>	REDACTED
<b>Agreement term</b>	REDACTED
<b>Agreement number</b>	REDACTED
<b>Contact info</b>	REDACTED

**More info** >



Mileage check

<b>Odometer</b>	In miles
<b>Mileage registrations</b>	14
<b>First mileage registration</b>	2010-09-17
<b>Last registration</b>	2022-07-04
<b>Complete history</b>	<a href="#">See info</a>



<b>Registration #1</b>	2010-09-17	23 mi
<b>Registration #2</b>	2013-08-15	62.879 mi
<b>Registration #3</b>	2013-11-29	67.639 mi
<b>Registration #4</b>	2015-01-03	81.452 mi
<b>Registration #5</b>	2015-12-30	96.745 mi
<b>Registration #6</b>	2017-01-19	106.652 mi
<b>Registration #7</b>	2017-01-20	106.659 mi
<b>Registration #8</b>	2019-05-01	111.277 mi
<b>Registration #9</b>	2019-05-01	111.277 mi
<b>Registration #10</b>	2019-05-01	111.277 mi
<b>Registration #11</b>	2019-05-01	111.277 mi
<b>Registration #12</b>	2019-05-01	111.277 mi
<b>Registration #13</b>	2019-05-01	111.277 mi
<b>Registration #14</b>	2019-05-01	111.277 mi

[More info >](#)



Car features

The FORD factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete FORD factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	2078 mm
Height	1500 mm
Length	4778 mm
Wheel base	2850 mm
Kerb weight	1587 kg
Max. allowed weight	2180 kg

Additional information

Fuel tank capacity	70 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5

**Number of axles**

2

**Engine number**

AU19126