



report date: 2024-03-29

General information

| | |
|---------------------|----------------|
| Make | VOLVO |
| Model | V50 D S V50 |
| Colour | Green |
| Year of manufacture | - |
| Top speed | 130 mph |
| 0 - 60 mph | 9.6 seconds |
| Gearbox | 6 speed Manual |

Engine & fuel consumption

| | |
|-------------------------|---------------------|
| Power | 136 BHP |
| Max. torque | 320 Nm at 2.000 rpm |
| Cylinders | 4 |
| Fuel type | Diesel |
| Consumption city | 37.2 mpg |
| Consumption extra urban | 61.4 mpg |
| Consumption combined | 49.6 mpg |



LABEL UNKNOWN



Internet history

Entry 1

| | |
|---------------|-----------------------------|
| Date | 2021-08-02 |
| Pictures | 23 |
| Listing price | View report |



source: autotrader.co.uk

**MOT history****MOT #16** 2021-11-08 12:13**MOT test number** 457125299895**Result** ✓ Passed**Next expiry date** 2022-11-07

Minor Nearside Front Track rod end ball joint dust cover damaged or deteriorated, but preventing the ingress of dirt (2.1.3 (g) (i))

Advice Offside Upper Engine mounting damaged but not to excess (6.1.8 (a) (i))

MOT #15 2020-10-13 18:01**MOT test number** 851889024429**Result** ✓ Passed**MOT #14** 2019-10-09 13:58**MOT test number** 993753410186**Result** ✓ Passed**MOT #13** 2018-10-18 16:26**MOT test number** 651664744894**Result** ✓ Passed

Advice Offside Front Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Nearside Front Outer Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #12 2017-10-06 15:53**MOT test number** 975664450055**Result** ✓ Passed

Advice Offside Rear Lower Anti-roll bar linkage has slight play in a ball joint (2.4.G.2)

MOT #11 2016-10-27 15:39**MOT test number** 386457249372**Result** ✓ Passed



| | |
|------------------------|------------------|
| MOT #10 | 2016-03-17 06:40 |
| MOT test number | 568888473555 |
| Result | ✓ Passed |
| MOT #9 | 2015-03-17 06:55 |
| MOT test number | 598866475091 |
| Result | ✓ Passed |
| MOT #8 | 2014-03-13 06:51 |
| MOT test number | 137702174093 |
| Result | ✓ Passed |
| MOT #7 | 2013-03-06 15:57 |
| MOT test number | 717215163067 |
| Result | ✓ Passed |
| MOT #6 | 2012-03-20 06:53 |
| MOT test number | 557500582074 |
| Result | ✓ Passed |
| MOT #5 | 2011-03-24 10:44 |
| MOT test number | 107533781461 |
| Result | ✓ Passed |
| MOT #4 | 2009-10-22 09:56 |
| MOT test number | 102445299282 |
| Result | ✓ Passed |
| MOT #3 | 2008-10-21 10:32 |
| MOT test number | 721625898259 |
| Result | ✓ Passed |



| | |
|-----------------|--|
| MOT #2 | 2007-10-29 10:12 |
| MOT test number | 273212507384 |
| Result | ✓ Passed |
| Advice | Nearside Rear Tyre worn close to the legal limit (4.1.E.1) |
| Advice | Offside Rear Tyre worn close to the legal limit (4.1.E.1) |

| | |
|-------------------------|--|
| MOT #1 | 2007-10-29 10:12 |
| MOT test number | 293352807364 |
| Result | ✗ Failed |
| Pass with rectification | Offside Front Headlamp aim too low (1.8) |
| Advice | Offside Rear Tyre worn close to the legal limit (4.1.E.1) |
| Pass with rectification | Nearside Front Headlamp aim too low (1.8) |
| Advice | Nearside Rear Tyre worn close to the legal limit (4.1.E.1) |



Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report [here](#) for the results.

Damage 1

| | |
|----------|--|
| Date | |
| Category | |
| Type | |

Damage 2

| | |
|----------|--|
| Date | |
| Category | |
| Type | |



Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

| | |
|-----------------------------|----------|
| Trade retail value | £ 19,999 |
| Auction value | £ 19,999 |
| Average private trade value | £ 19,999 |

More info >



Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners did this VOLVO have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

| | |
|-------|--------------|
| Owner | Registration |
| Owner | Registration |
| Owner | Registration |
| Owner | Registration |
| Owner | Registration |
| Owner | Registration |
| Owner | Registration |

More info >

Plate changes

See in this check if this VOLVO had different number plates.

| | |
|----------------------|------------|
| Number of plates | 1 |
| Current registration | |
| Plate since | 2024-03-29 |
| Current registration | |
| Plate since | 2024-03-29 |

More info >



Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLVO is financed.

| | | |
|-------------------|------------|------|
| Finance company | XXXXXXXXXX | XXXX |
| Date of agreement | XXXXXXXXXX | XXXX |
| Agreement type | XXXXXXXXXX | XXXX |
| Agreement term | XXXXXXXXXX | XXXX |
| Agreement number | XXXXXXXXXX | XXXX |
| Contact info | XXXXXXXXXX | XXXX |

More info >



Mileage check

| | |
|----------------------------|--------------------------|
| Odometer | In miles |
| Mileage registrations | 17 |
| First mileage registration | 2004-10-26 |
| Last registration | 2021-11-08 |
| Complete history | See info |



| | | |
|------------------|------------|------------|
| Registration #1 | 2004-10-26 | 17 mi |
| Registration #2 | 2007-10-29 | 64.690 mi |
| Registration #3 | 2008-10-21 | 70.102 mi |
| Registration #4 | 2009-10-22 | 75.719 mi |
| Registration #5 | 2011-03-24 | 86.068 mi |
| Registration #6 | 2012-03-20 | 93.171 mi |
| Registration #7 | 2013-03-06 | 99.282 mi |
| Registration #8 | 2014-03-13 | 105.014 mi |
| Registration #9 | 2015-03-17 | 110.379 mi |
| Registration #10 | 2016-03-20 | 115.744 mi |
| Registration #11 | 2017-03-20 | 121.109 mi |
| Registration #12 | 2018-03-20 | 126.474 mi |
| Registration #13 | 2019-03-20 | 131.839 mi |
| Registration #14 | 2020-03-20 | 137.204 mi |
| Registration #15 | 2021-03-20 | 142.569 mi |
| Registration #16 | 2022-03-20 | 147.934 mi |
| Registration #17 | 2023-03-20 | 153.299 mi |

More info >



Car features

The VOLVO factory car options list is only available in the premium report.

| | |
|-------|------------------|
| S0225 | Air conditioning |
| S0295 | |
| S0482 | |
| S0501 | |
| S0566 | |
| S0567 | |
| S0569 | |

View the complete VOLVO factory list for this vehicle [here](#).

More info >

Dimensions & weight

| | |
|---------------------|---------|
| Width | 1770 mm |
| Height | 1452 mm |
| Length | 4514 mm |
| Wheel base | 2640 mm |
| Kerb weight | 1456 kg |
| Max. allowed weight | 1960 kg |

Additional information

| | |
|--------------------|------------------|
| Fuel tank capacity | 55 l |
| Fuel delivery | Direct Injection |
| Number of doors | 5 |
| Number of seats | 5 |
| Number of axles | 2 |
| Engine number | 4023782 |