



MAIOMTJ

report date: 2024-03-29

General information

| | |
|---------------------|----------------|
| Make | FORD |
| Model | FIESTA ZETEC |
| Colour | Black |
| Year of manufacture | 2010 |
| Top speed | 104 mph |
| 0 - 60 mph | 13.3 seconds |
| Gearbox | 5 speed Manual |

Engine & fuel consumption

| | |
|-----------------|----------|
| Power | 81 BHP |
| Max. torque | 114 Nm |
| Engine capacity | 1.242 cc |
| Cylinders | 4 |
| Fuel type | Petrol |
| CO2 emission | 133 g/km |
| CO2 label | E |





Internet history

Entry 1

| | |
|---------------|-----------------------------|
| Date | 2021-01-30 |
| Pictures | 10 |
| Listing price | View report |



source: [autoonline.co.uk](#)



MOT history

| | |
|--------------------|------------|
| MOT expiry date | 2024-09-28 |
| MOT pass rate | 82 % |
| MOT passed | 9 |
| Failed MOT tests | 2 |
| Total advice items | 17 |
| Total items failed | 0 |

| | |
|------------------|---|
| MOT #11 | 2023-09-29 15:40 |
| MOT test number | 134670894745 |
| Result | ✓ Passed |
| Next expiry date | 2024-09-28 |
| Advice | Rear Service brake fluctuating, but not excessively (1.2.1 (e)) |
| Advice | Both front tyres showing heavy wear to the inner edges |
| Advice | Nearside Rear Tyre slightly damaged/cracking or perishing cracks around outer edge (5.2.3 (d) (ii)) |
| Advice | Front Brake disc worn, but not excessively both sides (1.1.14 (a) (i)) |
| Advice | Exhaust heat shield insecure (rear) |

| | |
|-----------------|---|
| MOT #10 | 2022-11-23 12:44 |
| MOT test number | 848266937696 |
| Result | ✓ Passed |
| Advice | Steering column universal joint as slight free play |

**MOT #9** 2022-11-23 09:26**MOT test number** 675141060916**Result** ✗ Failed**MAJOR** Offside Front Suspension arm ball joint excessively worn (5.3.4 (a) (i))**MAJOR** Offside Stop lamp(s) not working (4.3.1 (a) (ii))**Advice** Steering column universal joint as slight free play**MOT #8** 2021-11-24 16:02**MOT test number** 728806693797**Result** ✓ Passed**MOT #7** 2021-11-22 14:28**MOT test number** 717243845186**Result** ✗ Failed**MAJOR** Offside Front Coil spring fractured or broken (5.3.1 (b) (i))**MAJOR** Front Windscreen wiper does not clear the windscreen effectively both blades (3.4 (b) (ii))**MAJOR** Nearside Rear Direction indicator incorrect colour white in colour (4.4.3 (a))**MAJOR** Bonnet cannot be secured in the closed position (3.1 (b) (i))**MAJOR** Offside Rear Axle swivel pins and bushes swivel pin and/or bush excessively worn axle bush (5.1.2 (b) (i))**MAJOR** Offside Front Side repeater not working (4.4.1 (a) (ii))**MAJOR** Offside Rear Direction indicator incorrect colour white in colour (4.4.3 (a))**MAJOR** Nearside Rear Axle swivel pins and bushes swivel pin and/or bush excessively worn rear axle bush (5.1.2 (b) (i))**MOT #6** 2018-03-21 14:24**MOT test number** 235567655774**Result** ✓ Passed



| | |
|------------------------|------------------|
| MOT #5 | 2017-03-23 14:27 |
| MOT test number | 256261131164 |
| Result | ✓ Passed |
| MOT #4 | 2016-03-19 10:27 |
| MOT test number | 482227825934 |
| Result | ✓ Passed |
| MOT #3 | 2015-03-28 09:26 |
| MOT test number | 546777885092 |
| Result | ✓ Passed |
| MOT #2 | 2014-03-27 14:27 |
| MOT test number | 615606884031 |
| Result | ✓ Passed |
| MOT #1 | 2013-03-21 09:55 |
| MOT test number | 357650783077 |
| Result | ✓ Passed |



Tax & MOT check

✓
Taxed
Tax due:
1 February 2025

✓
MOT
Expires:
28 September 2024

| | |
|-------------------------|---------------------------------|
| Tax status | Valid until 1 February |
| Days left | 278 |
| MOT expiry date | 28 September 2024 |
| Full MOT history | See MOT history |

Tax calculation

| | |
|--|------------|
| Vehicle class | 48 |
| Band | E |
| Single payment (12 months) | £ 180,00,- |
| Single six month payment | £ 99,00,- |
| Total payable by 12 monthly instalments | £ 189,00,- |



Damage history

Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report [here](#) for the results.

Damage 1

| | |
|----------|--|
| Date | |
| Category | |
| Type | |

Damage 2

| | |
|----------|--|
| Date | |
| Category | |
| Type | |



Extra FORD salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this FORD in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

| | |
|-----------------------------|----------|
| Trade retail value | £ 10,000 |
| Auction value | £ 10,000 |
| Average private trade value | £ 10,000 |

More info >



Owner history

For how long did the current and previous owner(s) have this FORD? How many owners did this FORD have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

| | |
|-------|------------|
| Owner | Start date |
| Owner | Start date |
| Owner | Start date |
| Owner | Start date |
| Owner | Start date |
| Owner | Start date |
| Owner | Start date |

More info >

Plate changes

See in this check if this FORD had different number plates.

| | |
|----------------------|------------|
| Number of plates | 1 |
| Current registration | |
| Plate since | 2024-03-29 |
| Current registration | |
| Plate since | 2024-03-29 |

More info >



Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this FORD is financed.

| | | |
|-------------------|------------|------|
| Finance company | XXXXXXXXXX | XXXX |
| Date of agreement | XXXXXXXXXX | XXXX |
| Agreement type | XXXXXXXXXX | XXXX |
| Agreement term | XXXXXXXXXX | XXXX |
| Agreement number | XXXXXXXXXX | XXXX |
| Contact info | XXXXXXXXXX | XXXX |

More info >



Mileage check

| | |
|----------------------------|--------------------------|
| Odometer | In miles |
| Mileage registrations | 13 |
| First mileage registration | 2010-03-28 |
| Last registration | 2023-09-29 |
| Complete history | See info |



| | | |
|------------------|------------|------------|
| Registration #1 | 2010-03-28 | 14 mi |
| Registration #2 | 2013-03-21 | 24.209 mi |
| Registration #3 | 2014-03-27 | 31.407 mi |
| Registration #4 | 2015-03-28 | 38.470 mi |
| Registration #5 | 2016-03-19 | 46.216 mi |
| Registration #6 | 2017-03-23 | 55.288 mi |
| Registration #7 | 2018-03-21 | 62.699 mi |
| Registration #8 | 2019-03-20 | 70.277 mi |
| Registration #9 | 2020-03-20 | 78.277 mi |
| Registration #10 | 2021-03-20 | 86.277 mi |
| Registration #11 | 2022-03-20 | 94.277 mi |
| Registration #12 | 2023-03-20 | 102.277 mi |
| Registration #13 | 2023-09-29 | 110.277 mi |

More info >



Car features

The FORD factory car options list is only available in the premium report.

| | |
|-------|------------------|
| S0225 | Air conditioning |
| S0295 | |
| S0482 | |
| S0501 | |
| S0566 | |
| S0567 | |
| S0569 | |

View the complete FORD factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating



Video

[see crash video](#)



Dimensions & weight

| | |
|---------------------|---------|
| Width | 1722 mm |
| Height | 1433 mm |
| Length | 3950 mm |
| Wheel base | 2489 mm |
| Kerb weight | 1109 kg |
| Max. allowed weight | 1495 kg |

Additional information

| | |
|--------------------|-----------------------|
| Fuel tank capacity | 42 l |
| Fuel delivery | Multi-Point Injection |
| Number of doors | 5 |
| Number of seats | 5 |

Engine number

9E46444