





report date: 2024-03-28

General information

Make	TOYOTA
Model	LAND CRUISER D-4D LC4 8 SEATS
Colour	Black
Year of manufacture	2004
Top speed	106 mph
0 - 60 mph	12.8 seconds
Gearbox	4 speed automatic

Engine & fuel consumption

Power	161 BHP
Max. torque	343 Nm at 1.600 rpm
Engine capacity	2.982 cc
Cylinders	4
Fuel type	Diesel
Consumption city	21.6 mpg
Consumption extra urban	32.5 mpg
Consumption combined	27.2 mpg
CO2 emission	277 g/km
CO2 label	М



CarCheck.co.uk page 1/12



report date: 2024-03-28

Internet history

Entry 1

Date 2022-06-10

Pictures 50

Listing price <u>View report</u>









source: cargurus.co.uk

CarCheck.co.uk page 2/12



AKO4GAR report date: 2024-03-28

MOT history

MOT expiry date	2024-06-29
MOT pass rate	85 %
MOT passed	17
Failed MOT tests	3
Total advice items	13
Total items failed	3

MOT #20	2023-06-16 10:45
MOT test number	750663951576
Result	✓ Passed
Next expiry date	2024-06-29

MOT #19	2022-06-30 09:54
MOT test number	421114218671
Result	✓ Passed

MOT #18	2021-09-03 09:14
MOT test number	488972724630
Result	✓ Passed
Minor Offside Headlamp lens slightly defective (4.1.1 (b) (i))	
Advice Nearside Rear Shock absorbers has light misting of oil (5.3.2 (b))	
Minor Nearside Headlamp lens slightly defective (4.1.1 (b) (i))	

MOT #17	2020-07-01 15:09
MOT test number	802757184480
Result	✓ Passed
Advice Rear Registration plate deteriorated but not likely to be misread (0.1 (b))	

CarCheck.co.uk page 3/12



Result

AK04GAR

report date: 2024-03-28

✓ Passed

MOT #16	2020-07-01 08:56
MOT test	number 533528349125
Result	★ Failed
Minor	Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))
Minor	Offside Headlamp lens slightly defective (4.1.1 (b) (i))
Advice	Rear Registration plate deteriorated but not likely to be misread (0.1 (b))
Minor	Nearside Headlamp lens slightly defective (4.1.1 (b) (i))
MAJOR (5.3.4 (b)	Nearside Front Anti-roll bar ball joint dust cover no longer prevents the ingress of dirt drop link (ii))

MOT #15	2019-07-02 11:34
MOT test number	722534495290
Result	✓ Passed
MOT #14	2018-06-25 09:53
MOT test number	733820833393
Result	✓ Passed
MOT #13	2017-07-21 14:49
MOT test number	483223561909
Result	✓ Passed
MOT #12	2016-06-27 11:45
MOT test number	374570655244

MOT #11	2015-06-26 09:49
MOT test number	949347375195
Result	✓ Passed
Advice Offside Front Tyre worn close to the legal limit (4.1.E.1)	

CarCheck.co.uk page 4/12



report date: 2024-03-28

MOT #10 2014-06-25 11:30

MOT test number 935516274149

Result ✓ Passed

MOT #9 2014-06-25 11:30

MOT test number 979546774165

Result X Failed

Pass with rectification Front Windscreen wiper does not clear the windscreen effectively (8.2.2)

Pass with rectification Nearside Front Front position lamp(s) not working (1.1.A.3b)

MOT #8 2013-06-25 08:49

MOT test number 487596273157

Result \(\sqrt{Passed} \)

MOT #7 2012-06-26 14:12

MOT test number 477898472192

MOT #6 2012-02-18 13:09

MOT test number 118519642027

Result

Passed

Advice Front Brake pad(s) wearing thin (3.5.1g)

Advice Parking brake: parking brake efficiency only just met. It would appear that the braking system

requires adjustment or repair. (3.7.C.1b)

MOT #5 2011-02-21 11:46

MOT test number 857822551029

Notice Nearside rear tyre outer edge cracked

CarCheck.co.uk page 5/12



report date: 2024-03-28

MOT #4	2010-02-25 12:16
MOT test number	770476650086
Result	≍ Failed
Pass with rectification	Front Windscreen wiper does not clear the windscreen effectively (8.2.2)

Pass with rectification	Front Windscreen wiper does not clear the windscreen effectively (8.2.2)
MOT #3	2010-02-25 12:16
MOT test number	674306750011
Result	✓ Passed
MOT #2	2008-11-19 13:23
MOT test number	534894528376
Result	✓ Passed
MOT #1	2007-11-21 11:27
MOT test number	650895927302
Result	✓ Passed

CarCheck.co.uk page 6/12



report date: 2024-03-28

Damage history

Check the damage history for this TOYOTA. See if, where and when this TOYOTA had damage and the car repair costs. We also check if this TOYOTA was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	
Category	
Туре	
Damage 2	
Date	
Category	
Type	



Extra TOYOTA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 7/12



AKO4GAR report date: 2024-03-28

Vehicle valuation

What is this car worth? See the vehicle value of this TOYOTA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 8/12



Plate since

AK04GAR

report date: 2024-03-28

Owner history			
For how long did the current and previous owner(s) have this TOYOTA? How many owner have? Check it in the premium report and see all owner registrations. Download the full r		OTA	

	More info	>	
Plate changes			
See in this check if this TOYOTA had different number plates.			
Number of plates			
Europeat registration		***	7

More info >

EXCLUSION

CarCheck.co.uk page 9/12



report date: 2024-03-28

Finance check

Check if this TOYOTA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this TOYOTA has been settled.

If not, and you buy this TOYOTA then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this TOYOTA is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

Contact into

More info >

CarCheck.co.uk page 10/12



report date: 2024-03-28

Mileage check

Odometer	In miles
Mileage registrations	20
First mileage registration	2004-09-20
Last registration	2023-06-16
Complete history	See info



Registration #1	2004-09-20	14 mi
Registration #2	2007-11-21	8.988 mi
Registration #3	2008-11-19	10.947 mi
Registration #4	2010-02-25	16.749 mi
Registration #5	2011-02-21	21.611 mi
Registration #6	2012-02-18	28.392 mi
Registration #7	2012-06-26	30.470 mi
Registration #8	2013-06-25	4.874 mi
Registration #9	2014-06-25	14.518 mi
Registration #10	2015-06-26	21.691 mi
Registration #11		9.79 es
Registration #12		11.777 es
Registration #13		9.79 es
Registration #14		11.777 es
Registration #15		9.79 es
Registration #16		11.777 es
Registration #17		91,709 esi
Registration #18		11.777 es
Registration #19		11.777 es
Registration #20		11.777 au

More info >

CarCheck.co.uk page 11/12



AKO4GAR report date: 2024-03-28

Car features

S0225	Air conditioning
S0295	
50482	
50501	
50566	
50567	
50569	

Dimensions & weight

Width	1875 mm
Height	1905 mm
Length	4850 mm
Wheel base	2790 mm
Kerb weight	1990 kg

Additional information

Fuel tank capacity	87 I
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	8
Engine number	1KD1121289

CarCheck.co.uk page 12/12