





report date: 2024-03-29

### General information

Make	VOLKSWAGEN
Model	PASSAT R LINE TDI
Colour	Blue
Year of manufacture	2010
Top speed	119 mph
0 - 60 mph	9.8 seconds
Gearbox	5 speed Manual

### Engine & fuel consumption

Power	110 BHP
Max. torque	250 Nm at 1.500 rpm
Engine capacity	1.968 cc
Cylinders	4
Fuel type	Diesel
Consumption city	40.4 mpg
Consumption extra urban	62.8 mpg
Consumption combined	51.4 mpg
CO2 emission	143 g/km
CO2 label	F



CarCheck.co.uk page 1/13



# Internet history

#### Entry 1

Date	2021-10-13	
Pictures	1	
Listing price	<u>View report</u>	



source: autotrader.co.uk

CarCheck.co.uk page 2/13



MOT history

MOT expiry date	2024-10-23
MOT pass rate	75 %
MOT passed	12
Failed MOT tests	4
Total advice items	21
Total items failed	8

MOT #16		2023-10-24 10:06
MOT test	number	122959165433
Result		✓ Passed
Next exp	iry date	2024-10-23
Minor (b) (i))	Nearside Registration plate lamp inoperative in the case of multiple lamp	os or light sources (4.7.1
Advice (i))	Offside Rear Suspension arm pin or bush worn but not resulting in exces	ssive movement (5.3.4 (a)
<b>Advice</b> bone back	Offside Front Suspension arm pin or bush worn but not resulting in excest bush (5.3.4 (a) (i))	ssive movement wish
Advice (a) (i))	Nearside Rear Suspension arm pin or bush worn but not resulting in exco	essive movement (5.3.4
<b>Advice</b> bone back	Nearside Front Suspension arm pin or bush worn but not resulting in exc bush (5.3.4 (a) (i))	cessive movement wish

MOT #15		2022-10-20 11:53
MOT test	number	167273092537
Result		<b>✓</b> Passed
Advice	Offside Rear Tyre worn close to legal limit/worn on edge inner edge (5.2.3 (e))	
Advice	Advice Nearside Rear Child Seat fitted not allowing full inspection of adult belt	
Minor Nearside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))		
Advice Nearside Rear Tyre worn close to legal limit/worn on edge inner edge (5.2.3 (e))		2))
Advice	Offside Rear Child Seat fitted not allowing full inspection of adult belt	

CarCheck.co.uk page 3/13



MOT #14 2021-10-22 08:36

**MOT test number** 861590483983

**Result** ✓ Passed

**MOT #13** 2021-10-22 08:36

MOT test number 297132486817

Result × Failed

Pass with rectification Offside Front Headlamp not working on dipped beam (4.1.1 (a) (ii))

**Pass with rectification** Nearside Front Headlamp aim too high (4.1.2 (a))

MOT #12 2021-01-09 11:55

**MOT test number** 635430262933

Result \rightarrow Passed

Advice Nearside Rear Child Seat fitted not allowing full inspection of adult belt

**MOT #11** 2021-01-08 12:33

MOT test number 818745168259

Result × Failed

Fail Nearside Front Coil spring fractured or broken (5.3.1 (b) (i))

Advice Front Brake disc worn, pitted or scored, but not seriously weakened both (1.1.14 (a) (ii))

Fail Rear Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))

Advice Nearside Rear Child Seat fitted not allowing full inspection of adult belt

Fail Nearside Front Service brake excessively binding (1.2.1 (f))

Advice Rear Brake disc worn, pitted or scored, but not seriously weakened both (1.1.14 (a) (ii))

CarCheck.co.uk page 4/13



MOT #10

MOT test number

Result

Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Nearside Rear Nail in tyre in the outer shoulder.

MOT #9		2019-01-11 08:53
MOT test	number	288812621204
Result		✓ Passed
Advice	Nearside Front Child Seat fitted not allowing full inspection of adult belt	
Advice	Offside Rear Child Seat fitted not allowing full inspection of adult belt	
Advice	Nearside Rear Child Seat fitted not allowing full inspection of adult belt	
Advice	Nearside Front Service brake binding but not excessively (1.2.1 (f))	
Minor	Tyre pressure monitoring system warning lamp indicates a fault (5.2.3 (h) (i))	

MOT #8	2018-01-11 10:05
MOT test number	679996062756
Result	✓ Passed
MOT #7	2017-01-12 10:43
MOT test number	695013814696
Result	✓ Passed
MOT #6	2017-01-12 10:00
MOT test number	650478771180
Result	<b>×</b> Failed
Fail Offside Side repeater not working (1.4.A.2c)	

CarCheck.co.uk page 5/13



SB59JOA

report date: 2024-03-29

MOT #5	2015-12-22 10:21
MOT test number	160920070889
Result	✓ Passed
MOT #4	2014-12-22 10:55
MOT test number	838746554389
Result	✓ Passed
MOT #3	2014-12-22 10:55
MOT test number	659086354352
Result	<b>★</b> Failed
Pass with rectification	Nearside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)
Pass with rectification	Offside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)

MOT #2	2013-12-30 09:38
MOT test number	667794663369
Result	<b>√</b> Passed
MOT #1	2012-12-28 10:11
MOT test number	458623462437
Result	✓ Passed

CarCheck.co.uk page 6/13



# Tax & MOT check



Tax status	Valid until 1 April
Days left	336
MOT expiry date	23 October 2024
Full MOT history	See MOT history

# Tax calculation

Vehicle class	49
Band	F
Single payment (12 months)	£ 200,00,-
Single six month payment	£ 110,00,-
Total payable by 12 monthly instalments	£ 210,00,-

CarCheck.co.uk page 7/13



SB59JOA


report date: 2024-03-29

### Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report <a href="here">here</a> for the results.

#### Damage 1

Date	
Category	
Туре	
Damage 2	
Date	
Category	



#### Extra VOLKSWAGEN salvage check



**Type** 

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 8/13



### Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

**Trade retail value** 

**Auction value** 

Average private trade value

More info >

CarCheck.co.uk page 9/13



SB59JOA

report date: 2024-03-29

Owner history	
For how long did the current and previous owner(s) have this VOLKSWAGEN? How many VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Downere.	
HARMAN AND AND AND AND AND AND AND AND AND A	
*************	
*********	
***************************************	
**************************************	
Plate changes	More info >
See in this check if this VOLKSWAGEN had different number plates.	
Number of plates	
Current registration	NK NK
Plate since	
Current registration	UK UK
Plate since	
	More info >

CarCheck.co.uk page 10/13



### Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this VOLKSWAGEN is financed.

Finance company

Date of agreement

Agreement type

Agreement term

Agreement number

**Contact info** 

More info >

CarCheck.co.uk page 11/13



# Mileage check

Odometer	In miles
Mileage registrations	17
First mileage registration	2010-01-13
Last registration	2023-10-24
Complete history	See info



Registration #1	2010-01-13	9 mi
Registration #2	2012-12-28	18.716 mi
Registration #3	2013-12-30	25.117 mi
Registration #4	2014-12-22	31.002 mi
Registration #5	2015-12-22	36.885 mi
Registration #6	2017-01-12	43.518 mi
Registration #7	2017-01-12	43.518 mi
Registration #8	2018-01-11	52.231 mi
Registration #9	2019-01-11	59.267 mi
Registration #10		77,777 46
Registration #11		71.777 66
Registration #12		
Registration #13		71.777 66
Registration #13 Registration #14		11.07 m
		71.777 est 71.777 est 71.777 est
Registration #14		11.777 mi 11.777 mi 11.777 mi

More info >

CarCheck.co.uk page 12/13



### Car features

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

# Safety ratings

NCAP rating	****
Video	see crash video



# Dimensions & weight

Width	1820 mm
Height	1472 mm
Length	4765 mm
Wheel base	2709 mm
Kerb weight	1435 kg
Max. allowed weight	2080 kg

# Additional information

Fuel tank capacity	70 I
Fuel delivery	Direct Injection
Number of doors	4
CarChack so uk	nago 12/12

CarCheck.co.uk page 13/13

Number of seats	5
Number of axles	2
Engine number	CBD 371263