



report date: 2024-03-28

General information

Make	CITROEN
Model	XSARA 16V SX
Colour	Red
Year of manufacture	-
Top speed	118 mph
0 - 60 mph	11.5 seconds
Gearbox	4 speed automatic

Engine & fuel consumption

Power	110 BHP
Max. torque	147 Nm at 4.000 rpm
Cylinders	4
Fuel type	Petrol
Consumption city	28.0 mpg
Consumption extra urban	51.4 mpg
Consumption combined	39.2 mpg



LABEL UNKNOWN



Internet history

Entry 1

Date	2021-09-03
Pictures	7
Listing price	View report



source: autotrader.co.uk



MOT history

MOT #21 2020-08-13 10:53**MOT test number** 852575691943**Result** ✓ Passed**Next expiry date** 2021-09-03**Advice** Nearside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))**Minor** Nearside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))**MOT #20** 2019-08-16 10:21**MOT test number** 892123918423**Result** ✓ Passed**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #19** 2019-08-16 09:57**MOT test number** 206458052510**Result** ✗ Failed**Fail** Engine MIL inoperative or indicates a malfunction (8.2.1.2 (h))**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #18** 2018-09-04 10:38**MOT test number** 784970539561**Result** ✓ Passed**MOT #17** 2018-09-04 10:38**MOT test number** 510626950350**Result** ✗ Failed**Pass with rectification** Offside Front Position lamp not working (4.2.1 (a))

**MOT #16**

2017-08-09 09:40

MOT test number

116063293144

Result

✓ Passed

- Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)
- Advice** Passenger seat(s) missing at time of test all rear
- Advice** Vehicle structure has slight corrosion both front outer sills (6.1.B.2)
- Advice** Oil leak
- Advice** Spare tyre defective

MOT #15

2017-08-08 09:51

MOT test number

951572938836

Result

✗ Failed

- Advice** Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
- Fail** Offside Front Suspension arm has excessive play in a ball joint (2.4.G.2)
- Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)
- Advice** Passenger seat(s) missing at time of test all rear
- Fail** Front Brake pad(s) less than 1.5 mm thick (3.5.1g)
- Advice** Vehicle structure has slight corrosion both front outer sills (6.1.B.2)
- Fail** Offside Front Front constant velocity joint gaiter insecure to the extent that it no longer prevents the ingress of dirt etc (2.5.C.1a)
- Fail** Offside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)
- Advice** Oil leak
- Fail** Nearside Headlamp aim too low (1.8)
- Advice** Spare tyre defective

**MOT #14** 2016-08-08 12:18**MOT test number** 110841125399**Result** Passed**MOT #13** 2016-08-08 09:02**MOT test number** 256602492071**Result** Failed**Fail** Windscreen has a sticker or other obstruction encroaching into the swept area by more than 40mm outside zone 'A' (8.3.1e)**Fail** Nearside Registration plate lamp not working (1.1.C.1d)**Advice** Tyre worn close to the legal limit both rear (4.1.E.1)**Advice** Engine light on**Fail** Offside Stop lamp not working (1.2.1b)**Fail** Nearside Front position lamp(s) not working (1.1.A.3b)**MOT #12** 2015-07-30 15:45**MOT test number** 996991815221**Result** Passed**Notice** Child seat fitted not allowing full inspection of adult belt

**MOT #11**

2015-07-30 09:46

MOT test number

105621015261

Result**✗ Failed**

- Notice** Child seat fitted not allowing full inspection of adult belt
- Fail** Offside Front position lamp(s) not working (1.1.A.3b)
- Fail** Nearside Headlamp aim too low (1.8)
- Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)
- Fail** Windscreen has a sticker or other obstruction encroaching into the swept area by more than 40mm outside zone 'A' (8.3.1e)
- Notice** Vehicle's internal headlight adjuster altered to recheck lights
- Fail** Offside Registration plate lamp not working (1.1.C.1d)
- Fail** Track rod end ball joint has excessive play (2.2.B.1f)

MOT #10

2014-08-06 15:26

MOT test number

149788014242

Result**✓ Passed****MOT #9**

2014-08-06 09:37

MOT test number

398778014276

Result**✗ Failed**

- Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)
- Fail** Front Windscreen washer provides insufficient washer liquid (8.2.3)
- Fail** Nearside Registration plate lamp not working (1.1.C.1d)
- Fail** Front Windscreen wiper does not clear the windscreen effectively (8.2.2)
- Notice** Nail in nearside rear tyre
- Fail** Front Brakes imbalanced across an axle (3.7.B.5b)

**MOT #8** 2013-07-23 14:35**MOT test number** 288064103299**Result** ✓ Passed**MOT #7** 2013-07-23 09:08**MOT test number** 496054403289**Result** ✗ Failed**Fail** Front Brakes imbalanced across an axle (3.7.B.5b)**Advice** Tyre worn close to the legal limit (4.1.E.1)**Fail** Offside Registration plate lamp not working (1.1.C.1d)**Advice** Front Brake pad(s) wearing thin (3.5.1g)**Notice** Both front tyres wearing on both edges**MOT #6** 2012-08-07 09:10**MOT test number** 967790622266**Result** ✓ Passed**MOT #5** 2012-08-07 09:10**MOT test number** 359070522436**Result** ✗ Failed**Pass with rectification** Nearside Registration plate lamp not working (1.1.C.1d)**MOT #4** 2011-07-18 10:11**MOT test number** 398569391133**Result** ✓ Passed**Advice** Brakes imbalanced requirements only just met. It would appear that the braking system requires adjustment or repair. (3.7.B.5b)

**MOT #3** 2011-07-18 10:11**MOT test number** 516889391170**Result** ✗ Failed**Advice** Brakes imbalanced requirements only just met. It would appear that the braking system requires adjustment or repair. (3.7.B.5b)**Pass with rectification** Nearside Headlamp aim too low (1.8)**MOT #2** 2010-08-02 11:20**MOT test number** 422814710276**Result** ✓ Passed**MOT #1** 2010-07-30 13:17**MOT test number** 592731910229**Result** ✗ Failed**Fail** Nearside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)



Damage history

Check the damage history for this CITROEN. See if, where and when this CITROEN had damage and the car repair costs. We also check if this CITROEN was scrapped. Download the premium report [here](#) for the results.

Damage 1	
Date	
Category	
Type	
Damage 2	
Date	
Category	
Type	



Extra CITROEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this CITROEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 15,200
Auction value	£ 15,200
Average private trade value	£ 15,200

More info >



Owner history

For how long did the current and previous owner(s) have this CITROEN? How many owners did this CITROEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this CITROEN had different number plates.

Number of plates	1
Current registration	
Plate since	2019-03-28
Current registration	
Plate since	2019-03-28

More info >



Finance check

Check if this CITROEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this CITROEN has been settled.

If not, and you buy this CITROEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this CITROEN is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	21
First mileage registration	2007-08-09
Last registration	2020-08-13
Complete history	See info



Registration #1	2007-08-09	19 mi
Registration #2	2010-07-30	14.391 mi
Registration #3	2010-08-02	14.462 mi
Registration #4	2011-07-18	23.371 mi
Registration #5	2012-08-07	33.315 mi
Registration #6	2013-07-23	43.808 mi
Registration #7	2013-07-23	43.808 mi
Registration #8	2014-08-06	57.756 mi
Registration #9	2014-08-06	57.756 mi
Registration #10	2015-07-30	75.596 mi
Registration #11	2015-07-30	75.596 mi
Registration #12	2016-07-30	93.436 mi
Registration #13	2016-07-30	93.436 mi
Registration #14	2017-07-30	111.276 mi
Registration #15	2017-07-30	111.276 mi
Registration #16	2018-07-30	129.116 mi
Registration #17	2018-07-30	129.116 mi
Registration #18	2019-07-30	146.956 mi
Registration #19	2019-07-30	146.956 mi
Registration #20	2020-07-30	164.796 mi
Registration #21	2020-07-30	164.796 mi

More info >



Safety ratings

NCAP rating	★★★★☆
Video	see crash video



Dimensions & weight

Width	1667 mm
Height	1521 mm
Length	3850 mm
Wheel base	2460 mm
Max. allowed weight	1597 kg

Additional information

Fuel tank capacity	47 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5
Number of axles	2
Engine number	FX6F3239543