



RENAULT

HK08WKF


report date: 2024-03-29

General information

Make	RENAULT
Model	MEGANE
Colour	Gold
Year of manufacture	2008
Gearbox	-

Engine & fuel consumption

Engine capacity	1.870 cc
Fuel type	Diesel
CO2 emission	154 g/km
CO2 label	G





Internet history

Entry 1

Date	2021-07-06
Pictures	10
Listing price	View report



source: autotrader.co.uk



MOT history

MOT expiry date	2024-07-19
MOT pass rate	57 %
MOT passed	13
Failed MOT tests	10
Total advice items	42
Total items failed	21

MOT #23	2023-07-20 11:35
MOT test number	515423825166
Result	✓ Passed
Next expiry date	2024-07-19
Advice	Offside Front Seat belt webbing slightly damaged or frayed (7.1.2 (b) (ii))
Advice	Park brake performance only just met minimum standard
Advice	Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

MOT #22	2023-07-14 11:24
MOT test number	155487939836
Result	✗ Failed
MAJOR	Front Brake disc significantly and obviously worn (1.1.14 (a) (i))
MAJOR	Offside Headlamp aim projected beam image is obviously incorrect (4.1.2 (c))
Advice	Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
MAJOR	Offside Front Service brake excessively binding (1.2.1 (f))
MAJOR	Nearside Headlamp aim projected beam image is obviously incorrect (4.1.2 (c))
MAJOR	Nearside Front Suspension arm ball joint excessively worn (5.3.4 (a) (i))
DANGEROUS	Offside Front Seat belt webbing significantly weakened (7.1.2 (b) (ii))
MAJOR	Parking brake efficiency below requirements (1.4.2 (a) (i))

**MOT #21** 2022-02-14 14:50**MOT test number** 622704684612**Result** ✓ Passed**MOT #20** 2021-06-29 13:40**MOT test number** 131825158529**Result** ✓ Passed**Advice** Nearside front mirror damaged**MOT #19** 2021-06-18 13:04**MOT test number** 556358909734**Result** ✗ Failed**MAJOR** Rear Exhaust system insecure mount (6.1.2 (a))**DANGEROUS** Nearside Front Tyre tread pattern not visible over the whole tread area when minimum depth required is 1.0mm 205/55/17 (5.2.3 (e))**MAJOR** Anti-lock braking system warning lamp indicates an ABS fault (1.6 (b))**MAJOR** Offside Front Direction indicator incorrect colour (4.4.3 (a))**MAJOR** Nearside Front Upper Shock absorbers has an excessively worn bush (5.3.2 (c))**Advice** Nearside front mirror damaged**DANGEROUS** Offside Front Tyre tread pattern not visible over the whole tread area when minimum depth required is 1.0mm 205/50/17 (5.2.3 (e))**MAJOR** Nearside Rear Direction indicator incorrect colour (4.4.3 (a))**MOT #18** 2020-06-16 17:01**MOT test number** 162030745268**Result** ✓ Passed**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Upper Shock absorbers has a slightly worn bush (5.3.2 (c))

**MOT #17** 2020-06-16 12:43**MOT test number** 151923510748**Result** ✗ Failed**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MAJOR** Rear Exhaust system insecure (6.1.2 (a))**Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Upper Shock absorbers has a slightly worn bush (5.3.2 (c))**MOT #16** 2019-07-04 09:20**MOT test number** 765487864812**Result** ✓ Passed**MOT #15** 2018-06-22 17:18**MOT test number** 220528003268**Result** ✓ Passed**MOT #14** 2018-06-22 13:11**MOT test number** 653220111160**Result** ✗ Failed**DANGEROUS** Offside Rear Tyre tread depth below requirements of 1.6mm (5.2.3 (e))**DANGEROUS** Nearside Rear Tyre tread depth below requirements of 1.6mm (5.2.3 (e))**MOT #13** 2017-06-16 16:58**MOT test number** 754380243996**Result** ✓ Passed

**MOT #12** 2017-06-16 10:33**MOT test number** 790690058141**Result** ✗ Failed**Fail** Nearside Front brake disc in such a condition that it is seriously weakened (3.5.1i)**Fail** Nearside Front coil spring broken (2.4.C.1a)**Fail** Offside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)**Fail** Offside Front brake disc in such a condition that it is seriously weakened (3.5.1i)**Fail** Nearside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)**MOT #11** 2016-06-06 10:23**MOT test number** 109905645094**Result** ✓ Passed**Advice** Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**MOT #10** 2016-06-06 10:23**MOT test number** 343776379434**Result** ✗ Failed**Pass with rectification** Nearside Rear Stop lamp not working (1.2.1b)**Pass with rectification** Nearside Rear Rear position lamp(s) not working (1.1.A.3b)**Advice** Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**MOT #9** 2015-06-05 17:11**MOT test number** 939096255121**Result** ✓ Passed**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)

**MOT #8** 2015-06-05 13:26**MOT test number** 506376055177**Result** ✗ Failed**Fail** Offside Stop lamp not working (1.2.1b)**Fail** Nearside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1)**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**Fail** Offside Front Front constant velocity joint gaiter insecure to the extent that it no longer prevents the ingress of dirt etc (2.5.C.1a)**Fail** Registration plate lamp not working (1.1.C.1d)**Fail** Offside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)**Fail** Nearside Front Front constant velocity joint gaiter insecure to the extent that it no longer prevents the ingress of dirt etc (2.5.C.1a)**MOT #7** 2014-06-20 19:33**MOT test number** 978921274195**Result** ✓ Passed**MOT #6** 2013-06-07 11:48**MOT test number** 959558353114**Result** ✓ Passed**Advice** Front Brake pad(s) wearing thin (3.5.1g)**Advice** Rear Brake pad(s) wearing thin (3.5.1g)

**MOT #5** 2013-06-07 11:48**MOT test number** 225448753110**Result** ✗ Failed**Pass with rectification** Offside Headlamp aim too low (1.8)**Advice** Front Brake pad(s) wearing thin (3.5.1g)**Pass with rectification** Nearside Headlamp aim too high (1.8)**Pass with rectification** Nearside Windscreen wiper does not clear the windscreen effectively (8.2.2)**Advice** Rear Brake pad(s) wearing thin (3.5.1g)**MOT #4** 2012-05-31 16:12**MOT test number** 797152952104**Result** ✓ Passed**MOT #3** 2012-05-31 16:12**MOT test number** 226702052169**Result** ✗ Failed**Pass with rectification** Front registration plate character(s) incorrectly spaced (6.3.4a)**Pass with rectification** Rear registration plate character(s) incorrectly spaced (6.3.4a)**MOT #2** 2011-06-21 14:58**MOT test number** 658102471101**Result** ✓ Passed**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)



MOT #1

2011-06-15 16:07

MOT test number

358756461182

Result

✗ Failed

- Fail

Nearside Front Steering rack gaiter split (2.2.D.2d)
- Advice

Nearside Front Tyre worn close to the legal limit (4.1.E.1)
- Fail

Nearside Headlamp not working on dipped beam (1.7.5a)
- Notice

Nearside front steering rack slight play
- Fail

Nearside Front Steering rack gaiter insecure (2.2.D.2d)
- Advice

Offside Front Tyre worn close to the legal limit (4.1.E.1)



Tax & MOT check

X

Untaxed

Tax expired:
1 March 2024

✓

MOT

Expires:
19 July 2024

Tax status	Expired at 1 March 2024
Days left	60 days too late
MOT expiry date	19 July 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	G
Single payment (12 months)	£ 240,00,-
Single six month payment	£ 132,00,-
Total payable by 12 monthly instalments	£ 252,00,-



Damage history

Check the damage history for this RENAULT. See if, where and when this RENAULT had damage and the car repair costs. We also check if this RENAULT was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra RENAULT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this RENAULT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,299
Auction value	£ 19,299
Average private trade value	£ 19,299

More info >



Owner history

For how long did the current and previous owner(s) have this RENAULT? How many owners did this RENAULT have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this RENAULT had different number plates.

Number of plates	1
Current registration	XXXXXX
Plate since	2024-03-29
Current registration	XXXXXX
Plate since	2024-03-29

More info >



Finance check

Check if this RENAULT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this RENAULT has been settled.

If not, and you buy this RENAULT then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this RENAULT is financed.

Finance company	RENAULT	2024
Date of agreement	RENAULT	2024
Agreement type	RENAULT	2024
Agreement term	RENAULT	2024
Agreement number	RENAULT	2024
Contact info	RENAULT	2024

More info >



Mileage check

Odometer	In miles
Mileage registrations	23
First mileage registration	2008-06-20
Last registration	2023-07-20
Complete history	See info



Registration #1	2008-06-20	27 mi
Registration #2	2011-06-15	21.120 mi
Registration #3	2011-06-21	21.386 mi
Registration #4	2012-05-31	36.334 mi
Registration #5	2013-06-07	57.885 mi
Registration #6	2014-06-20	67.484 mi
Registration #7	2015-06-05	76.009 mi
Registration #8	2015-06-05	76.009 mi
Registration #9	2016-06-06	84.490 mi
Registration #10	2016-06-06	84.490 mi
Registration #11	2017-06-16	90.796 mi
Registration #12	2017-06-16	90.797 mi
Registration #13	2018-06-20	90.797 mi
Registration #14	2018-06-20	90.797 mi
Registration #15	2019-06-20	90.797 mi
Registration #16	2019-06-20	90.797 mi
Registration #17	2019-06-20	90.797 mi
Registration #18	2019-06-20	90.797 mi
Registration #19	2019-06-20	90.797 mi
Registration #20	2019-06-20	90.797 mi
Registration #21	2019-06-20	90.797 mi
Registration #22	2019-06-20	90.797 mi
Registration #23	2019-06-20	90.797 mi

More info >



Car features

The RENAULT factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete RENAULT factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Additional information

Number of seats 4

Engine number C044846