



report date: 2024-03-29

General information

Make	LAND ROVER
Model	RANGE ROVER SPORT TDV6 HSE
Colour	Silver
Year of manufacture	2006
Top speed	120 mph
0 - 60 mph	11.9 seconds
Gearbox	6 speed automatic

Engine & fuel consumption

Power	188 BHP
Max. torque	440 Nm at 1.900 rpm
Engine capacity	2.720 cc
Cylinders	6
Fuel type	Diesel
Consumption city	21.4 mpg
Consumption extra urban	33.2 mpg
Consumption combined	27.7 mpg
CO2 emission	271 g/km
CO2 label	M





Internet history

Entry 1

Date	2021-05-24
Pictures	15
Listing price	View report



source: autotrader.co.uk



MOT history

MOT expiry date	2024-03-07
MOT pass rate	71 %
MOT passed	10
Failed MOT tests	4
Total advice items	13
Total items failed	15

MOT #14	2023-03-08 15:54
MOT test number	820152361482
Result	✓ Passed
Next expiry date	2024-03-07

MOT #13	2022-02-25 09:08
MOT test number	684489568129
Result	✓ Passed
Advice	Offside Front Service brake binding but not excessively (1.2.1 (f))
Advice	Undertray fitted

MOT #12	2022-02-24 09:12
MOT test number	889768659114
Result	✗ Failed
Advice	Undertray fitted
Fail	Offside Rear Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))
Fail	Offside Rear Service brake excessively binding (1.2.1 (f))
Advice	Offside Front Service brake binding but not excessively (1.2.1 (f))

**MOT #11**

2021-12-22 09:44

MOT test number

825574866263

Result**✗ Failed****Minor**

Offside Front Headlamp lens slightly defective Slightly deteriorated (4.1.1 (b) (i))

Fail

Nearside Front Headlamp lens seriously defective Deteriorated (4.1.1 (b) (ii))

Advice

Offside Rear Service brake binding but not excessively (1.2.1 (f))

Advice

Undertray fitted

Fail

Offside Front Tyre has a tear, caused by separation or partial failure of its structure (5.2.3 (d) (ii))

Fail

Nearside Front Inner Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))

Fail

Prop shaft bearing excessively worn (6.1.7 (b) (i))

MOT #10

2020-12-15 15:55

MOT test number

140654471428

Result**✓ Passed****MOT #9**

2020-12-11 10:02

MOT test number

373491317129

Result**✗ Failed****Fail**

Front Suspension component pin or bush excessively worn rear bushes both (5.3.4 (a) (i))

Fail

Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii))

Fail

Nearside Rear Position lamp not working (4.2.1 (a) (ii))

Fail

Front Brakes imbalanced across an axle Axle 1 (1.2.1 (b) (i))

Fail

Windscreen washer not working (3.5 (a))

Fail

Nearside Front Position lamp not working (4.2.1 (a) (ii))

**MOT #8** 2019-12-20 10:56**MOT test number** 973384763848**Result** ✓ Passed**MOT #7** 2018-12-17 13:05**MOT test number** 623700482215**Result** ✓ Passed**Advice** Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**MOT #6** 2018-12-14 08:57**MOT test number** 774050403774**Result** ✗ Failed**Fail** Nearside Rear Registration plate lamp does not illuminate simultaneously with the position lamps (4.7.2 (a))**Fail** Nearside Front Tyre has a tear, caused by separation or partial failure of its structure (5.2.3 (d) (ii))**Fail** Offside Front Position lamp not working side light (4.2.1 (a))**Advice** Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**MOT #5** 2017-12-15 15:17**MOT test number** 984648784680**Result** ✓ Passed**MOT #4** 2016-12-07 10:57**MOT test number** 733637224492**Result** ✓ Passed**Advice** Rear Brake pipe slightly corroded both front to rear (3.6.B.2c)**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Front Suspension arm has slight play in a pin/bush both big bushes (2.4.G.2)



MOT #3	2015-12-16 10:53
MOT test number	730587786874
Result	✓ Passed
Advice	Rear Brake pad(s) wearing thin (3.5.1g)

MOT #2	2014-12-15 09:36
MOT test number	337069944333
Result	✓ Passed

MOT #1	2013-12-18 15:51
MOT test number	265192253322
Result	✓ Passed



Tax & MOT check

X

Untaxed

Tax expired:
1 October 2023

X

MOT

Expired:
7 March 2024

Tax status	Expired at 1 October 2023
Days left	212 days too late
MOT expiry date	7 March 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	M
Single payment (12 months)	£ 695,00,-
Single six month payment	£ 382,25,-
Total payable by 12 monthly instalments	£ 729,75,-



Damage history

Check the damage history for this LAND ROVER. See if, where and when this LAND ROVER had damage and the car repair costs. We also check if this LAND ROVER was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra LAND ROVER salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this LAND ROVER in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,200
Auction value	£ 19,200
Average private trade value	£ 19,200

More info >



Owner history

For how long did the current and previous owner(s) have this LAND ROVER? How many owners did this LAND ROVER have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To

More info >

Plate changes

See in this check if this LAND ROVER had different number plates.

Number of plates	1
Current registration	XXXXXX
Plate since	2024-03-29
Current registration	XXXXXX
Plate since	2024-03-29

More info >



Finance check

Check if this LAND ROVER is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this LAND ROVER has been settled.

If not, and you buy this LAND ROVER then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this LAND ROVER is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	16
First mileage registration	2006-05-12
Last registration	2023-03-08
Complete history	See info



Registration #1	2006-05-12	17 mi
Registration #2	2013-12-18	93.149 mi
Registration #3	2014-12-15	97.044 mi
Registration #4	2015-12-16	101.371 mi
Registration #5	2016-12-07	104.517 mi
Registration #6	2017-12-15	108.797 mi
Registration #7	2018-12-14	113.500 mi
Registration #8	2018-12-17	113.500 mi
Registration #9	2019-05-20	113.500 mi
Registration #10	2019-05-20	113.500 mi
Registration #11	2019-05-20	113.500 mi
Registration #12	2019-05-20	113.500 mi
Registration #13	2019-05-20	113.500 mi
Registration #14	2019-05-20	113.500 mi
Registration #15	2019-05-20	113.500 mi
Registration #16	2019-05-20	113.500 mi

More info >



Safety ratings

NCAP rating	★★★★☆
Video	see crash video



Dimensions & weight

Width	1928 mm
Height	1784 mm
Length	4788 mm
Wheel base	2745 mm
Kerb weight	2455 kg
Max. allowed weight	3070 kg

Additional information

Fuel tank capacity	84 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5
Number of axles	2
Engine number	0124983276DT