





report date: 2024-03-29

General information

Make	JAGUAR
Model	XJ D V6 R-SPORT
Colour	Red
Year of manufacture	2014
Top speed	149 mph
0 - 60 mph	6.7 seconds
Gearbox	8 speed automatic

Engine & fuel consumption

Power	240 BHP
Max. torque	500 Nm at 2.000 rpm
Engine capacity	2.993 сс
Cylinders	6
Fuel type	Diesel
Consumption city	37.7 mpg
Consumption extra urban	56.5 mpg
Consumption combined	47.1 mpg
CO2 emission	159 g/km
CO2 label	G



CarCheck.co.uk page 1/11



report date: 2024-03-29

Internet history

Entry 2

Date 2023-11-30	
-----------------	--

Pictures 50

Listing price <u>View report</u>









source: cargurus.co.uk

Entry 1

Date	2021-07-30
Pictures	0
Listing price	View report

source: cargurus.co.uk

CarCheck.co.uk page 2/11



report date: 2024-03-29

B 4	\sim $-$		
10.71	$^{\prime}$	hic	tory
101	C I	1115	I OI V
	•		,

MOT expiry date	2024-08-16
MOT pass rate	88 %
MOT passed	7
Failed MOT tests	1
Total advice items	12
Total items failed	0

MOT #8	2023-07-22 11:18
MOT test number	818110016440
Result	✓ Passed
Next expiry date	2024-08-16

MOT #7	2022-08-05 12:11
MOT test number	971234427324
Result	✓ Passed
Advice Covers and undertrays limit access to some components	

MOT #6	2021-08-13 15:47
MOT test number	473063269189
Result	✓ Passed

MOT #5	2020-08-17 09:54
MOT test number	638013902143
Result	✓ Passed
Advice Front Brake disc worn, pitted	l or scored, but not seriously weakened Both Inner Face Of Disc
Advice Front Brake disc worn, pitted (1.1.14 (a) (ii))	or scored, but not seriously weakened Both Inner Face O

CarCheck.co.uk page 3/11



report date: 2024-03-29

MOT #4 2019-07-25 12:36

MOT test number 136909658647

Result ✓ Passed

Advice Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Oil leak, but not excessive (8.4.1 (a) (i))

Advice Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

MOT #3 2018-07-31 13:45

MOT test number 485462223154

Result ✓ Passed

Advice Engine oil leak

Advice Front Brake disc worn, pitted or scored, but not seriously weakened inner faces uneven and corroded, slight judder felt (1.1.14 (a) (ii))

MOT #2 2018-07-30 12:22

MOT test number 714789972037

Result X Failed

Advice Nearside Front Tyre worn close to legal limit/worn on edge bald inner edge (5.2.3 (e))

Advice Engine oil leak

MAJOR Offside Rear Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (5.2.3 (d) (i))

Advice Front Brake disc worn, pitted or scored, but not seriously weakened inner faces uneven and corroded, slight judder felt (1.1.14 (a) (ii))

Advice Offside Front Tyre worn close to legal limit/worn on edge bald inner edge (5.2.3 (e))

MOT #1 2017-08-08 07:58

MOT test number 430289450836

Result

Passed

CarCheck.co.uk page 4/11



report date: 2024-03-29

Tax & MOT check



Tax status	Valid until 1 December
Days left	215
MOT expiry date	16 August 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	G
Single payment (12 months)	£ 240,00,-
Single six month payment	£ 132,00,-
Total payable by 12 monthly instalments	£ 252,00,-

CarCheck.co.uk page 5/11



report date: 2024-03-29

Damage history

Check the damage history for this JAGUAR. See if, where and when this JAGUAR had damage and the car repair costs. We also check if this JAGUAR was scrapped. Download the premium report <u>here</u> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra JAGUAR salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 6/11



report date: 2024-03-29

Vehicle valuation

What is this car worth? See the vehicle value of this JAGUAR in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 7/11



report date: 2024-03-29

α	vner	hi	ctc	1
\cup	viiei	ш	SIL	ע ונ

For how long did the current and previous owner(s) have this JAGUAR? How many owners have? Check it in the premium report and see all owner registrations. Download the full report and see all owner registrations.	

THE REAL PROPERTY AND ADDRESS OF THE PERTY ADDRESS OF THE PERTY ADDRESS OF THE PERTY AND ADDRESS OF THE PERTY ADDR	

	More info >
Plate changes	
See in this check if this JAGUAR had different number plates.	
Number of plates	
Current registration	UK UK
Plate since	
Current registration	NK NK
Plate since	
	More info >

CarCheck.co.uk page 8/11



report date: 2024-03-29

Finance check

Check if this JAGUAR is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this JAGUAR has been settled.

If not, and you buy this JAGUAR then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this JAGUAR is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

Contact info

More info >

CarCheck.co.uk page 9/11



report date: 2024-03-29

Mileage check

Odometer	In miles
Mileage registrations	11
First mileage registration	2014-12-20
Last registration	2023-07-22
Complete history	See info



Registration #1	2014-12-20	26 mi
Registration #2	2017-08-08	15.850 mi
Registration #3	2018-07-30	20.548 mi
Registration #4	2018-07-31	20.548 mi
Registration #5	2019-07-25	25.007 mi
Registration #6	2020-08-17	28.281 mi
Registration #7		11.777 es
Registration #8		11.777 es
Registration #9		11.777 es
Registration #10		11.777 es
Registration #11		11.777 mg

More info >

CarCheck.co.uk page 10/11



report date: 2024-03-29

Safety ratings

NCAP rating	***
Adult	79%
Children	73%
Pedestrian	62%
Safety systems	71%
Overall rating	74%
Video	see crash video



Dimensions & weight

Width	1877 mm
Height	1460 mm
Length	4961 mm
Wheel base	2909 mm
Kerb weight	1770 kg
Max. allowed weight	2360 kg

Additional information

Fuel tank capacity	70 I
Fuel delivery	Direct Injection
Number of doors	4
Number of seats	5
Number of axles	2
Engine number	0823391306DT

CarCheck.co.uk page 11/11