



report date: 2024-03-28

General information

|                     |                |
|---------------------|----------------|
| Make                | FORD           |
| Model               | MONDEO ST 220  |
| Colour              | Black          |
| Year of manufacture | 2006           |
| Top speed           | 155 mph        |
| 0 - 60 mph          | 7.6 seconds    |
| Gearbox             | 6 speed Manual |

Engine & fuel consumption

|                         |                     |
|-------------------------|---------------------|
| Power                   | 226 BHP             |
| Max. torque             | 285 Nm at 4.900 rpm |
| Engine capacity         | 2.967 cc            |
| Cylinders               | 6                   |
| Fuel type               | Petrol              |
| Consumption city        | 19.3 mpg            |
| Consumption extra urban | 34.9 mpg            |
| Consumption combined    | 26.9 mpg            |
| CO2 emission            | 249 g/km            |
| CO2 label               | L                   |





Internet history

Entry 1

|               |                             |
|---------------|-----------------------------|
| Date          | 2021-05-25                  |
| Pictures      | 0                           |
| Listing price | <a href="#">View report</a> |

source: [autotrader.co.uk](#)



## MOT history

|                    |            |
|--------------------|------------|
| MOT expiry date    | 2022-04-13 |
| MOT pass rate      | 76 %       |
| MOT passed         | 13         |
| Failed MOT tests   | 4          |
| Total advice items | 30         |
| Total items failed | 6          |

MOT #17 2022-05-04 08:46

MOT test number 709594295198

Result ✗ Failed

- Fail** Offside Front Coil spring fractured or broken (5.3.1 (b) (i))
- Fail** Nearside Rear Shock absorbers has a serious fluid leak (5.3.2 (b))

MOT #16 2021-03-19 10:11

MOT test number 803260379006

Result ✓ Passed

- Advice** Nearside Rear Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))
- Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Offside Rear Road wheel slightly distorted (5.2.2 (c) (i))
- Advice** Front Oil residue around engine area

**MOT #15**

2021-03-17 12:19

**MOT test number**

553828678969

**Result**

✗ Failed

**Advice** Nearside Rear Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))**Advice** Front Oil residue around engine area**Fail** Nearside Rear Hydraulic brake calliper leaking (1.1.16 (b) (i))**Advice** Offside Rear Road wheel slightly distorted (5.2.2 (c) (i))**Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**MOT #14**

2020-03-17 09:14

**MOT test number**

232514637371

**Result**

✓ Passed

**MOT #13**

2019-03-19 16:14

**MOT test number**

685448951471

**Result**

✓ Passed

**Advice** Nearside Rear Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))**MOT #12**

2018-03-27 10:22

**MOT test number**

745026329972

**Result**

✓ Passed

**Advice** Slight misting of oil engine area (belt side)**Advice** Nearside Rear Road wheel with a slightly distorted bead rim (4.2.A.1a)**Advice** Offside Front Tyre worn close to the legal limit beginning to wear on shoulders (4.1.E.1)**Advice** Offside Front Road wheel with a slightly distorted bead rim (4.2.A.1a)**Advice** Nearside Front Tyre worn close to the legal limit beginning to wear on shoulders (4.1.E.1)

**MOT #11** 2018-03-27 10:22**MOT test number** 259496032350**Result** ✗ Failed**Advice** Offside Front Tyre worn close to the legal limit beginning to wear on shoulders (4.1.E.1)**Pass with rectification** Offside Front position lamp(s) not working (1.1.A.3b)**Advice** Offside Front Road wheel with a slightly distorted bead rim (4.2.A.1a)**Advice** Nearside Front Tyre worn close to the legal limit beginning to wear on shoulders (4.1.E.1)**Advice** Slight misting of oil engine area (belt side)**Pass with rectification** Rear Inner All position lamps not working (1.1.A.3b)**Advice** Nearside Rear Road wheel with a slightly distorted bead rim (4.2.A.1a)**MOT #10** 2017-03-29 09:44**MOT test number** 569741788630**Result** ✓ Passed**MOT #9** 2016-03-16 14:49**MOT test number** 276703189890**Result** ✓ Passed**Advice** Front wipers poor**MOT #8** 2015-03-17 11:03**MOT test number** 907336375090**Result** ✓ Passed

**MOT #7** 2014-03-18 15:21**MOT test number** 375477474022**Result** ✓ Passed**Notice** Engine covers fitted obscuring some components in the engine bay**Advice** Front Anti-roll bar has slight play in a pin/bush (2.4.G.2)**MOT #6** 2013-03-26 12:53**MOT test number** 446455983091**Result** ✓ Passed**Notice** Front number plate poor**MOT #5** 2012-03-20 11:09**MOT test number** 148110682034**Result** ✓ Passed**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**MOT #4** 2011-03-16 15:16**MOT test number** 218065771012**Result** ✓ Passed**MOT #3** 2011-03-16 12:32**MOT test number** 346745971071**Result** ✗ Failed**Fail** Rear Brake pad(s) less than 1.5 mm thick (3.5.1g)**Notice** Handbrake near reserve travel limit



|                 |  |
|-----------------|--|
| MOT #2          | 2010-03-18 15:03   |
| MOT test number | 810297170021   |
| Result          | ✓ Passed   |
| Advice          | Nearside Front Tyre worn close to the legal limit (4.1.E.1)                  |
| Notice          | Front number plate beginning to deteriorate                                  |
| Advice          | Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i) |
| Advice          | Offside Front Tyre worn close to the legal limit (4.1.E.1)                   |

|                 |                  |
|-----------------|------------------|
| MOT #1          | 2009-04-01 17:51 |
| MOT test number | 970811999090     |
| Result          | ✓ Passed         |



Damage history

Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report [here](#) for the results.

Damage 1

|          |  |
|----------|--|
| Date     |  |
| Category |  |
| Type     |  |

Damage 2

|          |  |
|----------|--|
| Date     |  |
| Category |  |
| Type     |  |



Extra FORD salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >





Vehicle valuation

What is this car worth? See the vehicle value of this FORD in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

|                             |          |
|-----------------------------|----------|
| Trade retail value          | £ 19,999 |
| Auction value               | £ 19,999 |
| Average private trade value | £ 19,999 |

More info >



Owner history

For how long did the current and previous owner(s) have this FORD? How many owners did this FORD have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

|       |       |
|-------|-------|
| Owner | Since |
| Owner | Since |
| Owner | Since |
| Owner | Since |
| Owner | Since |
| Owner | Since |
| Owner | Since |

More info >

Plate changes

See in this check if this FORD had different number plates.

|                      |            |
|----------------------|------------|
| Number of plates     | 1          |
| Current registration |            |
| Plate since          | 2024-03-28 |
| Current registration |            |
| Plate since          | 2024-03-28 |

More info >



Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this FORD is financed.

|                   |          |      |
|-------------------|----------|------|
| Finance company   | XXXXXXXX | XXXX |
| Date of agreement | XXXXXXXX | XXXX |
| Agreement type    | XXXXXXXX | XXXX |
| Agreement term    | XXXXXXXX | XXXX |
| Agreement number  | XXXXXXXX | XXXX |
| Contact info      | XXXXXXXX | XXXX |

More info >



Mileage check

|                            |                          |
|----------------------------|--------------------------|
| Odometer                   | In miles                 |
| Mileage registrations      | 19                       |
| First mileage registration | 2006-04-13               |
| Last registration          | 2022-05-04               |
| Complete history           | <a href="#">See info</a> |



|                  |            |           |
|------------------|------------|-----------|
| Registration #1  | 2006-04-13 | 17 mi     |
| Registration #2  | 2009-04-01 | 14.179 mi |
| Registration #3  | 2010-03-18 | 21.517 mi |
| Registration #4  | 2011-03-16 | 28.602 mi |
| Registration #5  | 2011-03-16 | 28.602 mi |
| Registration #6  | 2012-03-20 | 32.629 mi |
| Registration #7  | 2013-03-26 | 36.499 mi |
| Registration #8  | 2014-03-18 | 40.220 mi |
| Registration #9  | 2015-03-17 | 43.803 mi |
| Registration #10 | 2016-03-16 | 47.278 mi |
| Registration #11 | 2016-03-16 | 51.777 mi |
| Registration #12 | 2016-03-16 | 51.777 mi |
| Registration #13 | 2016-03-16 | 51.777 mi |
| Registration #14 | 2016-03-16 | 51.777 mi |
| Registration #15 | 2016-03-16 | 51.777 mi |
| Registration #16 | 2016-03-16 | 51.777 mi |
| Registration #17 | 2016-03-16 | 51.777 mi |
| Registration #18 | 2016-03-16 | 51.777 mi |
| Registration #19 | 2016-03-16 | 51.777 mi |

More info >



Car features

The FORD factory car options list is only available in the premium report.

|       |                  |
|-------|------------------|
| S0225 | Air conditioning |
| S0295 |                  |
| S0482 |                  |
| S0501 |                  |
| S0566 |                  |
| S0567 |                  |
| S0569 |                  |

View the complete FORD factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating

Video [see crash video](#)



Dimensions & weight

|                     |         |
|---------------------|---------|
| Width               | 1931 mm |
| Height              | 1429 mm |
| Length              | 4731 mm |
| Wheel base          | 2754 mm |
| Kerb weight         | 1485 kg |
| Max. allowed weight | 1975 kg |

Additional information

|                    |                       |
|--------------------|-----------------------|
| Fuel tank capacity | 58 l                  |
| Fuel delivery      | Multi-Point Injection |
| Number of doors    | 4                     |
| Number of seats    | 5                     |

|                        |         |
|------------------------|---------|
| <b>Number of axles</b> | 2       |
| <b>Engine number</b>   | 6S69101 |