



General information

Make	VOLKSWAGEN
Model	TOURAN FSI S 5 STR
Colour	Silver
Year of manufacture	2004
Top speed	116 mph
0 - 60 mph	11.9 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	113 BHP
Max. torque	155 Nm at 4.000 rpm
Engine capacity	1.598 cc
Cylinders	4
Fuel type	Petrol
Consumption city	29.1 mpg
Consumption extra urban	44.1 mpg
Consumption combined	37.2 mpg
CO2 emission	180 g/km
CO2 label	I






Internet history

Entry 1

Date	2021-07-31
Pictures	22
Listing price	<a href="#">View report</a>



source: cargurus.co.uk



## MOT history

MOT expiry date	2025-03-24
MOT pass rate	70 %
MOT passed	16
Failed MOT tests	7
Total advice items	46
Total items failed	30

MOT #23 2024-03-22 11:09

MOT test number 973480604342

Result ✓ Passed

Next expiry date 2025-03-24

**Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**Minor** Nearside Front Outer Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))

**Advice** Nearside Rear Child Seat fitted not allowing full inspection of adult belt

MOT #22 2024-03-22 10:25

MOT test number 313222911327

Result ✗ Failed

**Advice** Nearside Rear Child Seat fitted not allowing full inspection of adult belt

**Fail** Engine MIL inoperative or indicates a malfunction (8.2.1.2 (h))

**Fail** Offside Headlamp aim projected beam image is obviously incorrect (4.1.2 (c))

**Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**Minor** Nearside Front Outer Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))

**Fail** Nearside Headlamp aim projected beam image is obviously incorrect (4.1.2 (c))

**Fail** Nearside Rear Position lamp not working (4.2.1 (a) (ii))



MOT #21	2023-03-21 14:49
MOT test number	539647757177
Result	✓ Passed
Minor	Nearside Rear Position lamp with a multiple light source up to 1/2 not functioning (4.2.1 (a) (i))

MOT #20	2023-03-21 11:11
MOT test number	599911906166
Result	✗ Failed
Fail	Engine MIL inoperative or indicates a malfunction (8.2.1.2 (h))
Minor	Nearside Rear Position lamp with a multiple light source up to 1/2 not functioning (4.2.1 (a) (i))
Fail	Exhaust Lambda reading after 2nd fast idle outside specified limits (8.2.1.2 (c))

MOT #19	2022-03-23 11:03
MOT test number	405121768543
Result	✓ Passed
Advice	Offside Rear Brake hose slightly deteriorated (1.1.12 (b) (ii))
Advice	Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #18	2022-03-22 12:54
MOT test number	422920323232
Result	✗ Failed
Fail	Nearside Rear Coil spring fractured or broken (5.3.1 (b) (i))
Advice	Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Fail	Nearside Rear Brake hose excessively damaged (1.1.12 (b) (ii))
Fail	Nearside Rear Anti-roll bar linkage ball joint excessively worn (5.3.4 (a) (i))
Advice	Offside Rear Brake hose slightly deteriorated (1.1.12 (b) (ii))



MOT #17	2021-03-25 16:11
MOT test number	403371767277
Result	✓ Passed
Advice	Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
Advice	Offside Front Brake hose slightly deteriorated (1.1.12 (b) (ii))
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**MOT #16**

2021-03-19 13:04

**MOT test number**

217688946605

**Result****✗ Failed**

- Fail** Central Rear Seat belt buckle not functioning as intended (7.1.2 (d))
- Fail** Offside Front Anti-roll bar ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))
- Fail** Offside Headlamp aim too high (4.1.2 (a))
- Advice** Offside Front Brake hose slightly deteriorated (1.1.12 (b) (ii))
- Fail** Offside Front Tyre has a tear, caused by separation or partial failure of its structure (5.2.3 (d) (ii))
- Fail** Offside Track rod end ball joint dust cover excessively damaged or deteriorated so that it no longer prevents the ingress of dirt (2.1.3 (g) (ii))
- Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Fail** Offside Front Lower Suspension arm pin or bush excessively worn (5.3.4 (a) (i))
- Fail** Windscreen wiper not working (3.4 (a))
- Fail** Nearside Front Anti-roll bar ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))
- Fail** Nearside Headlamp aim too low (4.1.2 (a))
- Fail** Nearside Front Brake hose excessively deteriorated (1.1.12 (b) (ii))
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Fail** Nearside Track rod end ball joint dust cover excessively damaged or deteriorated so that it no longer prevents the ingress of dirt (2.1.3 (g) (ii))
- Fail** Offside Rear Coil spring missing and directional control affected (5.3.1 (c) (ii))
- Fail** Nearside Front Lower Suspension arm pin or bush excessively worn rear (5.3.4 (a) (i))
- Fail** Horn sound not in accordance with requirements (7.7 (c))
- Fail** Nearside Rear Service brake excessively binding (1.2.1 (f))

**MOT #15**

2019-05-10 14:30

**MOT test number**

598138688277

**Result**

✓ Passed

- Advice** Nearside Rear Anti-roll bar ball joint has slight play (5.3.4 (a) (i))
- Minor** Nearside Front Anti-roll bar linkage ball joint dust cover severely deteriorated (5.3.4 (b) (i))
- Advice** Offside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (i))
- Advice** Offside Rear Child Seat fitted not allowing full inspection of adult belt
- Minor** Nearside Front Track rod end ball joint dust cover damaged or deteriorated, but preventing the ingress of dirt (2.1.3 (g) (i))
- Advice** Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
- Minor** Offside Front Anti-roll bar linkage ball joint dust cover severely deteriorated (5.3.4 (b) (i))

**MOT #14**

2018-06-08 16:18

**MOT test number**

191653593017

**Result**

✓ Passed

- Minor** Offside Front Brake hose slightly chafed (1.1.12 (b) (i))
- Advice** Under trays fitted obscuring full inspection [at time of test]
- Minor** Nearside Front Brake hose slightly chafed (1.1.12 (b) (i))
- Advice** Engine management warning light on [at time of test]

**MOT #13**

2017-06-09 16:44

**MOT test number**

815950440750

**Result**

✓ Passed

**MOT #12** 2017-03-20 09:19**MOT test number** 807367694750**Result** ✗ Failed**Fail** Nearside Front Front wheel bearing has excessive play (2.5.A.3c)**Fail** Exhaust emissions Lambda reading after 2nd fast idle outside specified limits (7.3.D.3)**MOT #11** 2016-04-01 08:13**MOT test number** 413832454086**Result** ✓ Passed**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**MOT #10** 2014-05-02 13:42**MOT test number** 227992424120**Result** ✓ Passed**Notice** Engine covers fitted obscuring some components in the engine bay**Notice** Under-trays fitted obscuring some underside components**MOT #9** 2013-05-15 10:41**MOT test number** 538535833193**Result** ✓ Passed**Notice** Engine covers fitted obscuring some components in the engine bay**Notice** Under-trays fitted obscuring some underside components**Notice** Adv rearmost seats unable to erect



**MOT #8**

2013-05-15 08:59

**MOT test number**

839035833187

**Result**

✗ Failed

- Notice** Under-trays fitted obscuring some underside components
- Notice** Adv offside rear tyre worn on inner section
- Fail** Nearside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1)
- Notice** Adv unable to see rear inner brake pads or discs
- Notice** Engine covers fitted obscuring some components in the engine bay
- Fail** Offside Rear Brake pad(s) less than 1.5 mm thick (3.5.1g)
- Notice** Adv rearmost seats unable to erect
- Fail** Anti-lock braking system warning lamp indicates an ABS fault (3.4.1c)

**MOT #7**

2012-05-24 12:20

**MOT test number**

359235942110

**Result**

✓ Passed

- Advice** Nearside Front Brake pad(s) wearing thin (3.5.1g)

**MOT #6**

2011-05-17 10:22

**MOT test number**

206467231175

**Result**

✓ Passed

- Notice** Child seat fitted not allowing full inspection of adult belt
- Advice** Nearside Rear Direction indicator slightly discoloured (1.4.A.2f)
- Advice** Offside Rear Direction indicator slightly discoloured (1.4.A.2f)

**MOT #5**

2010-05-13 15:52

**MOT test number**

654353830173

**Result**

✓ Passed



MOT #4	2010-05-13 14:40
MOT test number	404793530128
Result	✗ Failed
Fail	Nearside Rear Brake pad(s) less than 1.5 mm thick (3.5.1g)
MOT #3	2009-05-22 09:29
MOT test number	262352149408
Result	✓ Passed
MOT #2	2008-05-23 13:14
MOT test number	890244548176
Result	✓ Passed
Advice	Nearside Rear Tyre worn close to the legal limit (4.1.E.1)
MOT #1	2007-05-19 09:54
MOT test number	224519937136
Result	✓ Passed



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 February 2025

✓  
**MOT**  
**Expires:**  
24 March 2025

<b>Tax status</b>	Valid until 1 February
<b>Days left</b>	277
<b>MOT expiry date</b>	24 March 2025
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	48
<b>Band</b>	I
<b>Single payment (12 months)</b>	£ 320,00,-
<b>Single six month payment</b>	£ 176,00,-
<b>Total payable by 12 monthly instalments</b>	£ 336,00,-



Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history


For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this VOLKSWAGEN had different number plates.

Number of plates	1
Current registration	 BL04EEX
Plate since	2024-03-29
Current registration	 BL04EEX
Plate since	2024-03-29

More info >



Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLKSWAGEN is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	25
First mileage registration	2004-05-26
Last registration	2024-03-22
Complete history	<a href="#">See info</a>



Registration #1	2004-05-26	28 mi
Registration #2	2007-05-19	24.385 mi
Registration #3	2008-05-23	31.044 mi
Registration #4	2009-05-22	37.895 mi
Registration #5	2010-05-13	46.137 mi
Registration #6	2010-05-13	46.137 mi
Registration #7	2011-05-17	57.442 mi
Registration #8	2012-05-24	66.902 mi
Registration #9	2013-05-15	76.687 mi
Registration #10	2013-05-15	76.687 mi
Registration #11	2014-05-02	86.190 mi
Registration #12	2016-04-01	109.291 mi
Registration #13	2017-03-20	113.466 mi
Registration #14	2019-05-22	121.277 mi
Registration #15	2019-05-22	121.277 mi
Registration #16	2019-05-22	121.277 mi
Registration #17	2019-05-22	121.277 mi
Registration #18	2019-05-22	121.277 mi
Registration #19	2019-05-22	121.277 mi
Registration #20	2019-05-22	121.277 mi
Registration #21	2019-05-22	121.277 mi
Registration #22	2019-05-22	121.277 mi
Registration #23	2019-05-22	121.277 mi
Registration #24	2019-05-22	121.277 mi
Registration #25	2019-05-22	121.277 mi





Car features

The VOLKSWAGEN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLKSWAGEN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	2066 mm
Height	1635 mm
Length	4391 mm
Wheel base	2677 mm
Kerb weight	1423 kg

Additional information

Fuel tank capacity	60 l
Fuel delivery	Direct Injection
Number of doors	5
Engine number	BAG 014249