



RENAULT



report date: 2024-03-28

General information

Make	RENAULT
Model	KANGOO AUTHENTIQUE
Colour	Green
Year of manufacture	-
Top speed	91 mph
0 - 60 mph	14.3 seconds
Gearbox	4 speed automatic

Engine & fuel consumption

Power	75 BHP
Max. torque	114 Nm at 2.800 rpm
Cylinders	4
Fuel type	Petrol
Consumption city	27.4 mpg
Consumption extra urban	43.5 mpg
Consumption combined	35.8 mpg



LABEL UNKNOWN

**MOT history**

MOT #18	2022-09-23 08:23
MOT test number	872303114182
Result	✓ Passed
Next expiry date	2023-09-22

MOT #17	2021-12-14 11:49
MOT test number	543788316050
Result	✓ Passed

- Advice** Offside Front Anti-roll bar linkage pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
- Advice** Rear seat back play in latch
- Advice** Offside Play in steering rack inner joint(s)
- Advice** Offside Front Seat belt slightly damaged (7.1.2 (b) (i))
- Advice** Nearside Front Upper Macpherson strut pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
- Advice** Nearside Front arch liner damaged and slightly loose
- Advice** Nearside Front Anti-roll bar linkage pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
- Advice** Nearside Front Lower wing corroded and holed no sharp edges
- Advice** Nearside Play in steering rack inner joint(s)
- Advice** Offside Rear Brake hose has slight corrosion to ferrule (1.1.12 (f) (i))
- Advice** Wipers dont park
- Advice** Nearside Front Outer Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Brake pipe slightly damaged both front to rear (1.1.11 (c))
- Advice** Offside Front Upper Macpherson strut pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
- Advice** Both outer sills have damage

**MOT #16** 2020-10-28 11:12**MOT test number** 962097300361**Result** ✓ Passed**Advice** Slight play in n/s and o/s steering rack ends**MOT #15** 2019-04-10 12:31**MOT test number** 809527501702**Result** ✓ Passed**Advice** Slight play in n/s and o/s steering rack ends**MOT #14** 2019-04-10 10:39**MOT test number** 749135820984**Result** ✗ Failed**Fail** Nearside Front Anti-roll bar linkage damaged and seriously weakened (5.3.3 (b) (i))**Advice** Slight play in n/s and o/s steering rack ends**MOT #13** 2018-04-16 08:46**MOT test number** 540591758624**Result** ✓ Passed**Advice** Rear Brake hose has slight corrosion to ferrules both (3.6.B.4e)**Advice** Offside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Advice** Offside Front Brake hose has slight corrosion to ferrules (3.6.B.4e)**Advice** Nearside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Advice** Nearside Front Brake hose has slight corrosion to ferrules (3.6.B.4e)

**MOT #12** 2017-05-02 08:41**MOT test number** 339143904387**Result** ✓ Passed**Advice** Offside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Advice** Nearside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**MOT #11** 2016-04-08 09:35**MOT test number** 671072343874**Result** ✓ Passed**Advice** Offside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Advice** Nearside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**MOT #10** 2015-04-08 16:32**MOT test number** 158618395077**Result** ✓ Passed**Notice** Play in steering rack inner joint(s)**MOT #9** 2015-04-08 10:41**MOT test number** 799298295068**Result** ✗ Failed**Notice** Play in steering rack inner joint(s)**Fail** Offside Front Anti-roll bar rubber bush deteriorated resulting in excessive movement (2.4.G.2)**MOT #8** 2014-05-13 12:19**MOT test number** 848173334124**Result** ✓ Passed

**MOT #7** 2014-05-10 15:02**MOT test number** 427240734135**Result** ✗ Failed**Fail** Nearside Track rod end ball joint has excessive play (2.2.B.1f)**MOT #6** 2013-05-08 10:54**MOT test number** 309708523182**Result** ✓ Passed**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**Notice** Play in steering rack inner joint(s)**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**MOT #5** 2012-02-16 15:12**MOT test number** 658317642099**Result** ✓ Passed**MOT #4** 2012-02-16 11:51**MOT test number** 768727642016**Result** ✗ Failed**Fail** Nearside Front constant velocity joint gaiter insecure to the extent that it no longer prevents the ingress of dirt etc (2.5.C.1a)**MOT #3** 2011-02-03 17:25**MOT test number** 437334931043**Result** ✗ Failed**Pass with rectification** Offside Front Front constant velocity joint gaiter insecurely mounted to its housing (2.5.C.1a)



MOT #2	2011-02-03 17:25
MOT test number	988134431061
Result	✓ Passed
MOT #1	2010-02-09 09:37
MOT test number	133350140486
Result	✓ Passed



Damage history

Check the damage history for this RENAULT. See if, where and when this RENAULT had damage and the car repair costs. We also check if this RENAULT was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra RENAULT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this RENAULT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this RENAULT? How many owners did this RENAULT have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this RENAULT had different number plates.

Number of plates	1
Current registration	XXXXXX
Plate since	2019-01-01
Current registration	XXXXXX
Plate since	2019-01-01

More info >



Finance check

Check if this RENAULT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this RENAULT has been settled.

If not, and you buy this RENAULT then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this RENAULT is financed.

Finance company	RENAULT	2024
Date of agreement	RENAULT	2024
Agreement type	RENAULT	2024
Agreement term	RENAULT	2024
Agreement number	RENAULT	2024
Contact info	RENAULT	2024

More info >



Mileage check

Odometer	In miles
Mileage registrations	18
First mileage registration	2002-06-27
Last registration	2022-09-23
Complete history	See info



Registration #1	2002-06-27	29 mi
Registration #2	2010-02-09	39.826 mi
Registration #3	2011-02-03	45.299 mi
Registration #4	2012-02-16	51.716 mi
Registration #5	2012-02-16	51.716 mi
Registration #6	2013-05-08	55.336 mi
Registration #7	2014-05-10	61.173 mi
Registration #8	2014-05-13	61.175 mi
Registration #9	2015-04-08	64.719 mi
Registration #10	2015-05-20	65.377 mi
Registration #11	2015-05-20	65.377 mi
Registration #12	2015-05-20	65.377 mi
Registration #13	2015-05-20	65.377 mi
Registration #14	2015-05-20	65.377 mi
Registration #15	2015-05-20	65.377 mi
Registration #16	2015-05-20	65.377 mi
Registration #17	2015-05-20	65.377 mi
Registration #18	2015-05-20	65.377 mi

More info >



Car features

The RENAULT factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete RENAULT factory list for this vehicle [here](#).

More info >

Dimensions & weight

Width	2060 mm
Height	1827 mm
Length	3995 mm
Wheel base	2600 mm
Kerb weight	1065 kg

Additional information

Fuel tank capacity	52 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5
Number of axles	2
Engine number	R007267