





report date: 2024-03-28

General information

Make	MAZDA
Model	MX-5 I
Colour	Silver
Year of manufacture	2006
Top speed	122 mph
0 - 60 mph	9.4 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	124 BHP
Max. torque	166 Nm at 4.500 rpm
Engine capacity	1.798 cc
Cylinders	4
Fuel type	Petrol
Consumption city	28.5 mpg
Consumption extra urban	48.7 mpg
Consumption combined	38.7 mpg
CO2 emission	174 g/km
CO2 label	Н



CarCheck.co.uk page 1/12



report date: 2024-03-28


Internet history

Entry 1

Date 2021-06-15

Pictures 17

Listing price <u>View report</u>









source: autotrader.co.uk

CarCheck.co.uk page 2/12



AL54PAM report date: 2024-03-28

MOT history

MOT expiry date	2024-03-02
MOT pass rate	75 %
MOT passed	15
Failed MOT tests	5
Total advice items	9
Total items failed	5

MOT #20		2023-03-03 12:09
MOT test	number	688264146067
Result		✓ Passed
Next expiry date 2024-03-02		2024-03-02
Advice Vehicle structure is corroded but structural rigidity is not significantly reduced (6.1.1 (c) (i))		
Advice	Several suspension components corroded and sub-frames	

MOT #19		2023-03-02 09:41
MOT test	number	534956457475
Result		X Failed
MAJOR	Offside Front Coil spring fractured or broken (5.3.1 (b) (i))	
Advice	Vehicle structure is corroded but structural rigidity is not significantly reduced (6.1.1 (c) (i))	
Advice	Several suspension components corroded and sub-frames	
Advice	Nearside Front Brake pad(s) wearing thin (1.1.13 (a) (ii))	
MAJOR	Nearside Front Service brake excessively binding (1.2.1 (f))	

MOT #18	2022-01-05 15:27
MOT test number	821683434476
Result	✓ Passed

CarCheck.co.uk page 3/12



report date: 2024-03-28

MOT #17 2022-01-05 15:27

MOT test number 612286387984

Result X Failed

Pass with rectification

Nearside Front Tyre has a bulge, caused by separation or partial failure of its

structure (5.2.3 (d) (ii))

MOT #16 2020-11-02 17:55

MOT test number 126038062987

Result ✓ Passed

MOT #15 2020-09-26 15:52

MOT test number 755930557594

Result X Failed

MAJOR Nearside Front Suspension arm pin or bush excessively worn (5.3.4 (a) (i))

MAJOR Offside Front Suspension arm pin or bush excessively worn (5.3.4 (a) (i))

MOT #14 2019-08-28 17:00

MOT test number 675412371765

Result ✓ Passed

MOT #13 2018-08-28 08:50

MOT test number 836823773867

Result ✓ Passed

MOT #12 2017-08-15 09:11

MOT test number 802115454693

Result ✓ Passed

MOT #11 2016-08-23 11:04

MOT test number 447340546191

Result
✓ Passed

CarCheck.co.uk page 4/12



report date: 2024-03-28

MOT #10	2016-08-23 09:44
MOT test number	475801363489
Result	X Failed
Fail Nearside Windscreen wiper does not clear the windscreen effectively (8.2.2)	
Fail Rear Brake pad(s) less than 1.5 mm thick (3.5.1g)	
Fail Offside Windscreen wiper does not clear the windscreen effectively (8.2.2)	

MOT #9	2015-04-23 11:54
MOT test number	236053215478
Result	✓ Passed
MOT #8	2015-04-23 10:58
MOT test number	815183715115
Result	X Failed
Fail Offside Front Anti-roll bar linkage fractured (2.4.G.1)	

MOT #7	2014-04-11 14:42
MOT test number	617981704171
Result	✓ Passed
MOT #6	2013-09-17 09:37
MOT test number	396830663280
Result	✓ Passed
MOT #5	2012-09-17 12:19
MOT test number	409651462278
Result	✓ Passed

CarCheck.co.uk page 5/12



report date: 2024-03-28

MOT #4	2011-09-13 10:34
MOT test number	118046951225
Result	✓ Passed
MOT #3	2010-08-24 11:46
MOT test number	391196230277
Result	✓ Passed
MOT #2	2009-09-09 16:30
MOT test number	300812659451
Result	✓ Passed
MOT #1	2009-06-26 16:13
MOT test number	652117579179
Result	✓ Passed

CarCheck.co.uk page 6/12



report date: 2024-03-28

Tax & MOT check



Tax expired: 15 February 2024

X MOT

Expired: 2 March 2024

Tax status	Expired at 15 February 2024
Days left	74 days too late
MOT expiry date	2 March 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	Н
Single payment (12 months)	£ 290,00,-
Single six month payment	£ 159,50,-
Total payable by 12 monthly instalments	£ 304,50,-

CarCheck.co.uk page 7/12



report date: 2024-03-28

Damage history

Check the damage history for this MAZDA. See if, where and when this MAZDA had damage and the car repair costs. We also check if this MAZDA was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	
Category	
Туре	
Damage 2	
Date	
Category	
Туре	



Extra MAZDA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 8/12



report date: 2024-03-28

Owner history

For how long did the current and previous owner(s) have this MAZDA? How many owners have? Check it in the premium report and see all owner registrations. Download the full report and see all owner registrations.	

	More info >
Plate changes	
See in this check if this MAZDA had different number plates.	
Number of plates	
Current registration	UK UK
Plate since	
Current registration	UK UK
Plate since	
	More info >

CarCheck.co.uk page 9/12



report date: 2024-03-28

Finance check

Check if this MAZDA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MAZDA has been settled.

If not, and you buy this MAZDA then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this MAZDA is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

Contact info

More info >

CarCheck.co.uk page 10/12



report date: 2024-03-28

Mileage check

Odometer	In miles
Mileage registrations	22
First mileage registration	2006-06-30
Last registration	2023-03-03
Complete history	See info



Registration #1	2006-06-30	21 mi
Registration #2	2009-06-26	15.228 mi
Registration #3	2009-09-09	15.726 mi
Registration #4	2010-08-24	20.282 mi
Registration #5	2011-09-13	24.104 mi
Registration #6	2012-09-17	27.179 mi
Registration #7	2013-09-17	30.362 mi
Registration #8	2014-04-11	37.767 mi
Registration #9	2015-04-23	45.825 mi
Registration #10	2015-04-23	45.825 mi
Registration #11	2016-08-23	53.145 mi
Registration #12		77,777 46
Registration #13		71.777 66
Registration #14		77,777 46
Registration #15		71.777 66
Registration #16		11.777 es
Registration #17		11.777 es
Registration #18		71.777 es
Registration #19		11.777 es
Registration #20		71.777 46
Registration #21		11.777 es
Registration #22		71.777 66

More info >

CarCheck.co.uk page 11/12



report date: 2024-03-28

Safety ratings

NCAP rating	****
Video	see crash video



Dimensions & weight

Width	1680 mm
Height	1225 mm
Length	3975 mm
Wheel base	2265 mm
Max. allowed weight	1365 kg

Additional information

Fuel tank capacity	50 I
Fuel delivery	Multi-Point Injection
Number of doors	2
Number of seats	2
Number of axles	2
Engine number	L8322559

CarCheck.co.uk page 12/12