





report date: 2024-03-28

General information

Make	VOLKSWAGEN
Model	GOLF SE TDI
Colour	Silver
Year of manufacture	2009
Top speed	118 mph
0 - 60 mph	10.7 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	110 BHP
Max. torque	250 Nm at 1.750 rpm
Engine capacity	1.968 cc
Cylinders	4
Fuel type	Diesel
Consumption city	44.1 mpg
Consumption extra urban	70.6 mpg
Consumption combined	57.7 mpg
CO2 emission	128 g/km
CO2 label	D



CarCheck.co.uk page 1/12



Internet history

Entry 1


Date 2021-06-12

Pictures 9

Listing price <u>View report</u>









source: autotrader.co.uk

CarCheck.co.uk page 2/12



MOT history

MOT expiry date	2024-11-09
MOT pass rate	86 %
MOT passed	12
Failed MOT tests	2
Total advice items	13
Total items failed	5

MOT #14		2023-11-10 14:27
MOT test		695434912340
Result		✓ Passed
Next exp	iry date	2024-11-09
Minor ingress o	Offside Front Track rod end ball joint dust cover damaged or deteriorated, f dirt (2.1.3 (g) (i))	but preventing the
Minor	Offside Front Drive shaft joint constant velocity boot severely deteriorated	(6.1.7 (g) (i))
Advice	Advice Rear Sub-frame corroded but not seriously weakened all over (5.3.3 (b) (i))	
Minor	Offside Front Suspension component ball joint dust cover severely deterior	rated (5.3.4 (b) (i))
Advice Nearside Front Outer Suspension component pin or bush slightly worn wishbone push (5.3.4 (a) (i))		

MOT #13		2022-11-07 14:25
MOT test	number	365954328694
Result		✓ Passed
Advice	Under trays fitted	
Minor	Window excessively tinted but not adversely affecting driver's view all (3.2 (b) (i))	

CarCheck.co.uk page 3/12



MOT #12 2022-11-07 12:11

MOT test number 731835939978

Result X Failed

Fail Offside Rear Tyre has ply or cords exposed (5.2.3 (d) (ii))

Advice Nearside Rear Inner Tyre worn close to legal limit/worn on edge edge worn (5.2.3 (e))

Advice Under trays fitted

Minor Window excessively tinted but not adversely affecting driver's view all (3.2 (b) (i))

MOT #11 2021-11-02 09:54

MOT test number 373903122903

Result \sqrt{Passed}

Advice Under trays fitted

MOT #10 2020-10-24 10:05

MOT test number 212649132813

Result ✓ Passed

MOT #9 2019-05-08 12:25

MOT test number 436351069467

Result ✓ Passed

MOT #8 2018-05-08 16:43

MOT test number 536136245777

MOT #7 2017-04-21 15:30

MOT test number 631794560012

CarCheck.co.uk page 4/12



KV59DDA

report date: 2024-03-28

MOT #6	2016-05-10 08:26
--------	------------------

MOT test number 911252460273

Result ✓ Passed

MOT #5 2015-09-07 12:42

MOT test number 931117514857

Result ✓ Passed

MOT #4 2014-09-05 16:29

MOT test number 819528644209

Result ✓ Passed

MOT #3 2014-09-05 15:13

MOT test number 189268744225

Result X Failed

Fail Offside Front position lamp(s) not working (1.1.A.3b)

Fail Offside Windscreen wiper does not clear the windscreen effectively (8.2.2)

Fail Offside Headlamp aim too high (1.8)

Fail Nearside Windscreen wiper does not clear the windscreen effectively (8.2.2)

MOT #2 2013-09-06 16:30

MOT test number 438499543245

Advice Offside Front Tyre worn close to the legal limit (4.1.E.1)

MOT #1 2012-09-07 14:53

MOT test number 578461652288

Result

Passed

Notice Engine lamp on

CarCheck.co.uk page 5/12





Tax & MOT check



Tax status	Valid until 1 June
Days left	33
MOT expiry date	9 November 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	D
Single payment (12 months)	£ 150,00,-
Single six month payment	£ 82,50,-
Total payable by 12 monthly instalments	£ 157,50,-

CarCheck.co.uk page 6/12



Damage history


Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report here for the results.

Damage 1

Date	
Category	
Туре	
Damage 2	
Date	

Category

Type



Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 7/12



Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 8/12



Owner history	
For how long did the current and previous owner(s) have this VOLKSWAGEN? How many VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Dow here.	

	More info >
Plate changes	
See in this check if this VOLKSWAGEN had different number plates.	
Number of plates	,
Current registration	NK NK
Plate since	
Current registration	NK NY
Plate since	
	More info >

CarCheck.co.uk page 9/12



Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this VOLKSWAGEN is financed.

Finance company Date of agreement Agreement type Agreement term **Agreement number**

Contact info

More info >

CarCheck.co.uk page 10/12



Mileage check

Odometer	In miles
Mileage registrations	16
First mileage registration	2009-09-07
Last registration	2023-11-10
Complete history	See info



Registration #1	2009-09-07	14 mi
Registration #2	2012-09-07	21.738 mi
Registration #3	2013-09-06	31.565 mi
Registration #4	2014-09-05	41.069 mi
Registration #5	2014-09-05	41.069 mi
Registration #6	2015-09-07	51.583 mi
Registration #7	2016-05-10	56.433 mi
Registration #8	2017-04-21	67.842 mi
Registration #9		9.777 es
Registration #10		11.777 es
Registration #11		9.777 es
Registration #12		11.777 es
Registration #13		9.777 es
Registration #14		11.777 es
Registration #15		11.777 es
Registration #16		n.m.

More info >

CarCheck.co.uk page 11/12





report date: 2024-03-28

Car features

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

Safety ratings

NCAP rating	***
Adult	97%
Children	84%
Pedestrian	61%
Safety systems	71%
Overall rating	85%
Video	see crash video



Dimensions & weight

Width	1786 mm
Height	1479 mm
Length	4199 mm
Wheel base	2578 mm
Kerb weight	1266 kg
Max. allowed weight	1870 kg

Additional information

Fuel tank capacity	55 I
Fuel delivery	Direct Injection
Number of doors	3
CarChack caluk	nago 12/1

CarCheck.co.uk page 12/12

Number of seats	5
Number of axles	2
Engine number	CBD 106784