



report date: 2024-03-29

General information

Make	VOLKSWAGEN
Model	TOURAN SE TDI 105
Colour	Silver
Year of manufacture	2009
Top speed	110 mph
0 - 60 mph	13.5 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	103 BHP
Max. torque	250 Nm at 1.900 rpm
Engine capacity	1.896 cc
Cylinders	4
Fuel type	Diesel
Consumption city	37.7 mpg
Consumption extra urban	53.3 mpg
Consumption combined	47.1 mpg
CO2 emission	156 g/km
CO2 label	G






Internet history

Entry 2

Date	2023-12-13
Pictures	8



source: g3remarketing.co.uk

Entry 1

Date	2021-09-30
Pictures	6
Listing price	<a href="#">View report</a>



source: autotrader.co.uk



MOT history

MOT expiry date	2025-03-05
MOT pass rate	74 %
MOT passed	14
Failed MOT tests	5
Total advice items	39
Total items failed	8

MOT #19	2024-03-06 08:48
MOT test number	339441385813
Result	✓ Passed
Next expiry date	2025-03-05
Advice	Central Upper Stop lamp(s) non-obligatory stop lamp not working (4.3.1 (a) (ii))
Advice	Offside Rear Child Seat fitted not allowing full inspection of adult belt
Minor	Offside Front Lower Suspension arm ball joint dust cover severely deteriorated (5.3.4 (b) (i))
Advice	Nearside Rear Child Seat fitted not allowing full inspection of adult belt

**MOT #18**

2024-02-23 11:54

**MOT test number**

249442376591

**Result****✗ Failed**

- Minor** Offside Front Lower Suspension arm ball joint dust cover severely deteriorated (5.3.4 (b) (i))
- Advice** Nearside Rear Child Seat fitted not allowing full inspection of adult belt
- Fail** Nearside Front Position lamp not working (4.2.1 (a) (ii))
- Advice** Items removed from driver's view prior to test
- Fail** Offside Front Upper Anti-roll bar linkage ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))
- Advice** Central Upper Stop lamp(s) non-obligatory stop lamp not working (4.3.1 (a) (ii))
- Advice** Offside Rear Child Seat fitted not allowing full inspection of adult belt
- Fail** Offside Rear Anti-roll bar linkage ball joint excessively worn (5.3.4 (a) (i))
- Fail** Nearside Front Upper Anti-roll bar linkage ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))

**MOT #17**

2023-02-25 12:50

**MOT test number**

673159245138

**Result****✓ Passed**

- Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Minor** Front Windscreen wiper blade defective (3.4 (b) (i))
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))

**MOT #16** 2022-02-28 17:27**MOT test number** 274198571497**Result** ✓ Passed**MOT #15** 2021-11-15 12:14**MOT test number** 691887114199**Result** ✓ Passed**MOT #14** 2021-11-10 15:53**MOT test number** 597652207223**Result** ✗ Failed

**Fail** Nearside Front Suspension arm pin or bush excessively worn Wishbone Front + Rear Bush (5.3.4 (a) (i))

**MOT #13** 2021-10-05 14:31**MOT test number** 646012968888**Result** ✗ Failed

**Fail** Nearside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))

**MOT #12** 2020-11-10 17:35**MOT test number** 897263037869**Result** ✓ Passed**MOT #11** 2019-10-30 16:00**MOT test number** 983312729648**Result** ✓ Passed

**Advice** Nearside Rear Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**Advice** Offside Rear Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**MOT #10** 2018-10-25 11:32**MOT test number** 689929475357**Result** ✓ Passed**Advice** Nearside Rear Child Seat fitted not allowing full inspection of adult belt**MOT #9** 2018-10-24 12:29**MOT test number** 963531660786**Result** ✗ Failed**Advice** Nearside Rear Child Seat fitted not allowing full inspection of adult belt**Fail** Nearside Rear Coil spring fractured or broken (5.3.1 (b) (i))**MOT #8** 2017-10-11 10:52**MOT test number** 250513263737**Result** ✓ Passed**Advice** Offside Rear Shocker cover loose due to bump stop deteriorated**Advice** Nearside Child Seat fitted not allowing full inspection of adult belt 2nd row of seats**Advice** Front registration plate deteriorated but not likely to be misread (6.3.1d)**Advice** Nearside Rear Shocker cover loose due to bump stop deteriorated**Advice** Nearside Front Outer Tyre wall has cuts in it**Advice** Offside Child Seat fitted not allowing full inspection of adult belt 2nd row of seats**MOT #7** 2016-10-03 09:52**MOT test number** 992632874673**Result** ✓ Passed

**MOT #6** 2016-04-18 08:19**MOT test number** 758659849122**Result** ✓ Passed

- Advice** Offside Rear tyre bald inner edge + nail in tread
- Advice** Steering light + engine managment light on but dim
- Advice** Nearside Rear tyre low inner edge + two nails in tread
- Advice** Rear seats folded / covered, so cant check seats or belts

**MOT #5** 2015-04-09 11:04**MOT test number** 567579195020**Result** ✓ Passed

- Notice** Passenger seat(s) missing at time of test

**MOT #4** 2014-04-17 10:56**MOT test number** 896917004161**Result** ✓ Passed

- Notice** Passenger seat(s) missing at time of test
- Notice** Under-trays fitted obscuring some underside components

**MOT #3** 2013-04-04 14:34**MOT test number** 497314393056**Result** ✓ Passed

- Notice** Offside front headlamp has a damaged fixing point but head lamp is still secure
- Notice** Engine covers fitted obscuring some components in the engine bay
- Notice** Under-trays fitted obscuring some underside components



MOT #2	2013-04-04 14:34
MOT test number	778314493091
Result	✗ Failed
Notice	Offside front headlamp has a damaged fixing point but head lamp is still secure
Notice	Engine covers fitted obscuring some components in the engine bay
Pass with rectification	Nearside Registration plate lamp not working (1.1.C.1d)
Notice	Under-trays fitted obscuring some underside components

MOT #1	2012-04-24 14:11
MOT test number	567205912162
Result	✓ Passed





Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 September 2024

✓  
**MOT**  
**Expires:**  
5 March 2025

<b>Tax status</b>	Valid until 1 September
<b>Days left</b>	124
<b>MOT expiry date</b>	5 March 2025
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	49
<b>Band</b>	G
<b>Single payment (12 months)</b>	£ 240,00,-
<b>Single six month payment</b>	£ 132,00,-
<b>Total payable by 12 monthly instalments</b>	£ 252,00,-



Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this VOLKSWAGEN had different number plates.

Number of plates	1
Current registration	 <b>FP09NVK</b>
Plate since	2024-03-29
Current registration	 <b>FP09NVK</b>
Plate since	2024-03-29

More info >



Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLKSWAGEN is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	20
First mileage registration	2009-06-24
Last registration	2024-03-06
Complete history	<a href="#">See info</a>



Registration #1	2009-06-24	18 mi
Registration #2	2012-04-24	29.919 mi
Registration #3	2013-04-04	41.165 mi
Registration #4	2014-04-17	50.893 mi
Registration #5	2015-04-09	60.237 mi
Registration #6	2016-04-18	70.050 mi
Registration #7	2016-10-03	74.760 mi
Registration #8	2017-10-11	80.255 mi
Registration #9	2018-10-24	85.377 mi
Registration #10	2018-10-25	85.378 mi
Registration #11	2019-05-20	95.377 mi
Registration #12	2019-05-20	95.377 mi
Registration #13	2019-05-20	95.377 mi
Registration #14	2019-05-20	95.377 mi
Registration #15	2019-05-20	95.377 mi
Registration #16	2019-05-20	95.377 mi
Registration #17	2019-05-20	95.377 mi
Registration #18	2019-05-20	95.377 mi
Registration #19	2019-05-20	95.377 mi
Registration #20	2019-05-20	95.377 mi

More info >



Car features

The VOLKSWAGEN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLKSWAGEN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	2066 mm
Height	1635 mm
Length	4391 mm
Wheel base	2677 mm
Kerb weight	1539 kg
Max. allowed weight	2210 kg

Additional information

Fuel tank capacity	60 l
Fuel delivery	Direct Injection
Number of doors	5

Number of seats	7
Engine number	BXE0C36215