




report date: 2024-03-28

General information

Make	CITROEN
Model	XSARA EXCLUSIVE 16V PICASSO E4
Colour	Silver
Year of manufacture	2006
Top speed	119 mph
Gearbox	4 speed automatic

Engine & fuel consumption

Power	134 BHP
Max. torque	191 Nm at 4.100 rpm
Engine capacity	1.997 cc
Cylinders	4
Fuel type	Petrol
Consumption city	22.6 mpg
Consumption extra urban	44.1 mpg
Consumption combined	32.8 mpg
CO2 emission	205 g/km
CO2 label	K






Internet history

Entry 1

Date	2021-05-24
Pictures	16
Listing price	View report



source: [autotrader.co.uk](https://www.autotrader.co.uk)



MOT history

MOT expiry date	2024-11-10
MOT pass rate	84 %
MOT passed	16
Failed MOT tests	3
Total advice items	29
Total items failed	2

MOT #19 2023-11-06 10:10

MOT test number 966175074012

Result ✓ Passed

Next expiry date 2024-11-10

- Advice** Offside Front Anti-roll bar ball joint has slight play (5.3.4 (a) (i))
- Advice** Towball/hitch not fitted at time of test
- Advice** Nearside Front Anti-roll bar ball joint has slight play (5.3.4 (a) (i))
- Advice** Offside Front Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Offside Rear Service brake binding but not excessively (1.2.1 (f))

MOT #18 2022-11-08 09:48

MOT test number 593112416150

Result ✓ Passed

- Advice** Rear Exhaust mounting defective (6.1.2 (a))
- Advice** Nearside Rear Tyre worn close to legal limit/worn on edge 3mm only worn on outside edge, nail in tyre (5.2.3 (e))
- Advice** Offside Front Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))
- Advice** Nearside Front Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))

**MOT #17**

2021-11-11 11:46

MOT test number

788422001646

Result

✓ Passed

Advice

Rear exhaust in poor condition

Advice

Front and rear suspension components corroded

MOT #16

2020-11-04 14:21

MOT test number

903381095859

Result

✓ Passed

Advice

Rear Exhaust has a minor leak of exhaust gases (6.1.2 (a))

Advice

Rear Anti-roll bar corroded but not seriously weakened (5.3.3 (b) (i))

Advice

Front and rear components corroded

MOT #15

2019-05-10 12:46

MOT test number

429619618664

Result

✓ Passed

Advice

Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

Advice

Nearside Front Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #14

2019-05-09 16:17

MOT test number

680383116619

Result

✗ Failed

MAJOR

Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))

Advice

Nearside Front Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice

Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))



MOT #13	2018-05-11 15:01
----------------	------------------

MOT test number	982447409214
------------------------	--------------

Result	✓ Passed
---------------	----------

MOT #12	2017-05-11 12:32
----------------	------------------

MOT test number	762520239514
------------------------	--------------

Result	✓ Passed
---------------	----------

MOT #11	2016-05-31 12:08
----------------	------------------

MOT test number	775201602082
------------------------	--------------

Result	✓ Passed
---------------	----------

MOT #10	2015-05-21 11:01
----------------	------------------

MOT test number	108371145125
------------------------	--------------

Result	✓ Passed
---------------	----------

Notice	Child seat fitted not allowing full inspection of adult belt
---------------	--------------------------------------------------------------

Notice	Tow ball/hitch not fitted at time of test
---------------	-------------------------------------------

MOT #9	2014-06-17 11:57
---------------	------------------

MOT test number	617798564184
------------------------	--------------

Result	✓ Passed
---------------	----------

MOT #8	2013-10-14 11:20
---------------	------------------

MOT test number	317687583433
------------------------	--------------

Result	✓ Passed
---------------	----------

Notice	REAR TYRES WEARING THIN
---------------	-------------------------

**MOT #7** 2012-10-09 10:34**MOT test number** 656713582232**Result** ✓ Passed**Advice** Offside Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Advice** Nearside Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**MOT #6** 2011-10-07 11:19**MOT test number** 378220181426**Result** ✓ Passed**Notice** REAR BRAKE DISCS RUSTY IN POOR CONDITION OSF TYRE WEARING ON INNER EDGE!!!**MOT #5** 2010-10-12 10:54**MOT test number** 712675280217**Result** ✓ Passed**MOT #4** 2009-10-16 17:05**MOT test number** 751159089258**Result** ✓ Passed**MOT #3** 2009-10-16 15:56**MOT test number** 323109589444**Result** ✗ Failed**Fail** Nearside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1)**MOT #2** 2009-03-12 12:05**MOT test number** 624071979010**Result** ✓ Passed**Advice** Power steering pump has slight seepage from a component (2.3.3b)**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)



MOT #12009-03-12 12:05

MOT test number920321779022

Result

Failed

Advice

Power steering pump has slight seepage from a component (2.3.3b)

Pass with rectification

Power steering pipe(s) or hose(s) leaking (2.3.3b)

Advice

Nearside Rear Tyre worn close to the legal limit (4.1.E.1)



Tax & MOT check

✓
Taxed
Tax due:
1 January 2025

✓
MOT
Expires:
10 November 2024

Tax status	Valid until 1 January
Days left	247
MOT expiry date	10 November 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	K
Single payment (12 months)	£ 395,00,-
Single six month payment	£ 217,25,-
Total payable by 12 monthly instalments	£ 414,75,-



Damage history


Check the damage history for this CITROEN. See if, where and when this CITROEN had damage and the car repair costs. We also check if this CITROEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra CITROEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this CITROEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 15,200
Auction value	£ 15,200
Average private trade value	£ 15,200

More info >



Owner history

For how long did the current and previous owner(s) have this CITROEN? How many owners did this CITROEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this CITROEN had different number plates.

Number of plates	1
Current registration	*****
Plate since	2019-06-29
Current registration	*****
Plate since	2019-06-29

More info >



Finance check

Check if this CITROEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this CITROEN has been settled.

If not, and you buy this CITROEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this CITROEN is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	20
First mileage registration	2006-03-22
Last registration	2023-11-06
Complete history	See info



Registration #1	2006-03-22	11 mi
Registration #2	2009-03-12	27.638 mi
Registration #3	2009-10-16	32.607 mi
Registration #4	2009-10-16	32.607 mi
Registration #5	2010-10-12	40.277 mi
Registration #6	2011-10-07	47.749 mi
Registration #7	2012-10-09	55.944 mi
Registration #8	2013-10-14	63.220 mi
Registration #9	2014-06-17	67.046 mi
Registration #10	2015-05-21	69.860 mi
Registration #11	2016-05-20	71.277 mi
Registration #12	2017-05-20	71.277 mi
Registration #13	2018-05-20	71.277 mi
Registration #14	2019-05-20	71.277 mi
Registration #15	2020-05-20	71.277 mi
Registration #16	2021-05-20	71.277 mi
Registration #17	2022-05-20	71.277 mi
Registration #18	2023-05-20	71.277 mi
Registration #19	2024-05-20	71.277 mi
Registration #20	2025-05-20	71.277 mi

More info >



Safety ratings

NCAP rating

★ ★ ★ ★ ★

Video [see crash video](#)

Dimensions & weight

Width	1751 mm
Height	1637 mm
Length	4276 mm
Wheel base	2760 mm
Kerb weight	1245 kg
Max. allowed weight	1832 kg

Additional information

Fuel tank capacity	55 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5
Number of axles	2
Engine number	LH4G1437473