





report date: 2024-03-29

General information

Make	FORD
Model	B-MAX ZETEC
Colour	Blue
Year of manufacture	2015
Top speed	106 mph
Gearbox	5 speed Manual

Engine & fuel consumption

Power	66 kW / 90 HP / 89 BHP
Max. torque	128 Nm at 4.000 rpm
Engine capacity	1.388 сс
Cylinders	4
Fuel type	Petrol
Consumption city	35.8 mpg
Consumption extra urban	57.7 mpg
Consumption combined	47.1 mpg
CO2 emission	139 g/km
CO2 label	E



CarCheck.co.uk page 1/12



Internet history

Entry 3

Date 2021-06-28

Pictures 29

Listing price <u>View report</u>









source: heycar.co.uk

Entry 2

Date	2021-06-12	
Pictures	1	
Listing price	View report	



source: autoonline.co.uk

Entry 1

Date	2021-06-08
Pictures	0
Listing price	View report

source: autotrader.co.uk

CarCheck.co.uk page 2/12



MOT history

MOT expiry date	2024-05-24
MOT pass rate	86 %
MOT passed	6
Failed MOT tests	1
Total advice items	14
Total items failed	1

MOT #7	2023-05-24 14:11
MOT test number	106410719009
Result	✓ Passed
Next expiry date	2024-05-24

MOT #6	2023-05-24 12:20
MOT test number	168319007612
Result	X Failed
Fail Offside Stop lamp(s) not working (4.3.1 (a) (ii))	
Advice Offside Front Brake slight bind	
Advice Front Brake pad(s) wearing thin (1.1.13 (a) (ii))	

CarCheck.co.uk page 3/12



MOT #5 2022-05-25 11:18

MOT test number 314249177798

Result ✓ Passed

Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

Advice Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

Advice Offside Rear Child Seat fitted not allowing full inspection of adult belt

Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

Advice Nearside Rear Child Seat fitted not allowing full inspection of adult belt

MOT #4 2021-04-13 07:36

MOT test number 867800051900

Advice Offside rear tyre deteriorated

Advice Sill covers fitted

Advice Cuts in nearside front tyre

MOT #3 2020-04-30 13:38

MOT test number 373394732988

Result ✓ Passed

MOT #2 2019-05-03 10:50

MOT test number 754716636997

Result
✓ Passed

CarCheck.co.uk page 4/12



GY15ZDO

report date: 2024-03-29

MOT #1		2018-05-08 13:26
MOT test	number	821259544501
Result		✓ Passed
Advice	Offside Front Tyre worn close to the legal limit (4.1.E.1)	
Advice	Nearside Front Tyre worn close to the legal limit (4.1.E.1)	

CarCheck.co.uk page 5/12



Tax & MOT check



Tax status	Valid until 1 July
Days left	63
MOT expiry date	24 May 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	E
Single payment (12 months)	£ 180,00,-
Single six month payment	£ 99,00,-
Total payable by 12 monthly instalments	£ 189,00,-

CarCheck.co.uk page 6/12



Damage history

Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	
Category	
Туре	
Damage 2	
Date	
Category	



Extra FORD salvage check



Type

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 7/12



Vehicle valuation

What is this car worth? See the vehicle value of this FORD in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 8/12



Owner history

e union mestery	
For how long did the current and previous owner(s) have this FORD? How many owners of Check it in the premium report and see all owner registrations. Download the full report is	

	More info >
Plate changes See in this check if this FORD had different number plates.	
Number of plates	,
Current registration	UK UK
Plate since	
Current registration	NK NK
Plate since	
	More info >

CarCheck.co.uk page 9/12



Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this FORD is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

More info >

CarCheck.co.uk page 10/12



Mileage check

Odometer	In miles
Mileage registrations	11
First mileage registration	2015-06-30
Last registration	2023-05-24
Complete history	See info



Registration #1	2015-06-30	19 mi
Registration #2	2018-05-08	15.251 mi
Registration #3	2019-05-03	21.140 mi
Registration #4	2020-04-30	27.669 mi
Registration #5	2021-04-13	31.444 mi
Registration #6		0.00 44
Registration #7		11.777 es
Registration #8		11.777 es
Registration #9		11.777 es
Registration #10		0.07 44
Registration #11		10.777 au

More info >

CarCheck.co.uk page 11/12



Car features

S0225	Air conditionin
50295	
50482	
50501	
60566	
60567	
50569	

Safety ratings

NCAP rating	****
Adult	92%
Children	84%
Pedestrian	67%
Safety systems	71%
Overall rating	83%
Video	see crash video



Dimensions & weight

Width	2067 mm
Height	1604 mm
Length	4077 mm
Wheel base	2489 mm
Kerb weight	1760 kg
Max. allowed weight	1745 kg

Additional information

Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5
Number of axles CarCheck.co.uk	2 page 12/12