



RENAULT

SD59EW0

report date: 2024-03-29

General information

Make	RENAULT
Model	MEGANE DYNAMIQUE VVT
Colour	Blue
Year of manufacture	2009
Top speed	118 mph
0 - 60 mph	10.5 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	110 BHP
Max. torque	151 Nm at 4.250 rpm
Engine capacity	1.598 cc
Cylinders	4
Fuel type	Petrol
Consumption city	29.1 mpg
Consumption extra urban	50.4 mpg
Consumption combined	39.8 mpg
CO2 emission	162 g/km
CO2 label	G





Internet history

Entry 2

Date	2021-09-09
Pictures	12
Listing price	View report



source: cargurus.co.uk

Entry 1

Date	2021-09-08
Pictures	0
Listing price	View report

source: autotrader.co.uk



MOT history

MOT expiry date	2025-01-23
MOT pass rate	53 %
MOT passed	8
Failed MOT tests	7
Total advice items	50
Total items failed	3

MOT #15	2024-01-24 11:55
MOT test number	129026145374
Result	✓ Passed
Next expiry date	2025-01-23
Advice	Front Brake pad(s) wearing thin (1.1.13 (a) (ii))

MOT #14	2022-11-09 10:52
MOT test number	830261184395
Result	✓ Passed
Advice	Offside Rear Direction indicator slightly discoloured (4.4.3 (a))
Advice	Offside Front Road wheel slightly distorted (5.2.2 (c) (i))
Advice	Nearside Front Suspension arm ball joint has slight play (5.3.4 (a) (i))
Advice	Nearside Front Road wheel slightly distorted (5.2.2 (c) (i))
Advice	Nearside Rear Road wheel slightly distorted (5.2.2 (c) (i))

**MOT #13**

2022-11-08 12:13

MOT test number

808320054570

Result**✗ Failed**

- MAJOR** Nearside Front Position lamp not working (4.2.1 (a) (ii))
- MAJOR** Offside Front Anti-roll bar linkage ball joint excessively worn (5.3.4 (a) (i))
- Advice** Offside Front Road wheel slightly distorted (5.2.2 (c) (i))
- MAJOR** Reversing lamp inoperative (4.6.1 (a))
- MAJOR** Nearside Front Outer Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))
- MAJOR** Nearside Stop lamp(s) not working (4.3.1 (a) (ii))
- MAJOR** Offside Track rod end ball joint has excessive play (2.1.3 (b) (i))
- Advice** Offside Rear Direction indicator slightly discoloured (4.4.3 (a))
- Advice** Nearside Front Road wheel slightly distorted (5.2.2 (c) (i))
- Advice** Nearside Rear Road wheel slightly distorted (5.2.2 (c) (i))
- MAJOR** Nearside Side repeater not working (4.4.1 (a) (ii))
- Advice** Nearside Front Suspension arm ball joint has slight play (5.3.4 (a) (i))

MOT #12

2021-11-18 11:57

MOT test number

903296603361

Result**✓ Passed**

- Advice** All shocker bodies rusty
- Advice** Offside Track rod end ball joint has slight play (2.1.3 (b) (i))
- Advice** N/s/f outer c.v boot clip poor condition

**MOT #11**

2021-11-17 07:28

MOT test number

820291520096

Result**✗ Failed**

Advice Nearside Rear Tyre worn close to legal limit/worn on edge 2mm/cracking and wearing on edges (5.2.3 (e))

MAJOR Nearside Rear Position lamp not working (4.2.1 (a) (ii))

Advice All shocker bodies rusty

Advice Offside Track rod end ball joint has slight play (2.1.3 (b) (i))

DANGEROUS Offside Rear Tyre has a tear, caused by separation or partial failure of its structure (5.2.3 (d) (ii))

MAJOR Nearside Stop lamp(s) not working (4.3.1 (a) (ii))

MAJOR Windscreen washer provides insufficient washer liquid (3.5 (a))

Advice N/s/f outer c.v boot clip poor condition

MOT #10

2020-12-19 10:53

MOT test number

797240274183

Result**✓ Passed**

Advice Brake hose has slight corrosion to ferrule NSR&OSR + OSF (1.1.12 (f) (i))

Advice Tyre slightly damaged/cracking or perishing NSR&OSR cracking. (5.2.3 (d) (ii))

Advice Offside Front Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))

Advice Brake disc worn, but not excessively NSR&OSR (1.1.14 (a) (i))

Advice Shock absorbers has slight external damage to the casing All four(NSF&OSF + NSR&OSR shock absorber casing very corroded! (5.3.2 (b))

Advice Tyre worn close to legal limit/worn on edge NSR&OSR tyre very close to legal limit! And worn on outer edge too! (5.2.3 (e))

Advice Front Lower Suspension arm ball joint has slight play Both side, NSF&OSF lower arm ball joint! (5.3.4 (a) (i))

**MOT #9** 2020-12-18 16:18**MOT test number** 900867903295**Result** ✗ Failed

MAJOR Nearside Front Outer Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt No clamp! (6.1.7 (g) (ii))

Advice Front Lower Suspension arm ball joint has slight play Both side, NSF&OSF lower arm ball joint! (5.3.4 (a) (i))

Advice Tyre slightly damaged/cracking or perishing NSR&OSR cracking. (5.2.3 (d) (ii))

Advice Brake disc worn, but not excessively NSR&OSR (1.1.14 (a) (i))

Advice Shock absorbers has slight external damage to the casing All four(NSF&OSF + NSR&OSR shock absorber casing very corroded! (5.3.2 (b))

Advice Offside Front Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))

MAJOR Nearside Rear Coil spring fractured or broken Broken. (5.3.1 (b) (i))

Advice Tyre worn close to legal limit/worn on edge NSR&OSR tyre very close to legal limit! And worn on outer edge too! (5.2.3 (e))

Advice Brake hose has slight corrosion to ferrule NSR&OSR + OSF (1.1.12 (f) (i))

MOT #8 2019-06-07 11:25**MOT test number** 274109279540**Result** ✓ Passed**MOT #7** 2019-05-28 12:43**MOT test number** 122851068793**Result** ✗ Failed

DANGEROUS Nearside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))

Advice Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

MAJOR Nearside Front Anti-roll bar pin or bush excessively worn (5.3.4 (a) (i))

Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

**MOT #6** 2015-10-20 15:47**MOT test number** 642687504578**Result** ✓ Passed**MOT #5** 2015-10-20 15:47**MOT test number** 448170513823**Result** ✗ Failed**Pass with rectification** Offside Outer Front position lamp(s) not working (1.1.A.3b)**MOT #4** 2013-09-30 13:54**MOT test number** 266693873259**Result** ✓ Passed**MOT #3** 2013-09-30 13:54**MOT test number** 967933573248**Result** ✗ Failed**Pass with rectification** Nearside Outer Front Front constant velocity joint is insecure (2.5.C.1b)**MOT #2** 2012-09-25 14:49**MOT test number** 768589962200**Result** ✓ Passed**MOT #1** 2012-09-25 14:49**MOT test number** 808599562246**Result** ✗ Failed**Pass with rectification** Offside Headlamp aim too low (1.8)



Tax & MOT check

✓
Taxed
Tax due:
1 January 2025

✓
MOT
Expires:
23 January 2025

Tax status	Valid until 1 January
Days left	246
MOT expiry date	23 January 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	G
Single payment (12 months)	£ 240,00,-
Single six month payment	£ 132,00,-
Total payable by 12 monthly instalments	£ 252,00,-



Damage history

Check the damage history for this RENAULT. See if, where and when this RENAULT had damage and the car repair costs. We also check if this RENAULT was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra RENAULT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this RENAULT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this RENAULT? How many owners did this RENAULT have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this RENAULT had different number plates.

Number of plates	1
Current registration	SD59EWO
Plate since	2019-03-29
Current registration	SD59EWO
Plate since	2019-03-29

More info >



Finance check

Check if this RENAULT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this RENAULT has been settled.

If not, and you buy this RENAULT then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this RENAULT is financed.

Finance company	RENAULT	2024
Date of agreement	RENAULT	2024
Agreement type	RENAULT	2024
Agreement term	RENAULT	2024
Agreement number	RENAULT	2024
Contact info	RENAULT	2024

More info >



Mileage check

Odometer	In miles
Mileage registrations	16
First mileage registration	2009-10-01
Last registration	2024-01-24
Complete history	See info



Registration #1	2009-10-01	29 mi
Registration #2	2012-09-25	40.823 mi
Registration #3	2013-09-30	44.781 mi
Registration #4	2015-10-20	45.725 mi
Registration #5	2015-10-20	45.725 mi
Registration #6	2019-05-28	55.393 mi
Registration #7	2019-06-07	55.394 mi
Registration #8	2020-12-18	68.161 mi
Registration #9	2020-12-18	68.161 mi
Registration #10	2020-12-18	68.161 mi
Registration #11	2020-12-18	68.161 mi
Registration #12	2020-12-18	68.161 mi
Registration #13	2020-12-18	68.161 mi
Registration #14	2020-12-18	68.161 mi
Registration #15	2020-12-18	68.161 mi
Registration #16	2020-12-18	68.161 mi

More info >



Car features

The RENAULT factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete RENAULT factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	2037 mm
Height	1423 mm
Length	4299 mm
Wheel base	2640 mm
Kerb weight	1205 kg
Max. allowed weight	1728 kg

Additional information

Fuel tank capacity	60 l
Fuel delivery	Multi-Point Injection
Number of doors	3
Number of seats	5

Engine number	D043269
---------------	---------