



HONDA




report date: 2024-10-31

General information

Make	HONDA
Model	JAZZ DSI S
Colour	Blue
Year of manufacture	2009
Top speed	106 mph
Gearbox	5 speed Manual

Engine & fuel consumption

Power	76 BHP
Max. torque	110 Nm at 2.800 rpm
Engine capacity	1.246 cc
Cylinders	4
Fuel type	Petrol
Consumption city	41.5 mpg
Consumption extra urban	60.1 mpg
Consumption combined	51.4 mpg
CO2 emission	129 g/km
CO2 label	D





MOT history

MOT expiry date	2024-12-13
MOT pass rate	86 %
MOT passed	12
Failed MOT tests	2
Total advice items	17
Total items failed	2

**MOT #14** 2023-12-14 09:08

**MOT test number** 990396959720

**Result** ✓ Passed

**Next expiry date** 2024-12-13

**Advice** Offside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))

**MOT #13** 2022-11-23 10:58

**MOT test number** 935429950060

**Result** ✓ Passed

**Advice** Offside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))

**Advice** Rear Brake hose has slight corrosion to ferrule (1.1.12 (f) (i))

**Minor** Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

**MOT #12** 2021-12-05 11:04

**MOT test number** 408183743862

**Result** ✓ Passed

**Minor** Offside Front Headlamp lens slightly defective (4.1.1 (b) (i))

**Minor** Nearside Front Headlamp lens slightly defective (4.1.1 (b) (i))



**MOT #11** 2020-11-21 12:04

**MOT test number** 333936133871

**Result** ✓ Passed

- Advice** Nearside Front Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))
- Advice** Front Lower Suspension arm pin or bush worn but not resulting in excessive movement both sides (5.3.4 (a) (i))

**MOT #10** 2019-04-25 15:25

**MOT test number** 280642334701

**Result** ✓ Passed

- Minor** Offside Rear Rear reflector defective or damaged by up to 50% of the reflecting surface (4.8.1 (a) (i))

**MOT #9** 2018-02-09 09:48

**MOT test number** 686526479519

**Result** ✓ Passed

- Advice** Central Rear Upper high level brake light not working
- Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)

**MOT #8** 2018-02-08 14:37

**MOT test number** 422989154963

**Result** ✗ Failed

- Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)
- Fail** Offside Front Inner Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (4.1.D.1a)
- Advice** Central Rear Upper high level brake light not working

**MOT #7** 2017-02-06 15:26

**MOT test number** 385343771593

**Result** ✓ Passed

- Advice** Nearside Front Outer Tyre worn close to the legal limit (4.1.E.1)



<b>MOT #6</b>	2017-02-06 15:26
<b>MOT test number</b>	668712370011
<b>Result</b>	✗ Failed
<b>Advice</b>	Nearside Front Outer Tyre worn close to the legal limit (4.1.E.1)
<b>Pass with rectification</b>	Windscreen washer provides insufficient washer liquid (8.2.3)

<b>MOT #5</b>	2016-01-29 10:05
<b>MOT test number</b>	597520973849
<b>Result</b>	✓ Passed

<b>MOT #4</b>	2015-01-27 11:50
<b>MOT test number</b>	838297625046
<b>Result</b>	✓ Passed
<b>Advice</b>	Offside Front Tyre worn close to the legal limit (4.1.E.1)
<b>Advice</b>	Nearside Front Tyre worn close to the legal limit (4.1.E.1)

<b>MOT #3</b>	2014-01-22 12:03
<b>MOT test number</b>	579542824071
<b>Result</b>	✓ Passed

<b>MOT #2</b>	2013-01-14 11:24
<b>MOT test number</b>	135844613438
<b>Result</b>	✓ Passed

<b>MOT #1</b>	2012-01-12 16:28
<b>MOT test number</b>	762383051809
<b>Result</b>	✓ Passed



Tax & MOT check

✓  
**Taxed**

**Tax due:**  
1 September 2025

✓  
**MOT**

**Expires:**  
13 December 2024

**Tax status** Valid until 1 September

**Days left** 295

**MOT expiry date** 13 December 2024

**Full MOT history** [See MOT history](#)

Tax calculation

<b>Vehicle class</b>	48
<b>Band</b>	D
<b>Single payment (12 months)</b>	£ 150,00,-
<b>Single six month payment</b>	£ 82,50,-
<b>Total payable by 12 monthly instalments</b>	£ 157,50,-




Damage history

Check the damage history for this HONDA. See if, where and when this HONDA had damage and the car repair costs. We also check if this HONDA was scrapped. Download the premium report [here](#) for the results.


Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra HONDA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



**Vehicle valuation**

What is this car worth? See the vehicle value of this HONDA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

<b>Trade retail value</b>	£ 19,999
<b>Auction value</b>	£ 19,999
<b>Average private trade value</b>	£ 19,999

[More info >](#)



Owner history

For how long did the current and previous owner(s) have this HONDA? How many owners did this HONDA have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Start	End
Owner	Start	End
Owner	Start	End
Owner	Start	End
Owner	Start	End
Owner	Start	End
Owner	Start	End

More info >

Plate changes

See in this check if this HONDA had different number plates.

Number of plates	1
Current registration	<b>RA58AWC</b>
Plate since	2024-10-31
Current registration	<b>RA58AWC</b>
Plate since	2024-10-31

More info >





**Finance check**

Check if this HONDA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this HONDA has been settled. If not, and you buy this HONDA then you could lose the money and the car you paid for. Download the premium report [here](#) and check if this HONDA is financed.


<b>Finance company</b>	REDACTED
<b>Date of agreement</b>	REDACTED
<b>Agreement type</b>	REDACTED
<b>Agreement term</b>	REDACTED
<b>Agreement number</b>	REDACTED
<b>Contact info</b>	REDACTED

**More info** >



Mileage check

<b>Odometer</b>	In miles
<b>Mileage registrations</b>	15
<b>First mileage registration</b>	2009-01-29
<b>Last registration</b>	2023-12-14
<b>Complete history</b>	<a href="#">See info</a>



<b>Registration #1</b>	2009-01-29	7 mi
<b>Registration #2</b>	2012-01-12	13.218 mi
<b>Registration #3</b>	2013-01-14	18.631 mi
<b>Registration #4</b>	2014-01-22	24.457 mi
<b>Registration #5</b>	2015-01-27	29.688 mi
<b>Registration #6</b>	2016-01-29	34.936 mi
<b>Registration #7</b>	2017-02-06	48.276 mi
<b>Registration #8</b>	2017-02-06	48.276 mi
<b>Registration #9</b>	2019-05-01	55.277 mi
<b>Registration #10</b>	2019-05-01	55.277 mi
<b>Registration #11</b>	2019-05-01	55.277 mi
<b>Registration #12</b>	2019-05-01	55.277 mi
<b>Registration #13</b>	2019-05-01	55.277 mi
<b>Registration #14</b>	2019-05-01	55.277 mi
<b>Registration #15</b>	2019-05-01	55.277 mi

[More info >](#)



Safety ratings

NCAP rating ★★★★☆  
Video [see crash video](#)



Dimensions & weight

Width	1675 mm
Height	1525 mm
Length	3845 mm
Wheel base	2450 mm
Kerb weight	1086 kg
Max. allowed weight	1490 kg

Additional information

Fuel tank capacity	42 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5
Number of axles	2
Engine number	L12A17002423