




report date: 2024-03-29

General information

Make	VAUXHALL
Model	COMBO L2H1 2300 SPORTIVE CDTI S/S
Colour	White
Year of manufacture	2017
Gearbox	6 speed Manual

Engine & fuel consumption

Power	104 BHP
Engine capacity	1.598 cc
Cylinders	4
Fuel type	Diesel
Consumption city	43.5 mpg
Consumption extra urban	61.4 mpg
Consumption combined	53.3 mpg
CO2 emission	125 g/km
CO2 label	D





Internet history

Entry 2

Date	2021-09-08
Pictures	21
Listing price	View report



source: heycar.co.uk

Entry 1

Date	2021-09-04
Pictures	21
Listing price	View report



source: cargurus.co.uk



MOT history

MOT expiry date	2024-09-30
MOT pass rate	83 %
MOT passed	5
Failed MOT tests	1
Total advice items	12
Total items failed	1

MOT #6 2023-09-01 10:46

MOT test number 677917400652

Result ✓ Passed

Next expiry date 2024-09-30

Advice Nearside Rear Nail in tyre

Minor Offside Front Outer Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))

Minor Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))

MOT #5 2022-09-02 09:49

MOT test number 333253958791

Result ✓ Passed

Minor Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))

MOT #4 2021-10-01 08:57

MOT test number 687301252961

Result ✓ Passed

Advice Nearside Rear Tyre slightly damaged on outer wall (5.2.3 (d) (ii))

Minor Offside Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))

**MOT #3** 2021-09-30 14:49**MOT test number** 511990933532**Result** ✗ Failed**Fail** Offside Front Coil spring fractured or broken (5.3.1 (b) (i))**Minor** Offside Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))**Advice** Nearside Rear Tyre slightly damaged on outer wall (5.2.3 (d) (ii))**MOT #2** 2020-08-22 10:25**MOT test number** 483105276170**Result** ✓ Passed**Advice** Nearside Tyre has a cut but not deep enough to reach the ply or cords *2 (5.2.3 (d) (i))**Minor** Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #1** 2020-07-04 05:05**MOT test number** 854513811314**Result** ✓ Passed**Advice** COVID-19 6 MONTH EXTENSION



Tax & MOT check

✓
Taxed
Tax due:
1 October 2024

✓
MOT
Expires:
30 September 2024

Tax status	Valid until 1 October
Days left	155
MOT expiry date	30 September 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	39
Standard rate (12 months)	£ 320,00,-
Standard rate (6 months)	£ 176,00,-



Damage history

Check the damage history for this VAUXHALL. See if, where and when this VAUXHALL had damage and the car repair costs. We also check if this VAUXHALL was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra VAUXHALL salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VAUXHALL in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VAUXHALL? How many owners did this VAUXHALL have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

XXXXXXXXXX	XXXXXXXXXX
XXXXXXXXXXXXXX	XXXXXXXXXX
XXXXXXXXXX	XXXXXXXXXX
XXXXXXXXXX	XXXXXXXXXX
XXXXXXXXXXXXXX	XXXXXXXXXX
XXXXXXXXXX	XXXXXXXXXX

More info >

Plate changes

See in this check if this VAUXHALL had different number plates.

Number of plates	1
Current registration	 FD17JZC
Plate since	2024-03-29
Current registration	 FD17JZC
Plate since	2024-03-29

More info >



Finance check

Check if this VAUXHALL is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VAUXHALL has been settled.

If not, and you buy this VAUXHALL then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VAUXHALL is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	8
First mileage registration	2017-07-12
Last registration	2023-09-01
Complete history	See info



Registration #1	2017-07-12	9 mi
Registration #2	2020-08-22	21.818 mi
Registration #3	2023-09-01	21.818 mi
Registration #4	2023-09-01	21.818 mi
Registration #5	2023-09-01	21.818 mi
Registration #6	2023-09-01	21.818 mi
Registration #7	2023-09-01	21.818 mi
Registration #8	2023-09-01	21.818 mi

More info >



Dimensions & weight

Width	2119 mm
Height	1880 mm
Length	4740 mm
Kerb weight	1535 kg
Max. allowed weight	2349 kg

Additional information

Fuel tank capacity	60 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5
Engine number	263A80008098236 LJ5