




report date: 2024-03-29

General information

Make	KIA
Model	CARENS CRDI 16V LX
Colour	Silver
Year of manufacture	2006
Top speed	107 mph
0 - 60 mph	13.5 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	111 BHP
Max. torque	245 Nm at 2.000 rpm
Engine capacity	1.991 cc
Cylinders	4
Fuel type	Diesel
Consumption city	32.1 mpg
Consumption extra urban	55.4 mpg
Consumption combined	43.5 mpg
CO2 emission	171 g/km
CO2 label	H





Internet history

Entry 1

Date	2021-01-31
Pictures	1
Listing price	<a href="#">View report</a>



source: [autoonline.co.uk](#)



## MOT history

MOT expiry date	2020-10-24
MOT pass rate	65 %
MOT passed	11
Failed MOT tests	6
Total advice items	21
Total items failed	13

MOT #17	2019-04-25 09:28
MOT test number	932295009427
Result	✓ Passed
Next expiry date	2020-10-24
Advice	Nearside Front Wheel bearing has slight play (5.1.3 (a) (i))

MOT #16	2019-04-25 09:28
MOT test number	544797670519
Result	✗ Failed
Pass with rectification	Nearside Rear Tyre not fitted in accordance with side wall instructions (5.2.3 (i))
Advice	Nearside Front Wheel bearing has slight play (5.1.3 (a) (i))
Pass with rectification	Offside Rear Tyre not fitted in accordance with side wall instructions (5.2.3 (i))

MOT #15	2018-04-05 07:55
MOT test number	917484042942
Result	✓ Passed

**MOT #14** 2017-05-12 13:30**MOT test number** 309145279578**Result** ✓ Passed**Advice** Offside Rear Seat belt anchorage prescribed area is corroded but not considered excessive wheel arch (5.2.6)**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**MOT #13** 2017-05-12 07:52**MOT test number** 533166644699**Result** ✗ Failed**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**Fail** Parking brake: efficiency below requirements (3.7.B.7)**Advice** Parking brake lever has little reserve travel (3.1.6b)**Advice** Offside Rear Seat belt anchorage prescribed area is corroded but not considered excessive wheel arch (5.2.6)**MOT #12** 2016-05-03 10:13**MOT test number** 276516520327**Result** ✓ Passed**MOT #11** 2016-05-03 08:00**MOT test number** 876701583915**Result** ✗ Failed**Fail** Parking brake: efficiency below requirements (3.7.B.7)**Fail** Parking brake lever has no reserve travel (3.1.6b)

**MOT #10** 2015-05-15 13:30**MOT test number** 646755635160**Result** ✓ Passed**Advice** Nearside Rear Brake pipe slightly corroded (3.6.B.2c)**Advice** Offside Rear Brake pipe slightly corroded (3.6.B.2c)**MOT #9** 2015-05-15 09:59**MOT test number** 958385035149**Result** ✗ Failed**Fail** Parking brake: efficiency below requirements (3.7.B.7)**Advice** Nearside Rear Brake pipe slightly corroded (3.6.B.2c)**Fail** Offside Registration plate lamp not working (1.1.C.1d)**Fail** Parking brake lever has no reserve travel (3.1.6b)**Advice** Front Brake pad(s) wearing thin (3.5.1g)**Advice** Offside Rear Brake pipe slightly corroded (3.6.B.2c)**Fail** Nearside Windscreen wiper does not clear the windscreen effectively (8.2.2)**MOT #8** 2014-05-15 15:24**MOT test number** 517275534139**Result** ✓ Passed

**MOT #7** 2014-05-15 09:01**MOT test number** 517995334172**Result** ✗ Failed**Fail** Rear Brake pad(s) less than 1.5 mm thick (3.5.1g)**Fail** Offside Front position lamp(s) not working (1.1.A.3b)**Fail** Parking brake lever has no reserve travel (3.1.6b)**Advice** Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**MOT #6** 2013-05-31 11:48**MOT test number** 618071553163**Result** ✓ Passed**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Rear Brake pad(s) wearing thin (3.5.1g)**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**MOT #5** 2012-06-22 09:13**MOT test number** 257924572162**Result** ✓ Passed**MOT #4** 2011-06-23 09:32**MOT test number** 139204171125**Result** ✓ Passed**Notice** 2 nails in offside rear tyre and showing signs of wear



MOT #3	2011-06-23 09:32
MOT test number	295174871174
Result	✗ Failed
Notice	2 nails in offside rear tyre and showing signs of wear
Pass with rectification	Nearside Front Windscreen wiper does not clear the windscreen effectively (8.2.2)

MOT #2	2010-06-23 14:47
MOT test number	933224970126
Result	✓ Passed
Advice	Nearside Front Tyre worn close to the legal limit (4.1.E.1)
Advice	Offside Front Tyre worn close to the legal limit (4.1.E.1)

MOT #1	2009-06-29 10:45
MOT test number	790990589130
Result	✓ Passed



Tax & MOT check

✕  
Untaxed

Tax expired:  
31 March 2020

✕  
MOT

Expired:  
24 October 2020

Tax status	Expired at 31 March 2020
Days left	1491 days too late
MOT expiry date	24 October 2020
Full MOT history	<a href="#">See MOT history</a>

Tax calculation

Vehicle class	49
Band	H
Single payment (12 months)	£ 290,00,-
Single six month payment	£ 159,50,-
Total payable by 12 monthly instalments	£ 304,50,-



Damage history

Check the damage history for this KIA. See if, where and when this KIA had damage and the car repair costs. We also check if this KIA was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra KIA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this KIA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this KIA? How many owners did this KIA have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this KIA had different number plates.

Number of plates	1
Current registration	<b>BF56NVS</b>
Plate since	2019-03-29
Current registration	<b>BF56NVS</b>
Plate since	2019-03-29

More info >



Finance check

Check if this KIA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this KIA has been settled.

If not, and you buy this KIA then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this KIA is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	18
First mileage registration	2006-09-27
Last registration	2019-04-25
Complete history	<a href="#">See info</a>



Registration #1	2006-09-27	13 mi
Registration #2	2009-06-29	18.877 mi
Registration #3	2010-06-23	26.994 mi
Registration #4	2011-06-23	35.553 mi
Registration #5	2012-06-22	43.310 mi
Registration #6	2013-05-31	49.306 mi
Registration #7	2014-05-15	54.393 mi
Registration #8	2014-05-15	54.394 mi
Registration #9	2015-05-15	61.390 mi
Registration #10	2016-05-15	68.387 mi
Registration #11	2017-05-15	75.384 mi
Registration #12	2018-05-15	82.381 mi
Registration #13	2019-05-15	89.378 mi
Registration #14	2020-05-15	96.375 mi
Registration #15	2021-05-15	103.372 mi
Registration #16	2022-05-15	110.369 mi
Registration #17	2023-05-15	117.366 mi
Registration #18	2024-05-15	124.363 mi

More info >



Car features

The KIA factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete KIA factory list for this vehicle [here](#).

More info >

Dimensions & weight

Width	1748 mm
Height	1650 mm
Length	4493 mm
Wheel base	2560 mm
Kerb weight	1549 kg
Max. allowed weight	1965 kg

Additional information

Fuel tank capacity	55 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5
Number of axles	2
Engine number	D4EA5H13570