



TOYOTA

**P002JYY**

report date: 2024-03-28

General information

Make	TOYOTA
Model	CELICA VVTi
Colour	Silver
Year of manufacture	-
Top speed	127 mph
0 - 60 mph	8.7 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	140 BHP
Max. torque	172 Nm at 4.200 rpm
Cylinders	4
Fuel type	Petrol
Consumption city	27.4 mpg
Consumption extra urban	45.6 mpg
Consumption combined	36.7 mpg






Internet history

Entry 1

Date	2021-08-11
Pictures	24
Listing price	<a href="#">View report</a>



source: [autotrader.co.uk](https://www.autotrader.co.uk)

**MOT history**

<b>MOT #19</b>	2021-08-17 16:40
<b>MOT test number</b>	697690968260
<b>Result</b>	✓ Passed
<b>Next expiry date</b>	2022-08-16

<b>MOT #18</b>	2021-08-11 12:18
<b>MOT test number</b>	366596816730
<b>Result</b>	✗ Failed

**Fail** Offside Front Road wheel fixing missing (5.2.1 (a) (i))

**Fail** Exhaust carbon monoxide content after 2nd fast idle exceeds manufacturer's specified limits (8.2.1.2 (a))

**Advice** Nearside Front Nail in tyre

**Fail** Exhaust emits excessive dense blue smoke during acceleration (8.2.1.2 (g))

**Minor** Front Windscreen wiper blade defective nearside and offside (3.4 (b) (i))

**Advice** Nearside Tyre worn close to legal limit/worn on edge front and rear (5.2.3 (e))

<b>MOT #17</b>	2019-11-06 19:52
<b>MOT test number</b>	119212004831
<b>Result</b>	✓ Passed

**Advice** Exhaust emits blue smoke during acceleration (8.2.1.2 (g))

<b>MOT #16</b>	2018-11-20 16:31
<b>MOT test number</b>	489949405866
<b>Result</b>	✓ Passed

<b>MOT #15</b>	2017-11-22 11:04
<b>MOT test number</b>	635193628294
<b>Result</b>	✓ Passed

**MOT #14**

2016-12-08 10:25

**MOT test number**

546930937723

**Result**

✓ Passed

**Advice** Front Suspension arm rubber bush deteriorated but not resulting in excessive movement both sides (REAR BUSH) (2.4.G.2)

**Advice** Mot carried out in wet condition

**MOT #13**

2015-09-22 15:52

**MOT test number**

155061220369

**Result**

✓ Passed

**Advice** Offside Front Track rod end ball joint dust cover deteriorated, but preventing the ingress of dirt (2.2.C.1c)

**Advice** Offside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement rear (2.4.G.2)

**Advice** Undertrays fitted

**Advice** Nearside Front Shock absorber has slight corrosion to the casing (2.7.2a)

**Advice** Nearside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement rear (2.4.G.2)

**Advice** N/s/f wiper rubber split

**MOT #12**

2015-08-22 12:39

**MOT test number**

648930636393

**Result****✗ Failed**

**Advice** Offside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement rear (2.4.G.2)

**Advice** Undertrays fitted

**Fail** Exhaust emissions hydrocarbon content after 2nd fast idle excessive (7.3.D.3)

**Advice** Nearside Front Shock absorber has slight corrosion to the casing (2.7.2a)

**Advice** Nearside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement rear (2.4.G.2)

**Advice** N/S/F WIPER SPLIT

**Fail** Exhaust emissions carbon monoxide content at idle excessive (7.3.D.4)

**Fail** Exhaust emissions carbon monoxide content after 2nd fast idle excessive (7.3.D.3)

**Advice** Offside Front Track rod end ball joint dust cover deteriorated, but preventing the ingress of dirt (2.2.C.1c)

**MOT #11**

2014-09-16 11:34

**MOT test number**

216169754254

**Result****✓ Passed**

**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)

**Advice** Windscreen has damage to an area less than a 10mm circle within zone 'A' (8.3.1a)

**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)

**MOT #10**

2013-09-17 13:24

**MOT test number**

759660263299

**Result****✓ Passed**

**Advice** Front Brake pad(s) wearing thin (3.5.1g)

**Notice** Engine managment light remain on after start up

**Advice** Rear Brake pad(s) wearing thin (3.5.1g)

**MOT #9** 2012-09-21 14:01**MOT test number** 156315262221**Result** ✓ Passed**Advice** Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**MOT #8** 2010-02-23 16:56**MOT test number** 962964850038**Result** ✓ Passed**MOT #7** 2010-02-09 13:37**MOT test number** 282960440030**Result** ✓ Passed**Advice** Nearside Rear brake disc slightly scored (3.5.1h)**Advice** Offside Front brake disc slightly scored (3.5.1h)**Advice** Offside Rear brake disc slightly scored (3.5.1h)**Advice** Nearside Front brake disc slightly scored (3.5.1h)**MOT #6** 2009-04-07 14:23**MOT test number** 460997599059**Result** ✓ Passed**MOT #5** 2009-04-02 12:12**MOT test number** 951652999078**Result** ✗ Failed**Fail** Nearside Windscreen wiper does not clear the windscreen effectively (8.2.2)**Fail** Nearside Rear Brake pad(s) less than 1.5 mm thick (3.5.1g)**Fail** Offside Windscreen wiper does not clear the windscreen effectively (8.2.2)**Fail** Offside Rear Brake pad(s) less than 1.5 mm thick (3.5.1g)

**MOT #4** 2008-01-10 08:47**MOT test number** 604460718044**Result** ✓ Passed

- Advice** Offside Rear Brake pad(s) wearing thin (3.5.1g)
- Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)
- Advice** Nearside Rear Brake pad(s) wearing thin (3.5.1g)
- Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)

**MOT #3** 2008-01-09 09:43**MOT test number** 704219208069**Result** ✗ Failed

- Fail** Offside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1)
- Advice** Offside Rear Brake pad(s) wearing thin (3.5.1g)
- Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)
- Fail** Nearside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1)
- Advice** Nearside Rear Brake pad(s) wearing thin (3.5.1g)
- Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)

**MOT #2** 2006-08-16 15:03**MOT test number** 493248126247**Result** ✓ Passed

- Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)

**MOT #1** 2005-08-17 15:48**MOT test number** 484119125265**Result** ✓ Passed



Damage history

Check the damage history for this TOYOTA. See if, where and when this TOYOTA had damage and the car repair costs. We also check if this TOYOTA was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	

Extra TOYOTA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >





Vehicle valuation

What is this car worth? See the vehicle value of this TOYOTA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this TOYOTA? How many owners did this TOYOTA have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this TOYOTA had different number plates.

Number of plates	1
Current registration	*****
Plate since	2019-06-28
Current registration	*****
Plate since	2019-06-28

More info >



Finance check

Check if this TOYOTA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this TOYOTA has been settled. If not, and you buy this TOYOTA then you could lose the money and the car you paid for. Download the premium report [here](#) and check if this TOYOTA is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	21
First mileage registration	2002-08-01
Last registration	2021-08-17
Complete history	<a href="#">See info</a>



Registration #1	2002-08-01	14 mi
Registration #2	2005-08-17	22.360 mi
Registration #3	2006-08-16	30.134 mi
Registration #4	2008-01-09	37.868 mi
Registration #5	2008-01-10	37.868 mi
Registration #6	2009-04-02	45.327 mi
Registration #7	2009-04-07	45.350 mi
Registration #8	2010-02-09	128.224 mi
Registration #9	2010-02-23	52.970 mi
Registration #10	2012-09-21	70.965 mi
Registration #11	2013-09-17	77.102 mi
Registration #12	2015-05-20	95.277 mi
Registration #13	2015-05-20	95.277 mi
Registration #14	2015-05-20	95.277 mi
Registration #15	2015-05-20	95.277 mi
Registration #16	2015-05-20	95.277 mi
Registration #17	2015-05-20	95.277 mi
Registration #18	2015-05-20	95.277 mi
Registration #19	2015-05-20	95.277 mi
Registration #20	2015-05-20	95.277 mi
Registration #21	2015-05-20	95.277 mi

More info >



Car features

The TOYOTA factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete TOYOTA factory list for this vehicle [here](#).

More info >

Dimensions & weight

Width	1735 mm
Height	1315 mm
Length	4350 mm
Wheel base	2600 mm
Kerb weight	1145 kg

Additional information

Fuel tank capacity	60 l
Fuel delivery	Multi-Point Injection
Number of doors	3
Engine number	1ZZ0924775