



report date: 2024-03-29

General information

Make	VOLVO
Model	XC40 D3 MOMENTUM PRO
Colour	Red
Year of manufacture	2018
Top speed	124 mph
0 - 60 mph	9.8 seconds
Gearbox	8 speed automatic

Engine & fuel consumption

Power	148 BHP
Max. torque	320 Nm at 1.750 rpm
Engine capacity	1.969 cc
Cylinders	4
Fuel type	Diesel
Consumption combined	2.8 mpg
CO2 emission	131 g/km
CO2 label	E





Internet history

Entry 3

Date	2023-10-30
Pictures	1
Listing price	View report



source: cargurus.co.uk

Entry 2

Date	2021-10-28
Pictures	1
Listing price	View report



source: cargurus.co.uk

Entry 1

Date	2021-10-27
Pictures	1
Listing price	View report



source: autotrader.co.uk



MOT history

MOT expiry date	2024-10-10
MOT pass rate	60 %
MOT passed	3
Failed MOT tests	2
Total advice items	10
Total items failed	0

MOT #5	2023-10-04 12:04
MOT test number	502011141458
Result	✓ Passed
Next expiry date	2024-10-10

MOT #4	2023-10-03 10:34
MOT test number	248749034315
Result	✗ Failed
MAJOR	Nearside Front Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (5.2.3 (d) (i))
Advice	Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))

MOT #3	2022-10-06 12:04
MOT test number	171061948814
Result	✓ Passed

MOT #2	2021-10-01 10:10
MOT test number	142429165257
Result	✓ Passed
Advice	Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Nearside Rear Nail in tyre



MOT #12021-09-29 10:48

MOT test number366665540302

Result

Failed

DANGEROUS

Offside Front Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))

Advice

Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice

Nearside Rear Nail in tyre

DANGEROUS

Nearside Front Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))

Advice

Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))



Tax & MOT check

✓
Taxed
Tax due:
1 December 2024

✓
MOT
Expires:
10 October 2024

Tax status	Valid until 1 December
Days left	216
MOT expiry date	10 October 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	H
First licence fee (12 months)	£ 255,00,-
First licence fee diesel non RDE2 tested (12 months)	£ 645,00,-
Standard rate (12 months)	£ 180,00,-
Standard rate (6 months)	£ 99,00,-
Premium rate (12 months)	£ 570,00,-
Premium rate (6 months)	£ 313,50,-



Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,299
Auction value	£ 19,299
Average private trade value	£ 19,299

More info >



Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners did this VOLVO have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date

More info >

Plate changes

See in this check if this VOLVO had different number plates.

Number of plates	1
Current registration	XXXXXX
Plate since	2024-03-29
Current registration	XXXXXX
Plate since	2024-03-29

More info >



Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLVO is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	9
First mileage registration	2018-10-11
Last registration	2023-10-04
Complete history	See info



Registration #1	2018-10-11	18 mi
Registration #2	2021-09-29	32.249 mi
Registration #3	2021-10-01	32.249 mi
Registration #4	2023-10-04	32.249 mi
Registration #5	2023-10-04	32.249 mi
Registration #6	2023-10-04	32.249 mi
Registration #7	2023-10-04	32.249 mi
Registration #8	2023-10-04	32.249 mi
Registration #9	2023-10-04	32.249 mi

More info >



Car features

The VOLVO factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLVO factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	97%
Children	87%
Pedestrian	71%
Safety systems	76%
Overall rating	86%
Video	see crash video



Dimensions & weight

Width	1910 mm
Height	1658 mm
Length	4425 mm
Kerb weight	1603 kg
Max. allowed weight	2180 kg

Additional information

Fuel tank capacity	54 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5
Number of axles	2

Engine number

2896427