



RENAULT



NX56YSU


report date: 2024-03-29

General information

Make	RENAULT
Model	MEGANE DYNAMIQUE VVT 111
Colour	Blue
Year of manufacture	2006
Top speed	124 mph
0 - 60 mph	11.8 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	110 BHP
Max. torque	148 Nm at 3.750 rpm
Engine capacity	1.598 cc
Cylinders	4
Fuel type	Petrol
Consumption city	30.1 mpg
Consumption extra urban	49.6 mpg
Consumption combined	40.4 mpg
CO2 emission	166 g/km
CO2 label	H





Internet history

Entry 1

Date	2021-10-10
Pictures	10
Listing price	View report



source: [autotrader.co.uk](https://www.autotrader.co.uk)



MOT history

MOT expiry date	2023-10-14
MOT pass rate	88 %
MOT passed	14
Failed MOT tests	2
Total advice items	25
Total items failed	9

MOT #16 2022-10-15 08:33

MOT test number 438322812067

Result ✓ Passed

Next expiry date 2023-10-14

- Advice** Noise from Macpherson strut top mount when turning the wheels (Both front side)
- Advice** Nearside Rear Direction indicator slightly discoloured (4.4.3 (a))
- Advice** Offside Front Wheel bearing has slight play (5.1.3 (a) (i))
- Advice** Under trays fitted obscuring underside components
- Advice** Offside Rear Direction indicator slightly affected by the operation of another lamp (4.4.3 (b))
- Advice** Front Play in steering rack inner joint(s) Both side
- Advice** Oil leak, but not excessive (8.4.1 (a) (i))
- Advice** Offside Rear Wheel bearing has slight play (5.1.3 (a) (i))

**MOT #15**

2022-10-14 14:02

MOT test number

643227576974

Result

✗ Failed

- Advice** Offside Rear Wheel bearing has slight play (5.1.3 (a) (i))
- Fail** Offside Front Position lamp not working (4.2.1 (a) (ii))
- Advice** Front Play in steering rack inner joint(s) Both side
- Advice** Nearside Rear Direction indicator slightly discoloured (4.4.3 (a))
- Fail** Offside Front Lower Anti-roll bar linkage ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))
- Advice** Under trays fitted obscuring underside components
- Fail** Supplementary restraint system warning lamp indicates a fault (7.1.6 (a))
- Advice** Offside Front Wheel bearing has slight play (5.1.3 (a) (i))
- Fail** Nearside Front Position lamp not working (4.2.1 (a) (ii))
- Advice** Offside Rear Direction indicator slightly affected by the operation of another lamp (4.4.3 (b))
- Advice** Oil leak, but not excessive (8.4.1 (a) (i))
- Fail** Nearside Front Lower Anti-roll bar linkage ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))
- Advice** Noise from Macpherson strut top mount when turning the wheels (Both front side)
- Fail** Engine MIL inoperative or indicates a malfunction (8.2.1.2 (h))

MOT #14

2021-09-23 11:22

MOT test number

334477454315

Result

✓ Passed

- Advice** Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Advice** Nearside Front Inner Drag link end ball joint has slight play (2.1.3 (b) (i))

**MOT #13** 2020-08-11 07:47**MOT test number** 536812001747**Result** ✓ Passed**Advice** Play in steering rack inner joint(s)**MOT #12** 2019-05-09 13:15**MOT test number** 642516130738**Result** ✓ Passed**Advice** Play in steering rack inner joint(s)**MOT #11** 2018-02-22 08:44**MOT test number** 922243708085**Result** ✓ Passed**Advice** Play in steering rack inner joint(s)**MOT #10** 2017-02-23 10:57**MOT test number** 856819920037**Result** ✓ Passed**Advice** Play in steering rack inner joint(s)**MOT #9** 2016-02-12 08:49**MOT test number** 474489900182**Result** ✓ Passed**MOT #8** 2015-02-13 11:54**MOT test number** 886994045010**Result** ✓ Passed

**MOT #7** 2014-02-13 08:47**MOT test number** 456534644018**Result** ✓ Passed**MOT #6** 2013-02-05 10:29**MOT test number** 268136133072**Result** ✓ Passed**MOT #5** 2012-02-22 11:06**MOT test number** 805173852047**Result** ✓ Passed**MOT #4** 2011-03-04 17:26**MOT test number** 727543061085**Result** ✓ Passed**Notice** Osf and nsr tyres sidewalls perished**MOT #3** 2010-09-02 14:24**MOT test number** 730585240273**Result** ✓ Passed**MOT #2** 2009-08-24 16:09**MOT test number** 100256339263**Result** ✓ Passed**Advice** Front brake disc slightly pitted (3.5.1h)



MOT #1	2009-08-24 09:56
MOT test number	593176839281
Result	✗ Failed
Fail	Offside Rear brake disc excessively pitted (3.5.1h)
Advice	Front brake disc slightly pitted (3.5.1h)
Fail	Offside Windscreen wiper does not clear the windscreen effectively (8.2.2)
Fail	Nearside Rear brake disc excessively pitted (3.5.1h)



Tax & MOT check

X

Untaxed

Tax expired:
22 June 2023

X

MOT

Expired:
14 October 2023

Tax status	Expired at 22 June 2023
Days left	312 days too late
MOT expiry date	14 October 2023
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	H
Single payment (12 months)	£ 290,00,-
Single six month payment	£ 159,50,-
Total payable by 12 monthly instalments	£ 304,50,-



Damage history

Check the damage history for this RENAULT. See if, where and when this RENAULT had damage and the car repair costs. We also check if this RENAULT was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra RENAULT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this RENAULT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this RENAULT? How many owners did this RENAULT have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

XXXXXX	XXXXXX
XXXXXXXXXX	XXXXXX
XXXXXXXXXX	XXXXXX
XXXXXX	XXXXXX
XXXXXXXXXX	XXXXXX
XXXXXXXXXX	XXXXXX

More info >

Plate changes

See in this check if this RENAULT had different number plates.

Number of plates	1
Current registration	XXXXX
Plate since	2024-03-29
Current registration	XXXXX
Plate since	2024-03-29

More info >



Finance check

Check if this RENAULT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this RENAULT has been settled.

If not, and you buy this RENAULT then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this RENAULT is financed.


Finance company	REDACTED	REDACTED
Date of agreement	REDACTED	REDACTED
Agreement type	REDACTED	REDACTED
Agreement term	REDACTED	REDACTED
Agreement number	REDACTED	REDACTED
Contact info	REDACTED	REDACTED

More info >



Mileage check

Odometer	In miles
Mileage registrations	18
First mileage registration	2006-09-04
Last registration	2022-10-15
Complete history	See info



Registration #1	2006-09-04	23 mi
Registration #2	2009-08-24	18.814 mi
Registration #3	2009-08-24	18.817 mi
Registration #4	2010-09-02	19.660 mi
Registration #5	2011-03-04	19.887 mi
Registration #6	2012-02-22	29.753 mi
Registration #7	2013-02-05	37.799 mi
Registration #8	2014-02-13	41.713 mi
Registration #9	2015-02-13	44.836 mi
Registration #10	2016-02-22	50.277 mi
Registration #11	2017-02-22	55.277 mi
Registration #12	2018-02-22	60.277 mi
Registration #13	2019-02-22	65.277 mi
Registration #14	2020-02-22	70.277 mi
Registration #15	2021-02-22	75.277 mi
Registration #16	2022-02-22	80.277 mi
Registration #17	2023-02-22	85.277 mi
Registration #18	2024-02-22	90.277 mi

More info >



Car features

The RENAULT factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete RENAULT factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1698 mm
Height	1366 mm
Length	4028 mm
Wheel base	2522 mm
Kerb weight	1320 kg
Max. allowed weight	1775 kg

Additional information

Fuel tank capacity	60 l
Fuel delivery	Multi-Point Injection
Number of doors	2
Number of seats	4

Engine number	D050625
---------------	---------