



UK

AP52WAE


report date: 2024-03-29

General information

Make	NISSAN
Model	SKYLINE
Colour	Blue
Year of manufacture	2003
Gearbox	-

Engine & fuel consumption

Engine capacity	3.490 cc
Fuel type	Petrol
CO2 emission	282 g/km
CO2 label	M





Internet history

Entry 1

Date	2021-06-26
Pictures	17
Listing price	View report



source: [autotrader.co.uk](#)



MOT history

MOT expiry date	2025-02-24
MOT pass rate	76 %
MOT passed	19
Failed MOT tests	6
Total advice items	52
Total items failed	11

MOT #25	2024-02-21 13:39
MOT test number	724218867986
Result	✓ Passed
Next expiry date	2025-02-24
Minor	Nearside Front Suspension arm ball joint dust cover severely deteriorated (5.3.4 (b) (i))
Advice	Front Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))
Advice	Front Brake hose has slight corrosion to ferrule (1.1.12 (f) (i))
Advice	Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
Advice	Offside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))
Advice	Rear Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))
Advice	Nearside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))

MOT #24	2023-02-04 08:44
MOT test number	261419242568
Result	✓ Passed
Advice	Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))
Advice	Front and rear subframes have slight corrosion

**MOT #23**

2022-02-25 16:32

MOT test number

550027793365

Result

✓ Passed

- Advice** Offside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))
- Advice** Nearside Front foglamp lens broken
- Advice** Nearside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))

MOT #22

2020-08-03 12:39

MOT test number

903755599741

Result

✓ Passed

- Minor** Nearside Registration plate lamp insecure (4.7.1 (c) (i))
- Advice** Undertrays fitted

MOT #21

2019-07-24 12:01

MOT test number

799412435554

Result

✓ Passed

- Advice** Rear Anti-roll bar linkage ball joint has slight play both sides (5.3.4 (a) (i))
- Advice** Under-body components corroded
- Advice** Undertrays fitted
- Advice** Front Brake drum worn, pitted or scored, but not seriously weakened both sides (1.1.14 (a) (ii))

**MOT #20**

2019-07-12 13:23

MOT test number

781252766992

Result**✗ Failed****Advice** Under-body components corroded**Fail** Nearside Front Headlamp aim projected beam image is obviously incorrect (4.1.2 (c))**Advice** Front Brake drum worn, pitted or scored, but not seriously weakened both sides (1.1.14 (a) (ii))**Advice** Undertrays fitted**Advice** Rear Anti-roll bar linkage ball joint has slight play both sides (5.3.4 (a) (i))**Fail** Offside Front Headlamp aim projected beam image is obviously incorrect (4.1.2 (c))**MOT #19**

2018-08-08 12:14

MOT test number

458349687136

Result**✓ Passed****MOT #18**

2018-07-11 11:10

MOT test number

452379316084

Result**✗ Failed****Advice** Nearside Rear Lower Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))**Minor** Nearside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))**Fail** Nearside Headlamp aim too high (4.1.2 (a))**Advice** Offside Rear Lower Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))**Fail** Offside Headlamp aim too high (4.1.2 (a))

**MOT #17** 2017-07-11 14:50**MOT test number** 316611120919**Result** ✓ Passed**Advice** Nearside Rear Lower Anti-roll bar linkage has slight play in a ball joint (2.4.G.2)**Advice** Nearside Headlamp deteriorated but light output not reduced (1.7.5a)**Advice** Offside Rear Lower Anti-roll bar linkage has slight play in a ball joint (2.4.G.2)**Advice** Offside Headlamp deteriorated but light output not reduced (1.7.5a)**MOT #16** 2016-06-28 13:46**MOT test number** 820455631640**Result** ✓ Passed**MOT #15** 2015-07-08 09:57**MOT test number** 307809985173**Result** ✓ Passed**Advice** Rear fog lamp deteriorated, but still visible from a reasonable distance (1.3.2d)**MOT #14** 2015-07-07 16:26**MOT test number** 418168985198**Result** ✗ Failed**Advice** Rear fog lamp deteriorated, but still visible from a reasonable distance (1.3.2d)**Fail** Offside Front Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (4.1.D.1a)

**MOT #13** 2014-07-16 08:27**MOT test number** 588097794124**Result** ✓ Passed

- Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)
- Advice** Offside Rear fog lamp has light sources not illuminating, but not more than 50% (1.3.2b)
- Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)
- Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)
- Advice** Front Brake lining(s) wearing thin (3.5.1g)

MOT #12 2014-07-15 17:25**MOT test number** 298826394449**Result** ✗ Failed

- Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)
- Fail** Nearside Headlamp aim beam image obviously incorrect (1.8.A.1b)
- Fail** Offside Front position lamp(s) not working (1.1.A.3b)
- Advice** Front Brake lining(s) wearing thin (3.5.1g)
- Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)
- Fail** Offside Headlamp aim beam image obviously incorrect (1.8.A.1b)
- Advice** Offside Rear fog lamp has light sources not illuminating, but not more than 50% (1.3.2b)
- Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)

MOT #11 2013-07-04 14:10**MOT test number** 255425283156**Result** ✓ Passed

**MOT #10** 2012-07-13 09:03**MOT test number** 886665392108**Result** ✓ Passed**MOT #9** 2012-07-02 15:41**MOT test number** 386174082164**Result** ✗ Failed**Fail** Exhaust emissions Lambda reading after 2nd fast idle outside specified limits (7.3.D.3)**Fail** Exhaust has a major leak of exhaust gases (7.1.2)**MOT #8** 2011-07-01 12:31**MOT test number** 536542181137**Result** ✓ Passed**Notice** Front brake discs wearing thin!**MOT #7** 2010-06-28 09:11**MOT test number** 241119070418**Result** ✓ Passed**Advice** Rear Brake pad(s) wearing thin (3.5.1g)**MOT #6** 2009-06-30 08:45**MOT test number** 462381589109**Result** ✓ Passed**MOT #5** 2008-07-04 15:03**MOT test number** 581196888192**Result** ✓ Passed

**MOT #4** 2008-06-20 11:53**MOT test number** 282232078185**Result** ✗ Failed**Fail** Nearside Headlamp not working on dipped beam (1.7.5a)**MOT #3** 2007-06-28 11:45**MOT test number** 900899077113**Result** ✓ Passed**MOT #2** 2006-06-30 12:55**MOT test number** 594981586177**Result** ✓ Passed**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Exhaust has a minor leak of exhaust gases (7.1.2)**Notice** Nearside front wheel and tyre have kerbing damage.**Notice** Brake fluid level below maximum. Offside wiper only just clears screen and should be replaced.**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)**Notice** Both front tyres need replacing soon. Both are unevenly worn and starting to perish.**Notice** Front section of exhaust has minor damage.**MOT #1** 2006-02-22 17:07**MOT test number** 192113756096**Result** ✓ Passed**Advice** Front Tyre worn close to the legal limit (4.1.E.1)



Tax & MOT check

✓
Taxed
Tax due:
1 April 2025

✓
MOT
Expires:
24 February 2025

Tax status	Valid until 1 April
Days left	336
MOT expiry date	24 February 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	K
Single payment (12 months)	£ 395,00,-
Single six month payment	£ 217,25,-
Total payable by 12 monthly instalments	£ 414,75,-



Damage history

Check the damage history for this NISSAN. See if, where and when this NISSAN had damage and the car repair costs. We also check if this NISSAN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra NISSAN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Owner history

For how long did the current and previous owner(s) have this NISSAN? How many owners did this NISSAN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this NISSAN had different number plates.

Number of plates	1
Current registration	*****
Plate since	2019-06-29
Current registration	*****
Plate since	2019-06-29

More info >



Finance check

Check if this NISSAN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this NISSAN has been settled.

If not, and you buy this NISSAN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this NISSAN is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	27
First mileage registration	2003-02-01
Last registration	2024-02-21
Complete history	See info



Registration #1	2003-02-01	9 mi
Registration #2	2006-02-22	29.071 mi
Registration #3	2006-06-30	18.688 mi
Registration #4	2007-06-28	45.046 mi
Registration #5	2008-06-20	71.316 mi
Registration #6	2008-07-04	72.363 mi
Registration #7	2009-06-30	99.627 mi
Registration #8	2010-06-28	110.397 mi
Registration #9	2011-07-01	115.695 mi
Registration #10	2012-07-02	121.256 mi
Registration #11	2012-07-13	121.503 mi
Registration #12	2013-07-04	127.358 mi
Registration #13	2014-07-15	82.239 mi
Registration #14	2014-07-16	82.239 mi
Registration #15	2015-06-20	82.239 mi
Registration #16	2015-06-20	82.239 mi
Registration #17	2015-06-20	82.239 mi
Registration #18	2015-06-20	82.239 mi
Registration #19	2015-06-20	82.239 mi
Registration #20	2015-06-20	82.239 mi
Registration #21	2015-06-20	82.239 mi
Registration #22	2015-06-20	82.239 mi
Registration #23	2015-06-20	82.239 mi
Registration #24	2015-06-20	82.239 mi
Registration #25	2015-06-20	82.239 mi
Registration #26	2015-06-20	82.239 mi

More info >



Car features

The NISSAN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete NISSAN factory list for this vehicle [here](#).

More info >

Additional information

Number of seats	4
Engine number	NOT KNOWN