



report date: 2024-03-29

General information

Make	VOLKSWAGEN
Model	SCIROCCO GT TDI
Colour	Black
Year of manufacture	-
Top speed	129 mph
0 - 60 mph	9.3 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	140 BHP
Max. torque	320 Nm at 1.750 rpm
Cylinders	4
Fuel type	Diesel
Consumption city	42.8 mpg
Consumption extra urban	67.3 mpg
Consumption combined	55.4 mpg



LABEL UNKNOWN

**MOT history**

MOT #10	2021-01-06 08:39
MOT test number	751900081599
Result	✓ Passed
Next expiry date	2022-01-05

MOT #9	2019-06-15 13:07
MOT test number	618554096813
Result	✓ Passed

Advice Osf and nsf drop link dust covers are slightly damage

Advice Emission has too clean to detect

MOT #8	2018-06-26 14:58
MOT test number	578177082863
Result	✓ Passed

Minor Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))

MOT #7	2017-04-19 11:57
MOT test number	928350315828
Result	✓ Passed

MOT #6	2016-05-05 09:11
MOT test number	801561429480
Result	✓ Passed

MOT #5	2015-05-15 11:18
MOT test number	489035935183
Result	✓ Passed

MOT #4	2014-10-14 12:19
MOT test number	956737784271
Result	✓ Passed



MOT #3	2013-10-11 16:57
MOT test number	139594783272
Result	✓ Passed

MOT #2	2012-12-05 11:32
MOT test number	207660342310
Result	✗ Failed
Advice	Nearside Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
Pass with rectification	Nearside Headlamp aim too low and too far to the right. (1.8)
Advice	Offside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
Advice	Offside Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
Pass with rectification	Offside Headlamp aim too low (1.8)
Advice	Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

MOT #1	2012-12-05 11:32
MOT test number	928350742349
Result	✓ Passed
Advice	Offside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
Advice	Offside Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
Advice	Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
Advice	Nearside Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)



Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this VOLKSWAGEN had different number plates.

Number of plates	1
Current registration	 *****
Plate since	2019-06-29
Current registration	 *****
Plate since	2019-06-29

More info >



Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLKSWAGEN is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	10
First mileage registration	2009-12-19
Last registration	2021-01-06
Complete history	See info



Registration #1	2009-12-19	29 mi
Registration #2	2012-12-05	49.172 mi
Registration #3	2013-10-11	62.751 mi
Registration #4	2014-10-14	82.751 mi
Registration #5	2015-05-15	88.899 mi
Registration #6	2016-05-20	95.277 mi
Registration #7	2017-05-20	101.277 mi
Registration #8	2018-05-20	107.277 mi
Registration #9	2019-05-20	113.277 mi
Registration #10	2021-01-06	119.277 mi

More info >



Car features

The VOLKSWAGEN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLKSWAGEN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	97%
Children	84%
Pedestrian	61%
Safety systems	71%
Overall rating	85%
Video	see crash video



Dimensions & weight

Width	1810 mm
Height	1404 mm
Length	4256 mm
Wheel base	2578 mm
Kerb weight	1318 kg
Max. allowed weight	1750 kg

Additional information

Fuel tank capacity	55 l
Fuel delivery	Direct Injection
Number of doors	2

Number of seats	4
Number of axles	2
Engine number	CBD 437987