



report date: 2024-03-28

General information

Make	FIAT
Model	BRAVO ACTIVE 120 MULTIJET
Colour	Beige
Year of manufacture	2008
Top speed	120 mph
0 - 60 mph	10.5 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	120 BHP
Max. torque	255 Nm at 2.000 rpm
Engine capacity	1.910 cc
Cylinders	4
Fuel type	Diesel
Consumption city	40.9 mpg
Consumption extra urban	65.7 mpg
Consumption combined	53.3 mpg
CO2 emission	139 g/km
CO2 label	E






Internet history

Entry 2

Date	2021-11-10
Pictures	39
Listing price	View report



source: cargurus.co.uk

Entry 1

Date	2021-11-09
Pictures	0
Listing price	View report

source: autotrader.co.uk



MOT history

MOT expiry date	2024-11-10
MOT pass rate	72 %
MOT passed	13
Failed MOT tests	5
Total advice items	38
Total items failed	8

MOT #18 2023-10-13 11:21

MOT test number 370585236481

Result ✓ Passed

Next expiry date 2024-11-10

Advice Rear Outer Sub-frame corroded but not seriously weakened and front outer (5.3.3 (b) (i))**Minor** Front Windscreen wiper blade defective (3.4 (b) (i))**Advice** Parking brake lever defective but can be satisfactorily operated Lever travel reserve (1.1.6 (d))**Advice** Offside Rear Service brake binding but not excessively (1.2.1 (f))

MOT #17 2022-11-04 15:02

MOT test number 623296773377

Result ✓ Passed**Advice** Oil leak, but not excessive (8.4.1 (a) (i))**Advice** Nearside Front Tyre worn close to legal limit/worn on edge Worn smooth inner edge. 205/55/16 (5.2.3 (e))**Advice** Rear Exhaust silencer outer skin starting to peel**Advice** Offside Front Tyre worn close to legal limit/worn on edge Worn smooth inner edge (5.2.3 (e))**Advice** Front Exhaust flexible section damaged

**MOT #16**

2022-11-04 12:59

MOT test number

687065472535

Result**✗ Failed**

- Advice** Oil leak, but not excessive (8.4.1 (a) (i))
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge Worn smooth inner edge. 205/55/16 (5.2.3 (e))
- Advice** Rear Exhaust silencer outer skin starting to peel
- MAJOR** Windscreen washer not working (3.5 (a))
- MAJOR** Rear Exhaust system insecure Silencer securing clamp not fitted (6.1.2 (a))
- Advice** Offside Front Tyre worn close to legal limit/worn on edge Worn smooth inner edge (5.2.3 (e))
- Advice** Front Exhaust flexible section damaged

MOT #15

2021-11-11 16:40

MOT test number

793348081546

Result**✓ Passed****MOT #14**

2021-11-10 16:55

MOT test number

683971766218

Result**✗ Failed**

- MAJOR** Front Windscreen washer not working (3.5 (a))
- Advice** Rear boot lid not opening
- MAJOR** Exhaust emissions exceed default limit of 1.5m-1 (8.2.2.2 (b))

**MOT #13**

2021-03-25 10:47

MOT test number

982446960233

Result

✓ Passed

Advice Nearside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement
Rear bush (5.3.4 (a) (i))

Advice Nearside Rear Coil spring mounting corroded but not seriously weakened (5.3.1 (b) (i))

Advice Front Sub-frame is corroded but structural rigidity is not significantly reduced (6.1.1 (c) (i))

Advice Offside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement
Rear bush (5.3.4 (a) (i))

Advice Offside Rear Coil spring mounting corroded but not seriously weakened (5.3.1 (b) (i))

MOT #12

2020-03-27 14:05

MOT test number

666133648124

Result

✓ Passed

Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #11

2019-03-21 15:49

MOT test number

456389104778

Result

✓ Passed

Advice Offside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement
Rear bush (5.3.4 (a) (i))

Advice Nearside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement
Rear bush (5.3.4 (a) (i))

MOT #10

2018-03-30 13:41

MOT test number

901182572656

Result

✓ Passed



MOT #9	2018-03-28 15:31
MOT test number	769586689398
Result	✗ Failed
Fail	Nearside Front coil spring broken (2.4.C.1a)

MOT #8	2017-03-29 12:55
MOT test number	336007010330
Result	✓ Passed
Advice	Under trays fitted

MOT #7	2017-03-27 15:43
MOT test number	543037956444
Result	✗ Failed
Fail	Nearside Front Upper Windscreen washer provides insufficient washer liquid (8.2.3)
Fail	Offside Front Lower Tyre tread depth below requirements of 1.6mm (4.1.E.1)
Fail	Offside Front Upper Windscreen washer provides insufficient washer liquid (8.2.3)
Fail	Nearside Front Lower Tyre not fitted in accordance with side wall instructions (4.1.D.1f)

MOT #6	2016-03-19 09:16
MOT test number	950808904786
Result	✓ Passed
Advice	Nearside Rear Tyre worn close to the legal limit 2mm (4.1.E.1)
Advice	Nail in nearside front tyre
Advice	Offside Rear Tyre worn close to the legal limit 2mm (4.1.E.1)
Advice	Uneven wear both rear tyres

**MOT #5** 2016-03-18 14:56**MOT test number** 187871940704**Result** ✗ Failed**Advice** Nearside Rear Tyre worn close to the legal limit 2mm (4.1.E.1)**Advice** Nail in nearside front tyre**Fail** Nearside Windscreen washer provides insufficient washer liquid (8.2.3)**Fail** Exhaust emits an excessive level of metered smoke (7.4.B.3a)**Advice** Offside Rear Tyre worn close to the legal limit 2mm (4.1.E.1)**Advice** Uneven wear both rear tyres**Fail** Offside Windscreen washer provides insufficient washer liquid (8.2.3)**MOT #4** 2015-03-23 16:55**MOT test number** 566242185032**Result** ✓ Passed**Notice** Items removed from driver's view prior to test**MOT #3** 2013-10-22 12:38**MOT test number** 465865893200**Result** ✓ Passed**MOT #2** 2012-10-25 15:17**MOT test number** 627909992232**Result** ✓ Passed**MOT #1** 2011-11-01 15:21**MOT test number** 498545001475**Result** ✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 November 2024

✓
MOT
Expires:
10 November 2024

Tax status	Valid until 1 November
Days left	185
MOT expiry date	10 November 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	E
Single payment (12 months)	£ 180,00,-
Single six month payment	£ 99,00,-
Total payable by 12 monthly instalments	£ 189,00,-



Damage history

Check the damage history for this FIAT. See if, where and when this FIAT had damage and the car repair costs. We also check if this FIAT was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra FIAT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this FIAT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this FIAT? How many owners did this FIAT have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this FIAT had different number plates.

Number of plates	1
Current registration	
Plate since	2024-03-28
Current registration	
Plate since	2024-03-28

More info >



Finance check

Check if this FIAT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FIAT has been settled.

If not, and you buy this FIAT then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this FIAT is financed.

Finance company	REDACTED	REDACTED
Date of agreement	REDACTED	REDACTED
Agreement type	REDACTED	REDACTED
Agreement term	REDACTED	REDACTED
Agreement number	REDACTED	REDACTED
Contact info	REDACTED	REDACTED

More info >



Mileage check

Odometer	In miles
Mileage registrations	21
First mileage registration	2008-09-26
Last registration	2023-10-13
Complete history	See info



Registration #1	2008-09-26	28 mi
Registration #2	2011-11-01	31.042 mi
Registration #3	2012-10-25	35.285 mi
Registration #4	2013-10-22	41.190 mi
Registration #5	2015-03-23	52.602 mi
Registration #6	2016-03-18	58.921 mi
Registration #7	2016-03-19	58.961 mi
Registration #8	2017-03-27	65.303 mi
Registration #9	2017-03-29	65.303 mi
Registration #10	2018-03-28	70.564 mi
Registration #11	2018-03-30	70.579 mi
Registration #12	2019-03-29	75.837 mi
Registration #13	2019-03-29	75.837 mi
Registration #14	2019-03-29	75.837 mi
Registration #15	2019-03-29	75.837 mi
Registration #16	2019-03-29	75.837 mi
Registration #17	2019-03-29	75.837 mi
Registration #18	2019-03-29	75.837 mi
Registration #19	2019-03-29	75.837 mi
Registration #20	2019-03-29	75.837 mi
Registration #21	2019-03-29	75.837 mi

More info >



Car features

The FIAT factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete FIAT factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1792 mm
Height	1498 mm
Length	4336 mm
Wheel base	2600 mm
Kerb weight	1320 kg
Max. allowed weight	1830 kg

Additional information

Fuel tank capacity	58 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5

Engine number	5870275
---------------	---------