



report date: 2024-03-29

General information

Make	VOLKSWAGEN
Model	GOLF SE TDI
Colour	Silver
Year of manufacture	2010
Top speed	117 mph
0 - 60 mph	11.3 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	105 BHP
Max. torque	250 Nm at 1.500 rpm
Engine capacity	1.600 cc
Cylinders	4
Fuel type	Diesel
Consumption city	49.6 mpg
Consumption extra urban	72.4 mpg
Consumption combined	62.8 mpg
CO2 emission	119 g/km
CO2 label	C





Internet history

Entry 3

Date	2021-07-27
Pictures	20
Listing price	<a href="#">View report</a>



source: [autotrader.co.uk](#)

Entry 2

Date	2021-07-02
Pictures	20
Listing price	<a href="#">View report</a>



source: [autotrader.co.uk](#)

Entry 1

Date	2021-06-11
Pictures	20
Listing price	<a href="#">View report</a>



source: [autotrader.co.uk](#)



## MOT history

MOT expiry date	2024-11-16
MOT pass rate	73 %
MOT passed	11
Failed MOT tests	4
Total advice items	18
Total items failed	8

MOT #15	2023-11-13 16:03
MOT test number	696210604183
Result	✓ Passed
Next expiry date	2024-11-16

MOT #14	2023-11-11 12:25
MOT test number	723051103642
Result	✗ Failed
Fail	Offside Outer Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))
Fail	Bonnet primary retaining device ineffective (3.1 (c))
Fail	Offside Front Lower Coil spring fractured or broken (5.3.1 (b) (i))

MOT #13	2022-11-01 12:00
MOT test number	831461014004
Result	✓ Passed
Advice	Nearside Front Shock absorbers has light misting of oil (5.3.2 (b))
Advice	Rear items on rear seats preventing seat belt check

**MOT #12**

2021-11-05 10:32

**MOT test number**

734705301730

**Result**

✓ Passed

**Advice** Nearside Rear Service brake binding but not excessively BRAKE PADS WORN MORE THAN O/S/R (1.2.1 (f))

**Advice** Offside Front Nail in tyre

**Advice** Nearside Front Nail in tyre

**MOT #11**

2021-11-04 13:09

**MOT test number**

678419888980

**Result**

✗ Failed

**Advice** Offside Front Nail in tyre

**Advice** Nearside Rear Service brake binding but not excessively BRAKE PADS WORN MORE THAN O/S/R (1.2.1 (f))

**Advice** Nearside Front Nail in tyre

**Minor** Offside Rear Position lamp with a multiple light source up to 1/2 not functioning (4.2.1 (a) (i))

**Fail** Offside Rear Shock absorbers has a serious fluid leak (5.3.2 (b))

**MOT #10**

2020-10-20 11:30

**MOT test number**

213867715701

**Result**

✓ Passed

**Advice** Nearside Front Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))

**MOT #9**

2020-10-19 15:10

**MOT test number**

574951251414

**Result**

✗ Failed

**Advice** Nearside Front Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))

**Advice** Offside Front Tyre has a cut but not deep enough to reach the ply or cords no tread at inner edge (5.2.3 (d) (i))

**Fail** Nearside Front Tyre has ply or cords exposed (5.2.3 (d) (ii))

**MOT #8** 2019-10-22 14:16**MOT test number** 976381973081**Result** ✓ Passed**Advice** Offside Rear Service brake binding but not excessively (1.2.1 (f))**Advice** Nearside Rear Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))**MOT #7** 2018-11-08 12:17**MOT test number** 215840349996**Result** ✓ Passed**MOT #6** 2018-11-06 09:36**MOT test number** 600937385885**Result** ✗ Failed**Fail** Nearside Front Upper Anti-roll bar ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))**Fail** Offside Front Shock absorbers has a serious fluid leak (5.3.2 (b))**Fail** Offside Front Upper Anti-roll bar ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))**MOT #5** 2017-11-07 11:06**MOT test number** 566487524586**Result** ✓ Passed**MOT #4** 2016-11-17 15:16**MOT test number** 998972809184**Result** ✓ Passed**Advice** Engine cover/under-trays obscuring some components**Advice** Undetected Peak on Emissions test



MOT #3	2015-11-10 14:52
MOT test number	409041940986
Result	✓ Passed

MOT #2	2014-11-07 11:26
MOT test number	867011114355
Result	✓ Passed
<div><div>Notice</div> N/s rear tyre worn low</div> <div><div>Notice</div> Front number plate deteriorated</div>	

MOT #1	2013-10-22 14:12
MOT test number	847075693294
Result	✓ Passed



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 August 2024

✓  
**MOT**  
**Expires:**  
16 November 2024

<b>Tax status</b>	Valid until 1 August
<b>Days left</b>	94
<b>MOT expiry date</b>	16 November 2024
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	49
<b>Band</b>	C
<b>Single payment (12 months)</b>	£ 35,00,-
<b>Single six month payment</b>	Not applicable
<b>Total payable by 12 monthly instalments</b>	£ 36,75,-



Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >





Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this VOLKSWAGEN had different number plates.

Number of plates	1
Current registration	 <b>DE10UPN</b>
Plate since	2019-03-29
Current registration	 <b>DE10UPN</b>
Plate since	2019-03-29

More info >



Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLKSWAGEN is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	19
First mileage registration	2010-05-27
Last registration	2023-11-13
Complete history	<a href="#">See info</a>



Registration #1	2010-05-27	28 mi
Registration #2	2013-10-22	36.127 mi
Registration #3	2014-11-07	47.731 mi
Registration #4	2015-11-10	54.593 mi
Registration #5	2016-11-17	61.838 mi
Registration #6	2017-11-07	66.932 mi
Registration #7	2018-11-06	73.076 mi
Registration #8	2018-11-08	73.136 mi
Registration #9	2019-10-22	81.480 mi
Registration #10	2020-10-19	92.434 mi
Registration #11	2020-10-20	92.434 mi
Registration #12	2020-10-21	92.434 mi
Registration #13	2020-10-22	92.434 mi
Registration #14	2020-10-23	92.434 mi
Registration #15	2020-10-24	92.434 mi
Registration #16	2020-10-25	92.434 mi
Registration #17	2020-10-26	92.434 mi
Registration #18	2020-10-27	92.434 mi
Registration #19	2020-10-28	92.434 mi

More info >



Car features

The VOLKSWAGEN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLKSWAGEN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	97%
Children	84%
Pedestrian	61%
Safety systems	71%
Overall rating	85%
Video	<a href="#">see crash video</a>



Dimensions & weight

Width	1786 mm
Height	1479 mm
Length	4199 mm
Wheel base	2578 mm
Kerb weight	1266 kg
Max. allowed weight	1870 kg

Additional information

Fuel delivery	Direct Injection
Number of doors	3
Number of seats	5

Number of axles	2
Engine number	CAY 211766