





General information

Make	CITROEN
Model	XSARA HDI DESIRE PICASSO E4
Colour	Black
Year of manufacture	-
Top speed	109 mph
0 - 60 mph	13.8 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	89 BHP
Max. torque	215 Nm at 1.750 rpm
Cylinders	4
Fuel type	Diesel
Consumption city	43.5 mpg
Consumption extra urban	65.7 mpg
Consumption combined	55.4 mpg





Internet history

Entry 1

Date Pictures 2022-01-11

14

Listing price

View report



source: autotrader.co.uk



MOT history

MOT #17	2022-01-08 12:04	
MOT test number	790878981980	
Result	✓ Passed	
Next expiry date	2023-01-28	
Advice Spare wheel missing, carrier loose		
Minor Nearside Front Lower Suspension arm ball joint dust cover severely deteriorated (5.3.4 (b) (i))		
Advice Nearside Front Suspension arm ball joint has slight play (5.3.4 (a) (i))		
Advice Tyre worn close to legal limit/worn on edge all four (5.2.3 (e))		
Advice Offside sill has paint blisters		

MOT #16			2022-01-08 12:04
MOT test	number		205104993890
Result			🗙 Failed
Pass w	th rectification	Offside Headlamp aim projected beam image is ob	oviously incorrect (4.1.2 (c))
Advice	Spare wheel mis	sing, carrier loose	
Advice	Tyre worn close	to legal limit/worn on edge all four (5.2.3 (e))	
Advice Nearside Front Suspension arm ball joint has slight play (5.3.4 (a) (i))			
Advice	Offside sill has p	aint blisters	
Minor	Nearside Front Lo	wer Suspension arm ball joint dust cover severely d	eteriorated (5.3.4 (b) (i))

МОТ #15	2021-01-26 17:03
MOT test number	278964550206
Result	✓ Passed
Advice Clutch pedal anti-slip pad missing	





MOT #14	2021-01-25 08:57
MOT test number	800147350934
Result	🗙 Failed
Fail Offside Headlamp not working on dipped beam (4.1.1 (a) (ii))	
Minor Offside Registration plate lamp inoperative in the case of multiple lamps or light s (i))	ources (4.7.1 (b)
FailRear fog lamp switch inoperative (4.5.3 (a) (ii))	
Fail Nearside Front Anti-roll bar linkage ball joint excessively worn (5.3.4 (a) (i))	
Fail Windscreen washer not working (3.5 (a))	
Fail Central Rear Passenger's seat insecure (6.2.6 (a) (ii))	
FailOffside Rear fog lamp not working (4.5.1 (a) (ii))	
Fail Brake pedal anti-slip provision missing (1.1.2 (c))	
Fail Exhaust emissions exceed manufacturer's specified limit 1.8m3 (8.2.2.2 (a))	
Advice Clutch pedal anti-slip pad missing	

MOT #13		2020-01-29 16:13
MOT test i	number	505595481570
Result		✓ Passed
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice	Clutch pedal anti-slip pad missing	
Advice	Nearside Front Tyre worn close to legal limit/worn on edge 185/65 15 (5.2.3 (e))	





MOT #12	2020-01-29 08:49
MOT test number	349353137781
Result	🗙 Failed
Fail Exhaust emissions exceed manufacturer's specified limit 1.8 m3 (8.2.2.2 (a))	
Advice Nearside Front Tyre worn close to legal limit/worn on edge 185/65 15 (5.2.3 (e))	
Fail Offside Front Anti-roll bar linkage ball joint excessively worn (5.3.4 (a) (i))	
Advice Items removed from driver's view prior to test	
Advice Clutch pedal anti-slip pad missing	
Fail Windscreen washer provides insufficient washer liquid (3.5 (a))	
Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	

MOT #11	2019-01-26 10:02
MOT test number	641914904051
Result	✓ Passed

MOT #10		2019-01-26 10:02
MOT test number		877532951867
Result		🗙 Failed
Pass with rectification	Nearside Front Position lamp not working (4.2.1 (a))	

МОТ #9	2018-01-23 12:53
MOT test number	106270129457
Result	✓ Passed

MOT #8	2018-01-23 10:58
MOT test number	120382293419
Result	🗙 Failed
Fail Nearside Front Front wheel bearing rough when rotated (2.5.A.2)	





MOT #7		2017-01-16 10:16
MOT test	number	437539544222
Result		✓ Passed
Advice	Oil leak	
Advice	Nearside Front Anti-roll bar linkage has slight play in a ball joint (2.4.G.2)	

MOT #6	2016-	01-19 12:55
MOT test	number 77	9361514296
Result		🗸 Passed
Advice Sounds like exhaust has slight blow from front but covered by under tray so unable to see		see

MOT #	5	2016-01-18 17:26	
MOT te	est number	211208424002	
Result		🗙 Failed	
Fail	Offside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)		
Fail	Fail Nearside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)		
Fail	Fail Offside Rear Tyre has ply or cords exposed Perished and split (4.1.D.1b)		
Advice Sounds like exhaust has slight blow from front but covered by under tray so unable to see			
Fail	Windscreen washer provides insufficient washer liquid (8.2.3)		

MOT #4	2015-01-28 16:03
MOT test number	316818925085
Result	✓ Passed
МОТ #3	2014-05-07 13:04
MOT test number	467957024105
Result	✓ Passed





MOT #2	2013-05-08 13:52
MOT test number	219348723429
Result	✓ Passed
MOT #1	2012-04-05 11:59
MOT test number	147836592483
Result	✓ Passed
Advice Offside Front Tyre worn close to the legal limit (4.1.E.1)	





Damage history

Check the damage history for this CITROEN. See if, where and when this CITROEN had damage and the car repair costs. We also check if this CITROEN was scrapped. Download the premium report <u>here</u> for the results.

-
AMP
- A

Extra CITROEN salvage check

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.





Vehicle valuation

What is this car worth? See the vehicle value of this CITROEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	6.00.000
Auction value	4 11.111
Average private trade value	4 10 200





Owner history

For how long did the current and previous owner(s) have this CITROEN? How many owners did this CITROEN have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>.

	More info >
Plate changes	
See in this check if this CITROEN had different number plates.	
Number of plates	
Carrent registration	
Plate since	
Current registration	
Plate since	





Finance check

Check if this CITROEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this CITROEN has been settled.

If not, and you buy this CITROEN then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this CITROEN is financed.


Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	





Mileage check

Odometer	In miles
Mileage registrations	19
First mileage registration	2009-03-16
Last registration	2022-01-08
Complete history	See info



Registration #1	2009-03-16	22 mi
Registration #2	2012-04-05	40.865 mi
Registration #3	2013-05-08	47.449 mi
Registration #4	2014-05-07	54.400 mi
Registration #5	2015-01-28	56.030 mi
Registration #6	2016-01-18	65.267 mi
Registration #7	2016-01-19	65.267 mi
Registration #8	2017-01-16	75.423 mi
Registration #9	2018-01-23	85.031 mi
Registration #10	2018-01-23	85.031 mi
Registration #11		11.777 mi
Registration #12		11.777 esi
Registration #13		11.777 mi
Registration #14		11.777 esi
Registration #15		11.777 mi
Registration #16		11.777 esi
Registration #17		11.777 mi
Registration #18		11.777 est
Registration #19		





Safety ratings		
NCAP rating		0
Video	see crash video	
Dimensions & weight		
Width		1751 mm
Height		1637 mm
Length		4276 mm
Wheel base		2760 mm
Kerb weight		1300 kg
Max. allowed weight		1850 kg
Additional information		
Fuel tank capacity		60 I
Fuel delivery		Direct Injection
Number of doors		5
Number of seats		5
Number of axles		2
Engine number		JBAW3025790