



RENAULT




report date: 2024-03-29

General information

Make	RENAULT
Model	SCENIC DYNAMIQUE TOMTOM LUXE PACK DCI
Colour	Bronze
Year of manufacture	2012
Top speed	112 mph
Gearbox	6 speed Manual

Engine & fuel consumption

Power	110 BHP
Max. torque	240 Nm at 1.750 rpm
Engine capacity	1.461 cc
Cylinders	4
Fuel type	Diesel
Consumption city	51.4 mpg
Consumption extra urban	68.9 mpg
Consumption combined	61.4 mpg
CO2 emission	120 g/km
CO2 label	C






Internet history


Entry 1

Date	2021-12-25
Pictures	5
Listing price	View report



Video viewing
Book a video viewing with one of our team.
See the vehicle from the comfort of your own home.

[Visit our website for more info](#)





This dealer has signed up to our **Dealer Promise.**

- Free history check
- 6 months (minimum) MOT
- Free 12 months Breakdown cover

[aacars.com](#)





Click & Deliver
Complete your deal online or by phone.
Then arrange for the sanitised vehicle to be delivered to you.

[Visit our website for more info](#)





You're in safe hands
This dealer has signed our Dealer Promise



source: [cargurus.co.uk](#)



MOT history

MOT expiry date	2024-07-02
MOT pass rate	73 %
MOT passed	8
Failed MOT tests	3
Total advice items	27
Total items failed	4

MOT #11	2023-07-03 12:01
MOT test number	513469404413
Result	✓ Passed
Next expiry date	2024-07-02

MOT #10	2022-01-28 14:49
MOT test number	429437148215
Result	✓ Passed

MOT #9	2022-01-26 11:58
MOT test number	839441471339
Result	✗ Failed

Advice Nearside Rear Tyre worn close to legal limit/worn on edge wearing on outer edge (5.2.3 (e))

Fail Reversing lamp likely to become detached (4.6.1 (c) (ii))

**MOT #8**

2020-12-29 10:48

MOT test number

422266483647

Result

✓ Passed

- Advice** Offside Rear Child Seat fitted not allowing full inspection of adult belt
- Advice** Nearside Front Wheel bearing has slight play (5.1.3 (a) (i))
- Advice** Nearside Rear Tyre has a cut but not deep enough to reach the ply or cords (5.2.3 (d) (i))
- Advice** Offside Rear Direction indicator slightly discoloured (4.4.3 (a))
- Advice** Offside Front Anti-roll bar ball joint has slight play (5.3.4 (a) (i))
- Advice** Nearside Rear Direction indicator slightly discoloured (4.4.3 (a))
- Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #7

2020-12-29 10:48

MOT test number

999348298249

Result

✗ Failed

- Pass with rectification** Nearside Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))
- Advice** Nearside Front Wheel bearing has slight play (5.1.3 (a) (i))
- Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Nearside Rear Tyre has a cut but not deep enough to reach the ply or cords (5.2.3 (d) (i))
- Advice** Offside Rear Child Seat fitted not allowing full inspection of adult belt
- Advice** Offside Rear Direction indicator slightly discoloured (4.4.3 (a))
- Pass with rectification** Nearside Front Headlamp aim projected beam image is obviously incorrect (4.1.2 (c))
- Advice** Offside Front Anti-roll bar ball joint has slight play (5.3.4 (a) (i))
- Advice** Nearside Rear Direction indicator slightly discoloured (4.4.3 (a))

**MOT #6** 2019-12-21 10:34**MOT test number** 321027705559**Result** ✓ Passed

- Advice** Under trays fitted obscuring components
- Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Offside Front Anti-roll bar pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
- Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))

MOT #5 2018-12-22 08:43**MOT test number** 513747569856**Result** ✓ Passed

- Advice** Offside Front Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))
- Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Offside Rear Child Seat fitted not allowing full inspection of adult belt

MOT #4 2017-12-23 09:23**MOT test number** 893837974330**Result** ✓ Passed

- Advice** Nearside Rear Child Seat fitted not allowing full inspection of adult belt

MOT #3 2016-12-28 10:19**MOT test number** 789281533390**Result** ✓ Passed

- Advice** Nearside Rear Child Seat fitted not allowing full inspection of adult belt
- Advice** Nearside Front Nail in tyre



MOT #2	2015-12-31 10:39
MOT test number	912163858009
Result	✓ Passed

MOT #1	2015-12-29 13:00
MOT test number	862298589722
Result	✗ Failed

- Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)
- Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)
- Fail** Nearside Front Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (4.1.D.1a)



Tax & MOT check

✓
Taxed
Tax due:
1 January 2025

✓
MOT
Expires:
2 July 2024

Tax status	Valid until 1 January
Days left	246
MOT expiry date	2 July 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	C
Single payment (12 months)	£ 35,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 36,75,-



Damage history

Check the damage history for this RENAULT. See if, where and when this RENAULT had damage and the car repair costs. We also check if this RENAULT was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra RENAULT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this RENAULT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this RENAULT? How many owners did this RENAULT have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this RENAULT had different number plates.

Number of plates	1
Current registration	*****
Plate since	2023-03-29
Current registration	*****
Plate since	2023-03-29

More info >



Finance check

Check if this RENAULT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this RENAULT has been settled.

If not, and you buy this RENAULT then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this RENAULT is financed.

Finance company	RENAULT	2024
Date of agreement	RENAULT	2024
Agreement type	RENAULT	2024
Agreement term	RENAULT	2024
Agreement number	RENAULT	2024
Contact info	RENAULT	2024

More info >



Mileage check

Odometer	In miles
Mileage registrations	13
First mileage registration	2012-12-22
Last registration	2023-07-03
Complete history	See info



Registration #1	2012-12-22	23 mi
Registration #2	2015-12-29	30.963 mi
Registration #3	2015-12-31	30.993 mi
Registration #4	2016-12-28	38.913 mi
Registration #5	2017-12-23	47.252 mi
Registration #6	2018-12-22	55.484 mi
Registration #7	2019-12-21	65.168 mi
Registration #8	2020-05-29	75.277 mi
Registration #9	2020-05-29	75.277 mi
Registration #10	2020-05-29	75.277 mi
Registration #11	2020-05-29	75.277 mi
Registration #12	2020-05-29	75.277 mi
Registration #13	2020-05-29	75.277 mi

More info >



Car features

The RENAULT factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete RENAULT factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1845 mm
Height	1640 mm
Length	4366 mm
Max. allowed weight	1964 kg

Additional information

Number of seats	5
Number of axles	2
Engine number	D076130