



RENAULT

CA100JG

report date: 2024-03-28

General information

Make	RENAULT
Model	TRAFIC SL27 DCI 115 SWB P/V
Colour	Silver
Year of manufacture	2010
Top speed	99 mph
0 - 60 mph	15.0 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	115 BHP
Max. torque	240 Nm at 1.600 rpm
Engine capacity	1.995 cc
Cylinders	4
Fuel type	Diesel
Consumption city	28.8 mpg
Consumption extra urban	40.4 mpg
Consumption combined	35.8 mpg





Internet history

Entry 1

Date	2021-10-22
Pictures	12
Listing price	<a href="#">View report</a>



source: cargurus.co.uk



## MOT history

MOT expiry date	2024-10-21
MOT pass rate	63 %
MOT passed	12
Failed MOT tests	7
Total advice items	49
Total items failed	17

MOT #19 2023-10-18 14:09

MOT test number 270756548091

Result ✓ Passed

Next expiry date 2024-10-21

- Advice** Nearside washer jet not working
- Advice** Nearside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))
- Advice** Nearside Child Seat fitted not allowing full inspection of adult belt
- Advice** Offside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))

MOT #18 2023-10-14 07:33

MOT test number 623516411328

Result ✗ Failed

- Fail** Nearside Front Lower Anti-roll bar ball joint excessively worn (5.3.4 (a) (i))
- Advice** Nearside Child Seat fitted not allowing full inspection of adult belt
- Fail** Stop lamp(s) all not working (4.3.1 (a) (iii))
- Advice** Nearside washer jet not working
- Minor** Nearside Front Lower Anti-roll bar ball joint dust cover severely deteriorated (5.3.4 (b) (i))
- Fail** Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii))
- Fail** Nearside Front Lower Suspension arm ball joint excessively worn (5.3.4 (a) (i))

**MOT #17**

2022-10-13 08:04

**MOT test number**

953059300343

**Result**

✓ Passed

- Advice** Offside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))
- Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Advice** Nearside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))
- Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Advice** Oil leak, but not excessive (8.4.1 (a) (i))

**MOT #16**

2021-10-22 17:04

**MOT test number**

301300848867

**Result**

✓ Passed

**MOT #15**

2021-09-03 09:41

**MOT test number**

938984447015

**Result**

✓ Passed

**MOT #14**

2021-08-26 15:38

**MOT test number**

446507916091

**Result**

✗ Failed

- Fail** Offside Obligatory mirror seriously damaged, affecting the rear view (3.3 (b) (ii))
- Advice** Nearside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))
- Advice** Offside Rear Wheel bearing slightly noisy (5.1.3 (b) (i))
- Fail** Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))
- Advice** Nearside Rear Shock absorbers has a slightly worn bush (5.3.2 (c))
- Advice** Front Brake pipe corroded, covered in grease or other material both (1.1.11 (c))

**MOT #13**

2020-09-23 13:56

**MOT test number**

544796381032

**Result**

✓ Passed

- Advice** Rear Tyre slightly damaged/cracking or perishing Both rear inner sidewalls (5.2.3 (d) (ii))
- Advice** Offside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))
- Advice** Nearside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))
- Advice** Nearside Front Inner Anti-roll bar pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

**MOT #12**

2020-09-23 08:28

**MOT test number**

456420004441

**Result**

✗ Failed

- Advice** Nearside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))
- Fail** Offside Front Suspension arm ball joint excessively worn (5.3.4 (a) (i))
- Fail** Offside Front Position lamp not working (4.2.1 (a) (ii))
- Advice** Rear Tyre slightly damaged/cracking or perishing Both rear inner sidewalls (5.2.3 (d) (ii))
- Advice** Offside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))
- Advice** Nearside Front Inner Anti-roll bar pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

**MOT #11**

2019-08-31 08:55

**MOT test number**

885843055987

**Result**

✓ Passed

- Advice** Brake pipe corroded, covered in grease or other material Both rear's to hoses (1.1.11 (c))
- Advice** Offside Front Lower Suspension arm ball joint has slight play (5.3.4 (a) (i))
- Advice** Nearside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))
- Minor** Hazard warning switch faulty (4.4.2 (a) (i))

**MOT #10**

2019-08-23 12:43

**MOT test number**

793507070886

**Result**

✗ Failed

**Fail** Nearside Front Inner Suspension arm pin or bush excessively worn Rear bush (5.3.4 (a) (i))**Advice** Nearside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))**Fail** Offside Front Seat belt buckle not functioning as intended (7.1.2 (d))**Minor** Hazard warning switch faulty (4.4.2 (a) (i))**Fail** Nearside Front Lower Suspension arm ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))**Advice** Brake pipe corroded, covered in grease or other material Both rear's to hoses (1.1.11 (c))**Advice** Offside Front Lower Suspension arm ball joint has slight play (5.3.4 (a) (i))**Fail** Brake pipe excessively corroded Both front to rear (At rear) (1.1.11 (c))**MOT #9**

2018-08-14 12:27

**MOT test number**

678472116905

**Result**

✓ Passed

**Advice** Offside Rear Brake disc worn, pitted or scored, but not seriously weakened scored (1.1.14 (a) (ii))**Advice** Rear Brake pipe corroded, covered in grease or other material all corroded (1.1.11 (c))**Advice** Front Brake disc worn, pitted or scored, but not seriously weakened worn (1.1.14 (a) (ii))**MOT #8**

2017-08-15 10:33

**MOT test number**

380703447260

**Result**

✓ Passed

**Advice** Offside Rear Brake pad(s) wearing thin (3.5.1g)**Advice** Rear Brake pipe slightly corroded all steel (3.6.B.2c)

**MOT #7** 2016-07-27 14:47**MOT test number** 176801404162**Result** ✓ Passed**Advice** Nearside Front Anti-roll bar has slight play in a pin/bush D bush (2.4.G.2)**Advice** Vehicles internal headlight adjuster altered to recheck lights**MOT #6** 2016-07-26 12:22**MOT test number** 812053610451**Result** ✗ Failed**Fail** Nearside Front Track rod end ball joint has excessive play (2.2.B.1f)**Advice** Nearside Front Anti-roll bar has slight play in a pin/bush D bush (2.4.G.2)**Advice** Vehicles internal headlight adjuster altered to recheck lights**MOT #5** 2015-07-09 14:55**MOT test number** 389350095141**Result** ✓ Passed**Advice** Nearside Track rod end ball joint has slight play (2.2.B.1f)**MOT #4** 2014-07-09 12:53**MOT test number** 246310794475**Result** ✓ Passed



<b>MOT #3</b>	2014-07-08 14:14
<b>MOT test number</b>	995829284176
<b>Result</b>	✗ Failed
<b>Advice</b>	Front Brake pad(s) wearing thin (3.5.1g)
<b>Fail</b>	Rear fog lamp not working (1.3.2b)
<b>Fail</b>	Brake fluid warning lamp illuminated (3.6.G.2)
<b>Advice</b>	Rear Brake pad(s) wearing thin (3.5.1g)
<b>Fail</b>	Horn not loud enough to be heard by another road user (1.6.2b)

<b>MOT #2</b>	2013-07-04 12:15
<b>MOT test number</b>	407945083170
<b>Result</b>	✓ Passed
<b>Notice</b>	High line brake lamp not working
<b>Notice</b>	Accident damage to o/s/f bumper

<b>MOT #1</b>	2013-07-04 12:15
<b>MOT test number</b>	379235583195
<b>Result</b>	✗ Failed
<b>Notice</b>	High line brake lamp not working
<b>Pass with rectification</b>	Rear fog lamp not working (1.3.2b)
<b>Notice</b>	Accident damage to o/s/f bumper





Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 April 2025

✓  
**MOT**  
**Expires:**  
21 October 2024

Tax status		Valid until 1 April
Days left		337
MOT expiry date		21 October 2024
Full MOT history		<a href="#">See MOT history</a>



Damage history

Check the damage history for this RENAULT. See if, where and when this RENAULT had damage and the car repair costs. We also check if this RENAULT was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra RENAULT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this RENAULT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,299
Auction value	£ 19,299
Average private trade value	£ 19,299

More info >



Owner history

For how long did the current and previous owner(s) have this RENAULT? How many owners did this RENAULT have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this RENAULT had different number plates.

Number of plates	1
Current registration	<b>XXXXXX</b>
Plate since	2024-03-28
Current registration	<b>XXXXXX</b>
Plate since	2024-03-28

More info >



Finance check

Check if this RENAULT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this RENAULT has been settled.

If not, and you buy this RENAULT then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this RENAULT is financed.

Finance company	RENAULT	2024
Date of agreement	RENAULT	2024
Agreement type	RENAULT	2024
Agreement term	RENAULT	2024
Agreement number	RENAULT	2024
Contact info	RENAULT	2024

More info >



Mileage check

Odometer	In miles
Mileage registrations	20
First mileage registration	2010-06-30
Last registration	2023-10-18
Complete history	<a href="#">See info</a>



Registration #1	2010-06-30	11 mi
Registration #2	2013-07-04	19.915 mi
Registration #3	2014-07-08	33.781 mi
Registration #4	2014-07-09	33.781 mi
Registration #5	2015-07-09	49.012 mi
Registration #6	2016-07-26	60.272 mi
Registration #7	2016-07-27	60.272 mi
Registration #8	2017-08-15	72.221 mi
Registration #9	2018-08-14	82.165 mi
Registration #10	2019-08-23	89.585 mi
Registration #11	2020-05-20	95.000 mi
Registration #12	2021-05-20	95.000 mi
Registration #13	2022-05-20	95.000 mi
Registration #14	2023-05-20	95.000 mi
Registration #15	2024-05-20	95.000 mi
Registration #16	2025-05-20	95.000 mi
Registration #17	2026-05-20	95.000 mi
Registration #18	2027-05-20	95.000 mi
Registration #19	2028-05-20	95.000 mi
Registration #20	2029-05-20	95.000 mi

More info >



Car features

The RENAULT factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete RENAULT factory list for this vehicle [here](#).

More info >

Dimensions & weight

Width	2232 mm
Height	1944 mm
Length	4782 mm
Kerb weight	1678 kg
Max. allowed weight	2770 kg

Additional information

Fuel tank capacity	90 l
Fuel delivery	Direct Injection
Number of doors	4
Number of seats	4
Number of axles	2
Engine number	C053829