



Mercedes-Benz



report date: 2024-03-29

General information

Make	MERCEDES-BENZ
Model	CLS CLS320 CDI
Colour	Black
Year of manufacture	-
Top speed	148 mph
0 - 60 mph	7.0 seconds
Gearbox	7 speed automatic

Engine & fuel consumption

Power	221 BHP
Max. torque	510 Nm at 2.800 rpm
Cylinders	6
Fuel type	Diesel
Consumption city	27.2 mpg
Consumption extra urban	47.9 mpg
Consumption combined	27.7 mpg




LABEL UNKNOWN



Internet history

Entry 1

Date	2021-07-09
Pictures	6
Listing price	View report



source: autotrader.co.uk

**MOT history**

MOT #17	2022-12-19 16:46
MOT test number	805396633511
Result	✓ Passed
Next expiry date	2023-12-18

MOT #16	2021-12-16 16:18
MOT test number	503486392770
Result	✓ Passed
Advice	Nearside Rear Tyre slightly damaged Sidewall (5.2.3 (d) (ii))
Minor	Offside Front Lower Suspension arm ball joint dust cover severely deteriorated (5.3.4 (b) (i))

MOT #15	2020-11-03 10:51
MOT test number	741963836108
Result	✓ Passed
Advice	Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
Advice	Offside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))
Advice	Offside Front Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Nearside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))
Advice	Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
Advice	Exhaust mounting defective (6.1.2 (a))

MOT #14	2019-10-14 14:20
MOT test number	616949064687
Result	✓ Passed
Advice	Nearside Front Road wheel slightly distorted (5.2.2 (c) (i))
Advice	Offside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))
Advice	Nearside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))

**MOT #13** 2018-10-24 09:15**MOT test number** 623908786720**Result** ✓ Passed

- Advice** Engine bay covers fitted preventing the inspection of some engine bay components
- Advice** Offside Rear Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))
- Advice** Underbody covers fitted preventing the inspection of some underbody components
- Advice** Items removed from driver's view prior to test

MOT #12 2017-10-20 10:45**MOT test number** 351204048151**Result** ✓ Passed

- Advice** Underbody covers fitted preventing the inspection of some underbody components
- Advice** Engine bay covers fitted preventing the inspection of some engine bay components

MOT #11 2016-10-19 10:26**MOT test number** 114712437857**Result** ✓ Passed

- Advice** Engine bay covers fitted preventing the inspection of some engine bay components
- Advice** Offside Front Outer Brake pipe slightly corroded close to flexi (3.6.B.2c)
- Advice** Nearside Rear Brake hose slightly deteriorated (3.6.B.4d)
- Advice** Underside covers fitted preventing the inspection of some underside components
- Advice** Nearside Rear Brake pipe slightly corroded (3.6.B.2c)
- Advice** Offside Rear Brake hose slightly deteriorated (3.6.B.4d)
- Advice** Nearside Front Front suspension has slight play in a upper suspension ball joint (2.5.B.1a)

**MOT #10** 2015-10-15 08:45**MOT test number** 255192308618**Result** ✓ Passed**Advice** Nearside Front Brake pipe slightly corroded to rear (3.6.B.2c)**MOT #9** 2014-10-22 11:02**MOT test number** 729425394225**Result** ✓ Passed**Notice** Centre exhaust bracket broken from exhaust, but exhaust is still supported.**MOT #8** 2013-11-11 15:49**MOT test number** 888285113392**Result** ✓ Passed**MOT #7** 2013-01-29 13:23**MOT test number** 355219323078**Result** ✓ Passed**MOT #6** 2013-01-28 09:24**MOT test number** 999038123031**Result** ✗ Failed**Fail** Nearside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)**Fail** Nearside Front Suspension arm has excessive play in a ball joint (2.4.G.2)**MOT #5** 2011-10-03 10:45**MOT test number** 705646271204**Result** ✓ Passed



MOT #4	2011-10-03 10:45
MOT test number	267616971267
Result	✗ Failed
Pass with rectification	Offside Windscreen wiper does not clear the windscreen effectively (8.2.2)
Pass with rectification	Nearside Windscreen wiper does not clear the windscreen effectively (8.2.2)

MOT #3	2010-10-11 10:36
MOT test number	132074580277
Result	✓ Passed
Advice	Offside Front wheel bearing has slight play (2.5.A.3c)

MOT #2	2009-10-01 14:50
MOT test number	423894379238
Result	✓ Passed

MOT #1	2008-10-20 09:32
MOT test number	303064098441
Result	✓ Passed



Damage history

Check the damage history for this MERCEDES-BENZ. See if, where and when this MERCEDES-BENZ had damage and the car repair costs. We also check if this MERCEDES-BENZ was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra MERCEDES-BENZ salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this MERCEDES-BENZ in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this MERCEDES-BENZ? How many owners did this MERCEDES-BENZ have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this MERCEDES-BENZ had different number plates.

Number of plates	1
Current registration	 DK55PGV
Plate since	2019-03-29
Current registration	 DK55PGV
Plate since	2019-03-29

More info >



Finance check

Check if this MERCEDES-BENZ is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MERCEDES-BENZ has been settled.

If not, and you buy this MERCEDES-BENZ then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this MERCEDES-BENZ is financed.

Finance company	REDACTED	REDACTED
Date of agreement	REDACTED	REDACTED
Agreement type	REDACTED	REDACTED
Agreement term	REDACTED	REDACTED
Agreement number	REDACTED	REDACTED
Contact info	REDACTED	REDACTED

More info >



Mileage check

Odometer	In miles
Mileage registrations	18
First mileage registration	2005-10-14
Last registration	2022-12-19
Complete history	See info



Registration #1	2005-10-14	14 mi
Registration #2	2008-10-20	33.509 mi
Registration #3	2009-10-01	41.057 mi
Registration #4	2010-10-11	48.002 mi
Registration #5	2011-10-03	55.333 mi
Registration #6	2013-01-28	71.176 mi
Registration #7	2013-01-29	71.177 mi
Registration #8	2013-11-11	78.662 mi
Registration #9	2014-10-22	88.362 mi
Registration #10	2015-10-22	98.362 mi
Registration #11	2016-10-22	108.362 mi
Registration #12	2017-10-22	118.362 mi
Registration #13	2018-10-22	128.362 mi
Registration #14	2019-10-22	138.362 mi
Registration #15	2020-10-22	148.362 mi
Registration #16	2021-10-22	158.362 mi
Registration #17	2022-10-22	168.362 mi
Registration #18	2023-10-22	178.362 mi

More info >



Car features

The MERCEDES-BENZ factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete MERCEDES-BENZ factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	2059 mm
Height	1403 mm
Length	4913 mm
Wheel base	2854 mm
Kerb weight	1815 kg
Max. allowed weight	2280 kg

Additional information

Fuel tank capacity	80 l
Fuel delivery	Direct Injection
Number of doors	4

Number of seats	4
Number of axles	2
Engine number	64292040047905