





General information

| Make | PEUGEOT |
|---------------------|----------------|
| Model | 208 ALLURE |
| Colour | Grey |
| Year of manufacture | 2018 |
| Top speed | 111 mph |
| Gearbox | 5 speed Manual |

Engine & fuel consumption

| Power | 82 BHP | 0 < 101 A |
|-------------------------|---------------------|---------------|
| Max. torque | 118 Nm at 2.750 rpm | 101 - 120 B |
| Engine capacity | 1.200 cc | 121 - 140 P |
| Cylinders | 3 | 141 - 165 F G |
| Fuel type | Petrol | 166 - 185 H |
| Consumption city | 51.4 mpg | 186 - 225 J |
| Consumption extra urban | 72.4 mpg | 225+ L |
| Consumption combined | 62.8 mpg | |
| CO2 emission | 104 g/km | |
| CO2 label | В | |
| | | |





| Internet history | |
|------------------|-------------|
| Entry 1 | |
| Date | 2021-05-31 |
| Pictures | 1 |
| Listing price | View report |



source: autoonline.co.uk



MOT history

| MOT expiry date | 2025-03-30 |
|--------------------|------------|
| MOT pass rate | 67 % |
| MOT passed | 4 |
| Failed MOT tests | 2 |
| Total advice items | 10 |
| Total items failed | 0 |

| MOT #6 | | 2024-03-15 14:40 |
|---|--|------------------|
| MOT test | number | 991771283308 |
| Result | | ✓ Passed |
| Next expi | ry date | 2025-03-30 |
| Advice Nearside Front Tyre worn close to legal limit/worn on edge worn outer edge (5.2.3 (e)) | | |
| Advice | Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e)) | |

| МОТ #5 | 2024-03-15 09:36 | |
|---|------------------|--|
| MOT test number | 288847864854 | |
| Result | 🗙 Failed | |
| Advice Nearside Front Tyre worn close to legal limit/worn on edge worn outer edge (5.2.3 (e)) | | |
| DANGEROUS Offside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e)) | | |
| Advice Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e)) | | |

| МОТ #4 | 2023-03-17 12:20 |
|-----------------|------------------|
| MOT test number | 289690910307 |
| Result | ✓ Passed |





| MOT #3 | 2022-03-29 14:04 |
|---|---------------------------------------|
| MOT test number | 771489034999 |
| Result | ✓ Passed |
| Advice Nearside Rear evidence of impact damage to wheel arch are | ea |
| MOT #2 | 2022-03-29 07:42 |
| MOT test number | 161481363432 |
| Result | 🗙 Failed |
| Advice Nearside Rear evidence of impact damage to wheel arch are | |
| DANGEROUSNearside Front Tyre has ply or cords exposed Worn a65 X 15 T) (5.2.3 (d) (ii)) | t outer eage of the tread width (1857 |
| MOT #1 | 2021-03-09 10:28 |
| MOT test number | 374808301035 |
| Result | Passed |

Advice Offside Rear Muck deflector insecure.

Advice Nearside Front Tyre worn close to legal limit/worn on edge worn outer edge. (5.2.3 (e))



Tax & MOT check

| √ Taxed | ✓ MOT |
|-------------------------|---------------------------|
| Tax due: 1 June 2024 | Expires: 30 March 2025 |
| Tax status | Valid until 1 June |
| Days left | 33 |
| MOT expiry date | 30 March 2025 |
| Full MOT history | See MOT history |

Tax calculation

| Vehicle class | 48 |
|-------------------------------|------------|
| Band | F |
| First licence fee (12 months) | £ 185,00,- |
| Standard rate (12 months) | £ 180,00,- |
| Standard rate (6 months) | £ 99,00,- |
| Premium rate (12 months) | £ 570,00,- |
| Premium rate (6 months) | £ 313,50,- |





Damage history

Check the damage history for this PEUGEOT. See if, where and when this PEUGEOT had damage and the car repair costs. We also check if this PEUGEOT was scrapped. Download the premium report <u>here</u> for the results.

| Damage 1 | |
|----------|--|
| Date | FET I |
| Category | 4 DEMPE |
| Туре | |
| Domore 2 | ampti |
| Damage 2 | 6 Cott- Don |
| Date | 1. Contraction of the second s |
| Category | AMP |
| Туре | |

Extra PEUGEOT salvage check

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.





Vehicle valuation

What is this car worth? See the vehicle value of this PEUGEOT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

| Trade retail value | 6.00.000 |
|-----------------------------|----------|
| Auction value | 4 10.000 |
| Average private trade value | 4 11 711 |





Owner history

For how long did the current and previous owner(s) have this PEUGEOT? How many owners did this PEUGEOT have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>.

| and and a second s | |
|--|-------------|
| ********** | |
| ******* | |
| ****** | |
| ********* | |
| ******* | |
| | More info > |
| Plate changes | |
| See in this check if this PEUGEOT had different number plates. | |
| Number of plates | , |
| Correct registration | |
| Plate since | |
| Current registration | |
| Plate since | |
| | |





Finance check

Check if this PEUGEOT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this PEUGEOT has been settled.

If not, and you buy this PEUGEOT then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this PEUGEOT is financed.


| Finance company | |
|-------------------|--|
| Date of agreement | |
| Agreement type | |
| Agreement term | |
| Agreement number | |
| Contact info | |





Mileage check

| In miles |
|------------|
| 8 |
| 2018-03-31 |
| 2024-03-15 |
| See info |
| |



| Registration #1 | 2018-03-31 | 28 mi |
|-----------------|------------|------------|
| Registration #2 | 2021-03-09 | 17.835 mi |
| Registration #3 | | 11.777 mi |
| Registration #4 | 2022-03-29 | 22.679 mi |
| Registration #5 | | 11.777 esi |
| Registration #6 | | 11.777 esi |
| Registration #7 | | 11.777 esi |
| Registration #8 | | 10.000 est |





Car features

| 50225 | Air conditioning |
|-------|------------------|
| 50295 | |
| 50482 | |
| 50501 | |
| 60566 | |
| 60567 | |
| 60569 | |

Safety ratings

| NCAP rating | **** |
|----------------|-----------------|
| Adult | 88% |
| Children | 78% |
| Pedestrian | 61% |
| Safety systems | 83% |
| Overall rating | 80% |
| Video | see crash video |



| Dimensions & weight | |
|-----------------------------------|------------------|
| Width | 1739 mm |
| Height | 1460 mm |
| Length | 3973 mm |
| Wheel base | 2538 mm |
| Kerb weight | 975 kg |
| Max. allowed weight | 1546 kg |
| Additional information | |
| Fuel tank capacity | 50 I |
| Fuel delivery | Direct Injection |
| Number of doors | 5 |
| Number of seats CarCheck.co.uk | 5 page 11/11 |

| Number of axles | 2 |
|-----------------|-------------|
| Engine number | B2170444026 |