



HONDA



SLI5YED


report date: 2024-03-29

General information

Make	HONDA
Model	CIVIC I-VTEC SPORT
Colour	Blue
Year of manufacture	2015
Top speed	134 mph
Gearbox	6 speed Manual

Engine & fuel consumption

Power	140 BHP
Max. torque	174 Nm at 4.300 rpm
Engine capacity	1.798 cc
Cylinders	4
Fuel type	Petrol
Consumption city	37.2 mpg
Consumption extra urban	54.3 mpg
Consumption combined	46.3 mpg
CO2 emission	145 g/km
CO2 label	F





Internet history

Entry 1

Date	2021-01-31
Pictures	10
Listing price	View report



source: autoonline.co.uk

**MOT history**

MOT expiry date	2024-07-08
MOT pass rate	86 %
MOT passed	6
Failed MOT tests	1
Total advice items	12
Total items failed	4

MOT #7 2023-07-07 11:31**MOT test number** 858209002053**Result** Passed**Next expiry date** 2024-07-08

Advice Rear Suspension component mounting prescribed area is corroded but not considered excessive rear axle mounting area corroded (5.3.6 (a) (i))

Advice Offside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement lower arm front bush perished (5.3.4 (a) (i))

Advice Rear Brake hose has slight corrosion to ferrule (1.1.12 (f) (i))

Advice Nearside Rear Tyre has a cut but not deep enough to reach the ply or cords (5.2.3 (d) (i))

Advice Nearside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement lower arm front bush perished (5.3.4 (a) (i))

Advice Nearside Front Road wheel slightly distorted (5.2.2 (c) (i))

Advice Rear Suspension component corroded but not seriously weakened Rear axle corroded (5.3.3 (b) (i))

Advice Offside Rear Tyre has a cut but not deep enough to reach the ply or cords (5.2.3 (d) (i))

MOT #6 2022-06-30 12:56**MOT test number** 128903040809**Result** Passed

Advice Nearside Front Tyre slightly damaged/cracking or perishing sidewall damage /deteriorated (5.2.3 (d) (ii))

Advice Under body covers fitted

**MOT #5** 2022-06-30 08:35**MOT test number** 602949768188**Result** ✗ Failed**Fail** Nearside Rear Tyre has a tear, caused by separation or partial failure of its structure sidewall perished /damage (5.2.3 (d) (ii))**Fail** Anti-lock braking system warning lamp indicates an ABS fault (1.6 (b))**Fail** Offside Front Tyre has a tear, caused by separation or partial failure of its structure inner sidewalls split deteriorated (5.2.3 (d) (ii))**Advice** Nearside Front Tyre slightly damaged/cracking or perishing sidewall damage /deteriorated (5.2.3 (d) (ii))**Advice** Under body covers fitted**Pass with rectification** Windscreen washer provides insufficient washer liquid (3.5 (a))**MOT #4** 2021-06-14 13:50**MOT test number** 241132551822**Result** ✓ Passed**MOT #3** 2020-07-09 13:39**MOT test number** 804291929729**Result** ✓ Passed**MOT #2** 2019-06-03 12:09**MOT test number** 303817492085**Result** ✓ Passed**MOT #1** 2018-06-28 08:21**MOT test number** 292021968634**Result** ✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 February 2025

✓
MOT
Expires:
8 July 2024

Tax status	Valid until 1 February
Days left	279
MOT expiry date	8 July 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	F
Single payment (12 months)	£ 200,00,-
Single six month payment	£ 110,00,-
Total payable by 12 monthly instalments	£ 210,00,-



Damage history

Check the damage history for this HONDA. See if, where and when this HONDA had damage and the car repair costs. We also check if this HONDA was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra HONDA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this HONDA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 15,200
Auction value	£ 15,200
Average private trade value	£ 15,200

More info >



Owner history

For how long did the current and previous owner(s) have this HONDA? How many owners did this HONDA have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To

More info >

Plate changes

See in this check if this HONDA had different number plates.

Number of plates	1
Current registration	
Plate since	2015-03-29
Current registration	
Plate since	2015-03-29

More info >



Finance check

Check if this HONDA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this HONDA has been settled.

If not, and you buy this HONDA then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this HONDA is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	9
First mileage registration	2015-06-25
Last registration	2023-07-07
Complete history	See info



Registration #1	2015-06-25	10 mi
Registration #2	2018-06-28	22.651 mi
Registration #3	2019-06-03	28.112 mi
Registration #4	2020-07-09	32.869 mi
Registration #5	2021-06-25	35.277 mi
Registration #6	2022-06-25	35.277 mi
Registration #7	2022-06-25	35.277 mi
Registration #8	2022-06-25	35.277 mi
Registration #9	2023-07-07	35.277 mi

More info >



Safety ratings

NCAP rating	★★★★★
Adult	94%
Children	83%
Pedestrian	69%
Safety systems	86%
Overall rating	86%
Video	see crash video



Dimensions & weight

Width	1770 mm
Height	1470 mm
Length	4370 mm
Wheel base	2595 mm
Kerb weight	1341 kg
Max. allowed weight	1750 kg

Additional information

Fuel tank capacity	50 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5
Number of axles	2
Engine number	R18Z44002468