



report date: 2024-03-29

General information

Make	VOLKSWAGEN
Model	EOS TSI
Colour	Silver
Year of manufacture	2008
Top speed	122 mph
0 - 60 mph	10.9 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	122 BHP
Max. torque	200 Nm at 1.500 rpm
Engine capacity	1.390 cc
Cylinders	4
Fuel type	Petrol
Consumption city	32.5 mpg
Consumption extra urban	50.4 mpg
Consumption combined	42.2 mpg
CO2 emission	159 g/km
CO2 label	G






Internet history

Entry 2

Date	2022-03-07
Pictures	4
Listing price	View report



source: cargurus.co.uk

Entry 1

Date	2021-10-07
Pictures	0
Listing price	View report

source: autotrader.co.uk



MOT history

MOT expiry date	2024-07-30
MOT pass rate	80 %
MOT passed	12
Failed MOT tests	3
Total advice items	21
Total items failed	5

MOT #15	2023-07-31 08:39
MOT test number	548904783578
Result	✓ Passed
Next expiry date	2024-07-30
Advice	Nearside Front Tyre worn close to legal limit/worn on edge 215/55/16/w (5.2.3 (e))
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))

MOT #14	2023-07-28 08:20
MOT test number	121280196187
Result	✗ Failed
Advice	Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))
Fail	Nearside Rear Tyre tread depth below requirements of 1.6mm (5.2.3 (e))
Advice	Nearside Front Tyre worn close to legal limit/worn on edge 215/55/16/w (5.2.3 (e))
Fail	Offside Rear Tyre has ply or cords exposed (5.2.3 (d) (ii))
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**MOT #13** 2022-06-10 15:10**MOT test number** 273182758609**Result** ✓ Passed**Advice** Rear Inner Tyre worn close to legal limit/worn on edge BOTH (5.2.3 (e))**MOT #12** 2019-12-23 14:14**MOT test number** 328727225844**Result** ✓ Passed**MOT #11** 2018-12-27 09:35**MOT test number** 655661487611**Result** ✓ Passed**MOT #10** 2017-12-21 09:19**MOT test number** 907483749753**Result** ✓ Passed**Advice** Nearside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Advice** Offside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Advice** Coolant level low**MOT #9** 2016-12-22 14:15**MOT test number** 506454778288**Result** ✓ Passed**MOT #8** 2015-09-10 14:27**MOT test number** 707597299407**Result** ✓ Passed

**MOT #7** 2015-09-10 09:10**MOT test number** 238712675243**Result** ✗ Failed**Advice** NAIL IN THE N/S REAR TYRE**Advice** O/S FRONT TYRE IS WORN ON THE OUTER EDGE**Advice** O/S REAR TYRE IS LOW ON TREAD**Advice** NAIL IN THE O/S REAR TYRE**Advice** N/S REAR TYRE IS CRACKED AND PERISHED**Fail** Nearside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)**Advice** O/S FRONT TYRE IS LOW ON TREAD**Advice** O/S REAR TYRE IS CRACKED AND PERISHED**Advice** N/S REAR TYRE IS LOW ON TREAD**Fail** Nearside Side repeater not working (1.4.A.2c)**MOT #6** 2014-06-10 15:37**MOT test number** 237641864414**Result** ✓ Passed**Notice** Under-trays fitted obscuring some underside components**Notice** Engine covers fitted obscuring some components in the engine bay**MOT #5** 2014-04-25 09:58**MOT test number** 859205814196**Result** ✓ Passed**MOT #4** 2013-04-25 10:28**MOT test number** 649925813151**Result** ✓ Passed



MOT #3	2012-04-27 15:09
MOT test number	747868712185
Result	✓ Passed
Advice	Front Brake pad(s) wearing thin (3.5.1g)

MOT #2	2011-04-21 15:37
MOT test number	919991511199
Result	✓ Passed

MOT #1	2011-04-21 11:13
MOT test number	709751211124
Result	✗ Failed
Fail	Nearside Windscreen wiper does not clear the windscreen effectively (8.2.2)



Tax & MOT check

X

Untaxed

Tax expired:
19 January 2024

✓

MOT

Expires:
30 July 2024

Tax status	Expired at 19 January 2024
Days left	100 days too late
MOT expiry date	30 July 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	G
Single payment (12 months)	£ 240,00,-
Single six month payment	£ 132,00,-
Total payable by 12 monthly instalments	£ 252,00,-



Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this VOLKSWAGEN had different number plates.

Number of plates	1
Current registration	WR08KHY
Plate since	2019-06-29
Current registration	WR08KHY
Plate since	2019-06-29

More info >



Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLKSWAGEN is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	18
First mileage registration	2008-04-26
Last registration	2023-07-31
Complete history	See info



Registration #1	2008-04-26	25 mi
Registration #2	2011-04-21	27.295 mi
Registration #3	2011-04-21	27.295 mi
Registration #4	2012-04-27	35.619 mi
Registration #5	2013-04-25	43.901 mi
Registration #6	2014-04-25	52.802 mi
Registration #7	2014-06-10	53.577 mi
Registration #8	2015-09-10	59.206 mi
Registration #9	2015-09-10	59.206 mi
Registration #10	2016-09-10	65.206 mi
Registration #11	2017-09-10	71.206 mi
Registration #12	2018-09-10	77.206 mi
Registration #13	2019-09-10	83.206 mi
Registration #14	2020-09-10	89.206 mi
Registration #15	2021-09-10	95.206 mi
Registration #16	2022-09-10	101.206 mi
Registration #17	2023-07-31	107.206 mi
Registration #18	2023-07-31	107.206 mi

More info >



Car features

The VOLKSWAGEN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLKSWAGEN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating

Video [see crash video](#)



Dimensions & weight

Width	1791 mm
Height	1437 mm
Length	4407 mm
Wheel base	2578 mm
Max. allowed weight	1930 kg

Additional information

Fuel tank capacity	55 l
Fuel delivery	Multi-Point Injection
Number of doors	2
Number of seats	4

Number of axles

2

Engine number

CAX 016127